



Your recall status

Please be sure to read the entire page and follow our advice carefully. To book a Toyota service, please [click here](#).

Safety Recalls

Campaign Code

[2506F]

Recall Description

Spare winch wire cable may become frayed causing the spare wheel to eventually displace

Recall Number

Recall Status

● Complete

Completion Date

21/06/2002

Campaign Code

[7531A]

Recall Description

Front disc brake rotor retaining bolts may loosen under severe conditions & rattle & may lead to brakes pulling to one side

Recall Number

REC-002962

Recall Status

● Complete

Completion Date

09/05/2008

Vehicle Details

VIN	JTECJ09J305501310
Model	Landcruiser Wagon
Colour	Red Mica
Trim	Shadow Grey (RV/GXL)
Series	Wag 4A Pet RV/GXL
Production year/month	2000-11
Time/Date	02:18:33 16/03/2023

This search is provided for information purposes to assist Toyota guests and should not be solely relied upon. The Toyota VIN search tool is available for Toyota vehicles only that are supplied through authorised networks (i.e. it does not include 'grey imports'). The search results contain the best information currently available to Toyota.

*Recall Number (REC) is a unique identifier assigned to vehicle recalls by the Department of Infrastructure, Transport, Regional Development and Communications. Previously, Product Recall Australia (PRA) numbers were assigned by the Australian Competition and Consumer Commission (ACCC), therefore the Toyota Safety Recall Website may display REC number or PRA number formats.

For more detail about REC numbers and/or PRA numbers, please visit

<https://www.vehiclerecalls.gov.au/> or <https://www.productsafety.gov.au/>

Note: Takata airbag mandatory safety recalls are controlled/monitored by the ACCC and will display the PRA Number only.