



Vehicle Service Records (VSR Explorer) Repair history MA5-808006

Registration nr: XV62EW
Market type: CLX1664T

Chassis nr: MA5-808006
Country: AUS

VIN nr: 6FMT14H83GD808006
Delivery date: 2017-02-24

| PC | Type | Code | Description (Original) | # |
|--|------|-----------------|--|------|
| 2022-08-09 - Mileage: 1169284 - Order nr: 2230900 | | | | |
| | | VO-1774400 | Basic service. Chassis lubrication and o | 3.5 |
| | | | oil changes included only in some models | |
| | * | 94 | EPA CHARGES | |
| | | VO-85114535 | FILTER KIT MP8/10 | 1 |
| | | | *** POSSIBLE POLICY CLAIM *** | |
| | | VO-20579690 | SUMP PLUG DOWTY WASHER | 1 |
| | | AU2-AMP23068346 | VO ENG OIL VDS4.5 BULK PER LT | 52 |
| | | | Carried out basic service & inspection as per customer | |
| | | | request. | |
| | * | 91 | CONSUMABLES | |
| 2022-08-09 - Mileage: 0 - Order nr: 2230899 | | | | |
| | * | CARD | NOT REQUIRED | |
| 2022-07-18 - Mileage: 1149531 - Order nr: 2230449 | | | | |
| | * | SHIFT | EVENING - 18/07 - DAY - 19/07. | |
| | | VO-1774400 | Basic service. Chassis lubrication and o | 3.5 |
| | * | 94 | EPA CHARGES | |
| | | LO-640 | AIR LEAKS - CHECK AND RECTIFY | 1.75 |
| | | VO-85114535 | FILTER KIT MP8/10 | 1 |
| | | VO-20579690 | SUMP PLUG DOWTY WASHER | 1 |
| | | VO-20448956 | FITTING | 1 |
| | | AU2-AMP23068346 | VO ENG OIL VDS4.5 BULK PER LT | 52 |
| | | LO-386 | FRONT DIFF TEMP SENSOR - REPLACE | 2.5 |
| | | VO-25173266 | TEMPERATURE SENSOR | 1 |
| | | VO-22037645 | ADAPTER, REAR AXLE | 1 |
| | | VO-18813 | GASKET | 1 |
| | | | - INCLUDING DIAGNOSTIC TIME. | |
| | | LO-265 | BOOST HOSES & CLAMPS - REPLACE | 1.6 |
| | | VO-20550690 | HOSE | 2 |
| | | OTH-SC097-SS | CLAMP T-BOLT FULL SS 97 MM | 4 |
| | | | Carried out basic service as per specifications. | |

| PC | Type | Code | Description (Original) | # |
|--|------|-----------------|---|-----|
| | 🔧 | | Check over the vehicle and locate air leak at the power | |
| | 🔧 | | steering reservoir air valve. Fit new fitting on pipe. | |
| | 🔧 | | Replace 2x boost hoses and clamps with new. | |
| | 🔧 | | Connect laptop and read fault codes. Carry out GD; check | |
| | 🔧 | | wiring and connections. No sensor or adaptor fitted, only | |
| | 🔧 | | the plug in the diff. Fit sensor and adaptor as required. | |
| 🟢 | * | 91 | CONSUMABLES | |
| 🔍 2022-06-21 - Mileage: 0 - Order nr: 2230120 | | | | |
| 🟢 | * | CARD | NOT REQUIRED | |
| 🔍 2022-06-20 - Mileage: 1128987 - Order nr: 2229862 | | | | |
| 🟢 | * | SHIFT | DAY | |
| 🟢 | 🟡 | LO-1774 | Basic Service | 3.5 |
| | 🔧 | | Change Fuel filters | |
| 🟢 | * | 93 | GREASE | |
| 🟢 | * | 94 | EPA CHARGES | |
| 🟢 | * | 91 | CONSUMABLES | |
| 🟢 | 🔧 | VO-85114535 | FILTER KIT MP8/10 | 1 |
| 🟢 | 🔧 | VO-20579690 | SUMP PLUG DOWTY WASHER | 1 |
| 🟢 | 🟡 | VO-2141300 | Valves and unit injectors, adjust | 3.5 |
| 🟢 | 🔧 | VO-23991740 | PLUG | 1 |
| 🟢 | 🔧 | AU2-AMP23068346 | VO ENG OIL VDS4.5 BULK PER LT | 51 |
| 🟢 | 🔧 | VO-949329 | COPPER WASHER | 1 |
| 🟢 | 🟡 | VO-4600000 | Rear axle, drive shaft, general. Seconda | 1 |
| | 🔧 | | Check wheel Bearings | |
| | 🔧 | | Check all Belts and Tensioners | |
| | 🔧 | | Pressure test cooling system | |
| | 🔧 | | Carry out Basic Service checklist | |
| | 🔧 | | Change engine oil and filters | |
| | 🔧 | | Carried out Basic Service as per service check sheets. | |
| | 🔧 | | Listed all defects found. | |
| | 🔧 | | Removed intakes etc. Removed rocker cover. Carried out | |
| | 🔧 | | top set to spec. Record all measurements. Refit rocker | |
| | 🔧 | | cover. Refit intakes etc. Road tested. Checked over. | |
| | 🔧 | | All OK. | |
| | 🔧 | | Diff plug removed to check oil level. Found thread on | |
| | 🔧 | | plug damaged. Attempted to source new one but part | |
| | 🔧 | | unavailable at this time. Brought back in to fit temp | |
| | 🔧 | | plug and secure diff temp sensor wiring until correct one | |

| PC | Type | Code | Description (Original) | # |
|--|------|-----------------|---|------|
| | 🔧 | | can be fitted. | |
| 🔧 | * | 91 | CONSUMABLES | |
| 🔍 2022-05-16 - Mileage: 1098427 - Order nr: 2228824 | | | | |
| 🔧 | * | SHIFT | DAY | |
| 🔧 | 🔧 | LO-1774 | Basic Service | 3.5 |
| | 🔧 | | Change Fuel filters | |
| | 🔧 | | Check wheel Bearings | |
| | 🔧 | | Check all Belts and Tensioners | |
| | 🔧 | | Pressure test cooling system | |
| | 🔧 | | Carry out Basic Service checklist | |
| | 🔧 | | Change engine oil and filters | |
| 🔧 | * | 93 | GREASE | |
| 🔧 | * | 94 | EPA CHARGES | |
| 🔧 | * | 91 | CONSUMABLES | |
| 🔧 | 🔧 | VO-85114535 | FILTER KIT MP8/10 | 1 |
| 🔧 | 🔧 | VO-20579690 | SUMP PLUG DOWTY WASHER | 1 |
| 🔧 | 🔧 | LO-3000 | LIGHTNING BOLT ON DASH | 0.25 |
| | 🔧 | | - INVESTIGATE, SUSPECT EXCESSIVE CLUTCH WEAR - QUOTED | |
| 🔧 | 🔧 | AU2-AMP23068346 | VO ENG OIL VDS4.5 BULK PER LT | 51 |
| 🔧 | 🔧 | LO-560 | RECTIFY LOOSE AIR DRYER SILENCER | 0.5 |
| 🔧 | 🔧 | LO-710 | RECTIFY LOOSE WALK PLATE | 0.5 |
| 🔧 | 🔧 | MK-745-5004224N | SILENCER KIT | 1 |
| 🔧 | 🔧 | VO-8155731 | CLAMP | 2 |
| 🔧 | 🔧 | VO-984736 | M8*30 FL BOLT | 2 |
| 🔧 | 🔧 | VO-984737 | M8*35 FL BOLT | 2 |
| 🔧 | 🔧 | VO-60111983 | WASHER | 2 |
| | 🔧 | | *** POSSIBLE POLICY CLAIM *** | |
| 🔧 | 🔧 | LO-311 | Bottom front battery failed test - | 0.5 |
| | 🔧 | | Replace 1x battery | |
| | 🔧 | | REPALCEMENT OF CLUTCH | |
| 🔧 | 🔧 | AU2-21209957 | BATTERY BULLDOG 12V | 1 |
| | 🔧 | | Carried out Basic Service as per service check sheets. | |
| | 🔧 | | Pressure tested cooling system. No leaks noted. Listed | |
| | 🔧 | | all defects found. | |
| | 🔧 | | Checked codes. Found clutch worn. Print out codes and | |
| | 🔧 | | attach to job card. | |
| | 🔧 | | Removed and replaced front battery as required. Tested. | |
| | 🔧 | | All OK. | |

| PC | Type | Code | Description (Original) | # |
|--|------|-----------------|---|------|
| | 🔧 | | Fit new air drier silencer and secure. Checked over. | |
| | 🔧 | | All OK. | |
| | 🔧 | | Fit 2 x new brackets to walk plate and secure with new | |
| | 🔧 | | bolts. Checked over. All OK. | |
| 🔧 | * | 91 | CONSUMABLES | |
| 🔍 2022-03-30 - Mileage: 1066299 - Order nr: 2228234 | | | | |
| 🔧 | * | SHIFT | DAY/EVENING - 30/03/2022. | |
| 🔧 | 🔧 | LO-1774 | BASIC SERVICE | 3.5 |
| | 🔧 | | Carry out Basic Service checklist | |
| 🔧 | * | 93 | ENGINE OIL & GREASE | |
| 🔧 | * | 94 | EPA CHARGES | |
| 🔧 | * | 91 | CONSUMABLES | |
| 🔧 | 🔧 | VO-85114535 | FILTER KIT MP8/10 | 1 |
| 🔧 | 🔧 | VO-20579690 | SUMP PLUG DOWTY WASHER | 1 |
| 🔧 | 🔧 | LO-253 | ENGINE BRAKE INOP - RECTIFY | 2.5 |
| | 🔧 | | - BROKEN WIRING TO TEMP SENSOR AND | |
| 🔧 | 🔧 | LO-210 | TURN OFF IDLE SHUT DOWN | 0.05 |
| 🔧 | 🔧 | AU2-AMP23068346 | VO ENG OIL VDS4.5 BULK PER LT | 48 |
| 🔧 | 🔧 | AU2-AMP23068346 | VO ENG OIL VDS4.5 BULK PER LT | 2 |
| 🔧 | 🔧 | LO-263 | DEFECT: BELTS & TENSIONERS - REPLACE | 1 |
| 🔧 | 🔧 | VO-22950501 | BELT TENSIONER | 1 |
| 🔧 | 🔧 | VO-21819687 | BELT TENSIONER | 1 |
| 🔧 | 🔧 | VO-22926887 | ADAPTER | 1 |
| 🔧 | 🔧 | VO-23961744 | V-RIBBED BELT | 1 |
| 🔧 | 🔧 | VO-984754 | FLANGE SCREW | 2 |
| | 🔧 | | Change engine oil and filters | |
| | 🔧 | | Change Fuel filters | |
| | 🔧 | | Check wheel Bearings | |
| | 🔧 | | Check all Belts and Tensioners | |
| | 🔧 | | Pressure test cooling system | |
| | 🔧 | | - AS PER CUSTOMER REQUEST. | |
| | 🔧 | | Connect laptop and program as required. | |
| | 🔧 | | Replace both tensioners and belt with new as required. | |
| | 🔧 | | WASTE GATE SHUTTLE VALVE. | |
| | 🔧 | | Test and found no 5 volt feed to sensor. Remove the harness | |
| | 🔧 | | and cut out - all wiring chaffed and broken. Repair as | |
| | 🔧 | | required. Tape up each wire and refit. Road test - all OK. | |
| 🔧 | * | 91 | CONSUMABLES | |

| PC | Type | Code | Description (Original) | # |
|--|------|-------------|---|-----|
| 2021-12-20 - Mileage: 1021601 - Order nr: R01090827 | | | | |
| | | VO-22058741 | AIR SPRING | 1 |
| | | VO-23359624 | STEERING DAMPER | 1 |
| | | VO-82278971 | SWITCH | 1 |
| | | VO-21780376 | SEALING RING | 1 |
| | | VO-22859765 | FLANGE SCREW | 1 |
| | | VO-84727009 | BEARING | 1 |
| | | VO-85142429 | SEAT BELT | 1 |
| | | 56000 | Air pressure brake, general | 0 |
| | | 72602 | Air bellows, drive axle, replace. One | 0 |
| | | 64100 | Steering wheel, column lock, steering column, shaft | 0 |
| | | 88408 | Seat belt, replace (one) | 0 |
| | | 21700 | Sump | 0 |
| | | 36405 | Switch, window lift, replace | 0 |
| | | 64602 | Steering damper, replace | 0 |
| | | 46800 | Differential lock with control | 0 |
| | | 22100 | Oil pump and line | 0 |
| 2021-12-13 - Mileage: 1021556 - Order nr: RE0030469 | | | | |
| | | VO-23149532 | BRAKE PAD KIT | 1 |
| | | VO-23149532 | BRAKE PAD KIT | 1 |
| | | VO-85109890 | REPAIR KIT | 2 |
| | | VO-85109889 | REPAIR KIT | 2 |
| | | 51321 | Brake pads, replace | 0 |
| | | 77036 | Driving wheels remove install (two sides) | 0 |
| | | 77040 | Front wheels, remove-install (two sides) | 0 |
| | | 51195 | Bushings, seals and guide sleeves, replace | 0 |
| | | 51121 | Brake pads, replace (two front wheels) | 0 |
| 2021-12-13 - Mileage: 1021556 - Order nr: RE0030469 | | | | |
| | | | c: check oil leak at filler hose on sump | |
| | | VO-2210000 | Oil pump and line. r&r oil filler tube sealing o'ring | 0.2 |
| | | VO-21780376 | SEALING RING | 1 |
| 2021-11-18 - Mileage: 1010286 - Order nr: R08034277 | | | | |
| | | VO-990950 | FLANGE LOCK NUT | 1 |
| | | VO-25110476 | ALTERNATOR | 1 |
| | | VO-994441 | FLANGE SCREW | 1 |
| | | VO-20784537 | PLANE GASKET | 1 |
| | | VO-22206133 | PLANE GASKET | 1 |
| | | VO-1675066 | SEALING RING | 1 |

| PC | Type | Code | Description (Original) | # |
|----|--|-----------------|---|----|
| | | VO-20784537 | PLANE GASKET | 1 |
| | | VO-8073055 | O-RING | 1 |
| | | VO-470993 | GASKET | 1 |
| | | VO-21638569 | TURBOCHARGER | 1 |
| | | 25336 | Engine brake function, test | 0 |
| | | 17906 | Diagnostic with Tech Tool/GD | 0 |
| | | 32101 | Alternator, replace | 0 |
| | | 25518 | Engine turbocharger, replace | 0 |
| | | 32002 | Charging test, in vehicle | 0 |
| | | 37100 | Cables | 0 |
| | | 25500 | Turbocharger | 0 |
| | | 17906 | Diagnostic with Tech Tool/GD | 0 |
| | | 37102 | Electric wires and connections, check | 0 |
| | 2021-11-15 - Mileage: 1007456 - Order nr: R08034118 | | | |
| | | 17906 | Diagnostic with Tech Tool/GD | 0 |
| | | 37100 | Cables | 0 |
| | | 37102 | Electric wires and connections, check | 0 |
| | | 17034 | Vehicle information, test | 0 |
| | | 38168 | Instrument cluster complete, replace | 0 |
| | | 38145 | MID 140 Control unit, programming | 0 |
| | 2021-11-11 - Mileage: 1005167 - Order nr: RE0029554 | | | |
| | | 26120 | Radiator hose, replace (Upper) | 0 |
| | | VO-21922388 | HOSE CLAMP | 2 |
| | | nU2-CnL85112987 | | 1 |
| | | VO-22891920 | HOSE | 1 |
| | 2021-10-20 - Mileage: 988448 - Order nr: RE0028609 | | | |
| | | 21413 | Valves and unit injectors, adjust | 0 |
| | | 23311 | Filter, water separator, replace | 0 |
| | | 17513 | Engine, oil and filter, replace | 0 |
| | | 26010 | Coolant, change | 0 |
| | | 25822 | Filter, AdBlue, replace | 0 |
| | | 56166 | Air drier cassette, replace | 0 |
| | | 26323 | Fan hub, replace | 0 |
| | | 23306 | Fuel filter, replace (one) | 0 |
| | | VO-85129545 | WASHER FLUID | 1 |
| | | 17744 | Basic service. Chassis lubrication and oil changes included only in some models | 0 |
| | | nU2-nMP85112988 | | 40 |

| PC | Type | Code | Description (Original) | # |
|---|------|-----------------|---|-----|
| | | VO-24122024 | SERVICE KIT | 1 |
| | | 17586 | Top up oil and fluid levels. Secondary operation number | 0 |
| | | nU2-nMP85158444 | | 1 |
| | | VO-85129688 | AIR DRIER KIT | 1 |
| | | VO-23381558 | FILTER | 1 |
| | | VO-23585940 | FAN CLUTCH | 1 |
| | | nU2-CnL85121795 | VDS4 BULK ENGINE O | 52 |
| 2021-10-20 - Mileage: 988448 - Order nr: RE0028609 | | | | |
| | | VO-23469625 | SPIDER | 2 |
| | | VO-4517100 | Universal joints, replace (each). Removed propeller shaft | 1.2 |
| | | | C: replace uni joints | |
| | | VO-995906 | HEXAGON SCREW | 8 |
| | | VO-4511600 | Propeller shaft intermediate, remove-install | 0.3 |
| | | VO-984050 | HEXAGON NUT | 8 |
| | | VO-2210000 | Oil pump and line. r&r oil filler o ring | 0.4 |
| | | VO-21780376 | SEALING RING | 1 |
| | | | C- Rectify oil leak at oil filler hose o ring | |
| 2021-10-13 - Mileage: 976935 - Order nr: R08033586 | | | | |
| | | VO-994458 | FLANGE SCREW | 1 |
| | | 25200 | Silencer and exhaust pipe | 0 |
| 2021-09-14 - Mileage: 972021 - Order nr: R01088082 | | | | |
| | | VO-25192096 | POWER OUTLET | 1 |
| | | 88100 | Instrument and radio panel | 0 |
| | | VO-21827215 | ELBOW | 1 |
| | | 87306 | Blower motor, replace | 0 |
| | | VO-85113771 | BLOWER MOTOR | 1 |
| | | 36400 | Electrical item | 0 |
| | | VO-25190213 | POWER OUTLET | 1 |
| | | 76102 | Front shock absorber, replace (one) | 0 |
| | | VO-23359394 | SHOCK ABSORBER | 2 |
| | | VO-8071883 | EXHAUST PIPE CLAMP | 2 |
| | | 25200 | Silencer and exhaust pipe | 0 |
| | | 37102 | Electric wires and connections, check | 0 |
| 2021-09-01 - Mileage: 949272 - Order nr: RS0000654 | | | | |
| | | VO-20799996 | SEALING RING | 1 |
| | | VO-21420336 | CONNECTION PIPE | 1 |
| | | VO-20799996 | SEALING RING | 1 |
| | | nU2-CnL85112988 | | 2 |

| PC | Type | Code | Description (Original) | # |
|--|------|-----------------|---|-----|
| | | VO-21423788 | SEALING RING | 1 |
| | | 19212 | Transfer time to breakdown site and back to repairing dealer. Breakdown, call-out service | 0 |
| | | 26200 | Coolant pump and thermostat | 0 |
| 2021-08-07 - Mileage: 949272 - Order nr: R08032308 | | | | |
| | | VO-25192096 | POWER OUTLET | 1 |
| | | 37102 | Electric wires and connections, check | 0 |
| | | 36403 | Cigarette lighter, replace | 0 |
| 2021-07-16 - Mileage: 934815 - Order nr: RE0025985 | | | | |
| | | 72602 | Air bellows, drive axle, replace. One | 0 |
| | | 17744 | Basic service. Chassis lubrication and oil changes included only in some models | 0 |
| | | 23306 | Fuel filter, replace (one) | 0 |
| | | 17586 | Top up oil and fluid levels. Secondary operation number | 0 |
| | | 31168 | Battery system, test | 0 |
| | | 23311 | Filter, water separator, replace | 0 |
| | | 72603 | Air bellows, driven axle, check | 0 |
| | | 77145 | Wheel nuts, check tightening (all) | 0 |
| | | 56166 | Air drier cassette, replace | 0 |
| | | 17513 | Engine, oil and filter, replace | 0 |
| | | 31103 | Battery, replace (one) | 0 |
| | | nU2-CnL85121777 | | 1 |
| | | nU2-21209957 | | 1 |
| | | VO-85129545 | WASHER FLUID | 1 |
| | | VO-85129688 | AIR DRIER KIT | 1 |
| | | VO-22058741 | AIR SPRING | 2 |
| | | nU2-CnL85121795 | VDS4 BULK ENGINE O | 52 |
| | | VO-22058737 | AIR SPRING | 3 |
| | | VO-85136742 | FILTER KIT | 1 |
| 2021-07-16 - Mileage: 934815 - Order nr: RE00259785 | | | | |
| | | | C-RECTIFY LEAK FROM ENGINE OIL FILLER PIPE AT SUMP | |
| | | VO-21780376 | SEALING RING | 1 |
| | | VO-2210000 | Oil pump and line. R&R oil filler o ring | 0.4 |
| 2021-06-28 - Mileage: 922213 - Order nr: R01086142 | | | | |
| | | VO-22602989 | STARTER MOTOR | 1 |
| | | 31168 | Battery system, test | 0 |
| | | 19212 | Transfer time to breakdown site and back to repairing dealer. Breakdown, call-out service | 0 |
| | | 33106 | Starter motor, replace | 0 |

| PC | Type | Code | Description (Original) | # |
|---|------|-------------------|---|-----|
| 2021-05-27 - Mileage: 917284 - Order nr: R01085249 | | | | |
| | | VO-21053033 | HOSE | 1 |
| | | VO-23653292 | RADIATOR | 1 |
| | | 26006 | Coolant system, pressure test | 0 |
| | | 26100 | Radiator and connections | 0 |
| | | 49116 | Radiator, replace | 0 |
| 2021-04-20 - Mileage: 885492 - Order nr: RE0023285 | | | | |
| | | VO-82710488 | WIPER BLADE | 2 |
| | | MK-5839-870678n | | 1 |
| | | nU2-CnL85112987 | | 1 |
| | | VO-23359624 | STEERING DAMPER | 1 |
| | | VO-85114535 | FILTER KIT | 1 |
| | | nU2-CnL8394861 | ATF DEXRON III 208 | 0 |
| | | VO-85129688 | AIR DRIER KIT | 1 |
| | | VO-85129545 | WASHER FLUID | 1 |
| | | VO-85151124 | FILTER | 1 |
| | | nU2-CnL85131754PO | | 34 |
| | | nU2-CnL85121795 | VDS4 BULK ENGINE O | 52 |
| | | VO-995906 | HEXAGON SCREW | 8 |
| | | VO-23469625 | SPIDER KIT | 2 |
| | | VO-984050 | HEXAGON NUT | 8 |
| | | 56166 | Air drier cassette, replace | 0 |
| | | 17586 | Top up oil and fluid levels. Secondary operation number | 0 |
| | | 36304 | Windscreen wiper blade, replace | 0 |
| | | 17527 | Final drive oil, change | 0 |
| | | 23311 | Filter, water separator, replace | 0 |
| | | 64514 | Oil and filter, power steering, replace | 0 |
| | | 87208 | Air conditioning air filter, replace | 0 |
| | | 17744 | Basic service. Chassis lubrication and oil changes included only in some models | 0 |
| | | 17513 | Engine, oil and filter, replace | 0 |
| | | 23306 | Fuel filter, replace (one) | 0 |
| | | 64602 | Steering damper, replace | 0 |
| | | 45110 | Propeller shaft front, remove-install | 0 |
| 2021-04-20 - Mileage: 885492 - Order nr: RE0023285 | | | | |
| | | VO-2210000 | r/r o-ring | 0.4 |
| | | | c- Rectify oil filler leaking | |
| | | VO-21780376 | SEALING RING | 1 |

| PC | Type | Code | Description (Original) | # |
|---|------|-------------|---|---|
| 2021-03-01 - Mileage: 842670 - Order nr: 808006 | | | | |
| | | 96000 | | 0 |
| 2021-02-03 - Mileage: 842669 - Order nr: R01082347 | | | | |
| | | 41183 | Valve assembly, clutch, replace | 0 |
| | | 21805 | Cushion mount, replace (front) | 0 |
| | | 72602 | Air bellows, drive axle, replace | 0 |
| | | 26118 | Expansion tank, replace | 0 |
| | | 26100 | Radiator and connections. Secondary operation number | 0 |
| | | 17010 | Connect-disconnect of diagnostic tool | 0 |
| | | VO-20503550 | RUBBER CUSHION | 1 |
| | | 17010 | Connect-disconnect of diagnostic tool | 0 |
| | | VO-23059017 | EXPANSION TANK | 1 |
| | | VO-25099500 | HOSE CLAMP | 1 |
| | | 17012 | Fault codes, reading | 0 |
| | | 56001 | Pressure drop in compressed air system, check | 0 |
| | | 40010 | Clutch cylinder, test | 0 |
| | | 72603 | Air bellows, driven axle, check | 0 |
| | | 41182 | PWM valves clutch, activation, test | 0 |
| | | VO-22058737 | AIR SPRING | 1 |
| | | 40070 | Clutch, gearbox, pulling position, calibration | 0 |
| | | 41126 | Clutch wear, check. VCADS Pro operation | 0 |
| | | VO-22327069 | SOLENOID VALVE | 1 |
| 2021-02-01 - Mileage: 838158 - Order nr: 808006 | | | | |
| | | 96000 | | 0 |
| 2021-01-11 - Mileage: 837992 - Order nr: R01081143 | | | | |
| | | 83505 | Window lift, replace | 0 |
| | | VO-82278971 | SWITCH | 1 |
| 2021-01-08 - Mileage: 838157 - Order nr: R01081414 | | | | |
| | | 46500 | Final drive (front and rear). Secondary operation number | 0 |
| | | 56401 | | 0 |
| | | 26300 | Fan, fan shroud and clutch. Secondary operation number | 0 |
| | | 25104 | Gaskets, exhaust manifold, replace | 0 |
| | | 26006 | Coolant system, pressure test | 0 |
| | | 56100 | Compressor, regulator, anti-freeze unit. Secondary operation number | 0 |
| | | 22100 | Oil pump and line. Secondary operation number | 0 |
| | | 51221 | Brake pads, replace (two rear wheels). Wheel removed | 0 |
| | | 45108 | Propeller shaft rear, remove-install | 0 |

| PC | Type | Code | Description (Original) | # |
|---|------|-------------|--|---|
| | | VO-22987428 | VALVE | 1 |
| | | VO-22227597 | SHIELD | 1 |
| | | VO-21352841 | GASKET | 6 |
| | | 26100 | Radiator and connections | 0 |
| | | VO-20733172 | SILENCER | 1 |
| | | VO-21780376 | SEALING RING | 1 |
| | | 77036 | Driving wheels remove install (two sides) | 0 |
| | | VO-1673393 | FLANGE NUT | 1 |
| | | VO-21344787 | FLANGE SCREW | 8 |
| | | VO-23149532 | BRAKE PAD KIT | 1 |
| | | VO-995906 | HEXAGON SCREW | 4 |
| | | VO-8073055 | O-RING | 1 |
| | | VO-984050 | HEXAGON NUT | 4 |
| | | VO-1675066 | SEALING RING | 1 |
| | | VO-22206133 | PLANE GASKET | 1 |
| | | VO-21940615 | SEALING RING | 1 |
| | | VO-469601 | RUBBER MOULDING | 1 |
| | | VO-470993 | GASKET | 1 |
| | | VO-20938964 | SEALING KIT | 1 |
| | | VO-21695684 | SEALING RING | 4 |
| | | VO-20784537 | PLANE GASKET | 1 |
| | | VO-22718181 | KIT | 1 |
| | | VO-23639642 | EXHAUST MANIFOLD | 1 |
| | | VO-467310 | V-CLAMP | 1 |
| | | VO-994441 | FLANGE SCREW | 1 |
| | | VO-990950 | FLANGE LOCK NUT | 1 |
| | | VO-21029030 | V-CLAMP | 1 |
| | | VO-8073055 | O-RING | 1 |
| | | VO-1675066 | SEALING RING | 1 |
| | | VO-20592783 | V-CLAMP | 2 |
| 2021-01-01 - Mileage: 829895 - Order nr: 808006 | | | | |
| | | 96000 | | 0 |
| 2020-12-21 - Mileage: 829894 - Order nr: RE0019931 | | | | |
| | | 17746 | Annual service. Chassis lubrication and oil changes included only in some models | 0 |
| | | 56166 | Air drier cassette, replace | 0 |
| | | 25822 | Filter, AdBlue, replace | 0 |
| | | 64525 | Oil filter, power steering, replace | 0 |

| PC | Type | Code | Description (Original) | # |
|----|------|---|--|----|
| | | 17000 | Service and maintenance, general. Secondary operation number | 0 |
| | | 25627 | Filter insert, air cleaner, replace. Only valid for primary filter | 0 |
| | | 32123 | Alternator belt, replace | 0 |
| | | 32107 | Belt tensioner, alternator, replace | 0 |
| | | 26307 | Drive belts fan, replace | 0 |
| | | 26313 | Fan belt tensioner, replace | 0 |
| | | 77145 | Wheel nuts, check tightening (all) | 0 |
| | | 23414 | Filter for fuel tank ventilation, replace | 0 |
| | | 21413 | Valves and unit injectors, adjust | 0 |
| | | 23306 | Fuel filter, replace (one) | 0 |
| | | VO-85129688 | AIR DRIER KIT | 1 |
| | | VO-23381558 | FILTER | 1 |
| | | MK-5839-870678n | | 1 |
| | | VO-85114535 | FILTER KIT | 0 |
| | | MK-57MD42M | | 2 |
| | | VO-22950621 | V-RIBBED BELT | 1 |
| | | VO-21422767 | BELT TENSIONER | 1 |
| | | VO-22950564 | V-RIBBED BELT | 1 |
| | | VO-22950501 | BELT TENSIONER | 1 |
| | | VO-21807998 | WHEEL NUT | 0 |
| | | VO-22124666 | VENTILATION FILTER | 1 |
| | | VO-20513285 | EXHAUST VALVE | 0 |
| | | 17513 | Engine, oil and filter, replace. Lube area | 0 |
| | | nU2-CnL85121777 | | 1 |
| | | 23311 | Filter, water separator, replace | 0 |
| | | VO-85114535 | FILTER KIT | 1 |
| | | nU2-CnL85121795 | VDS4 BULK ENGINE O | 52 |
| | | nU2-WUR0892333 | CLNR-WSCRN-RAPID-3 | 0 |
| | | 2020-12-01 - Mileage: 790725 - Order nr: 808006 | | |
| | | 96000 | | 0 |
| | | 2020-11-02 - Mileage: 772384 - Order nr: 808006 | | |
| | | 96000 | | 0 |
| | | 2020-10-17 - Mileage: 790724 - Order nr: R01078509 | | |
| | | 21547 | Timing gear plate, replace | 0 |
| | | 25811 | Dosage valve / AdBlue nozzle, replace | 0 |
| | | 51221 | Brake pads, replace (two rear wheels). Wheel removed | 0 |
| | | 36400 | Electrical item. Secondary operation number | 0 |
| | | 87474 | Air filter insert, A/C unit, replace | 0 |

| PC | Type | Code | Description (Original) | # |
|----|------|----------------|--|---|
| | | 41320 | Clutch cylinder, replace. Gearbox removed | 0 |
| | | 51100 | Front wheel brake. Secondary operation number | 0 |
| | | 64113 | Steering wheel, additional time to remove and install (UD market) | 0 |
| | | 64174 | Steering shaft, replace | 0 |
| | | 25200 | Silencer and exhaust pipe | 0 |
| | | 25251 | Clamp, exhaust pipe, replace | 0 |
| | | 21515 | Timing gear cover (upper), replace | 0 |
| | | 25708 | Separator, crankcase ventilation, replace | 0 |
| | | 64500 | Power steering equipment | 0 |
| | | 49147 | | 0 |
| | | 18202 | Localised wash for fault tracing | 0 |
| | | VO-21647145 | DOSAGE VALVE | 1 |
| | | 77036 | Driving wheels remove install (two sides) | 0 |
| | | VO-22222498 | SWITCH | 1 |
| | | VO-85151124 | FILTER | 1 |
| | | VO-23417527 | | 1 |
| | | VO-3092282 | RUBBER CAP | 2 |
| | | VO-85113737 | BEARING KIT | 2 |
| | | VO-21006995 | STEERING SHAFT | 1 |
| | | 20002 | Extract broken bolt on engine (each) | 0 |
| | | VO-1629499 | V-CLAMP | 1 |
| | | VO-20815558 | SEALING STRIP | 1 |
| | | VO-20532891 | GASKET | 1 |
| | | MK-5839-Q66297 | | 1 |
| | | VO-23701846 | OIL HOSE | 1 |
| | | 26026 | Cooling system, drain and refill coolant. Vacuum method | 0 |
| | | VO-21352570 | BRAKE PAD KIT | 1 |
| | | VO-25106380 | HEXAGON SCREW | 3 |
| | | VO-23701845 | OIL HOSE | 1 |
| | | 41101 | Clutch, replace | 0 |
| | | VO-22485772 | SEALING KIT | 1 |
| | | 21233 | Flywheel housing, replace. Flywheel and air filter housing removed and coolant drained | 0 |
| | | 21235 | Flywheel housing run-out, check. Clutch removed | 0 |
| | | 17010 | Connect-disconnect of diagnostic tool | 0 |
| | | 40070 | Clutch, gearbox, pulling position, calibration | 0 |
| | | 43302 | Program Transmission ECU (MID 130) | 0 |
| | | 17012 | Fault codes, reading | 0 |

| PC | Type | Code | Description (Original) | # |
|----|------|---|---|----|
| | | VO-85108352 | CRANKSHAFT SEAL | 1 |
| | | VO-995906 | HEXAGON SCREW | 4 |
| | | VO-984050 | HEXAGON NUT | 4 |
| | | VO-992065 | O-RING | 1 |
| | | VO-977030 | O-RING | 1 |
| | | VO-20852765 | SEALING RING | 4 |
| | | VO-471708 | RUBBER MOULDING | 1 |
| | | VO-20734156 | SEALING STRIP | 1 |
| | | VO-20734156 | SEALING STRIP | 1 |
| | | VO-21780376 | SEALING RING | 1 |
| | | VO-949656 | O-RING | 1 |
| | | VO-943177 | O-RING | 1 |
| | | VO-21724614 | SEAL | 2 |
| | | nU2-CnL85121777 | | 1 |
| | | VO-976068 | O-RING | 1 |
| | | VO-983762 | HEX. SOCKET SCREW | 1 |
| | | VO-994447 | FLANGE SCREW | 25 |
| | | VO-21015266 | FLANGE SCREW | 6 |
| | | VO-20483919 | HEX. SOCKET SCREW | 6 |
| | | VO-8192804 | FLANGE SCREW | 8 |
| | | VO-990941 | FLANGE NUT | 1 |
| | | VO-994195 | FLANGE SCREW | 1 |
| | | VO-20723207 | SEALING RING | 1 |
| | | VO-60113828 | SCREW | 1 |
| | | 2020-10-01 - Mileage: 772383 - Order nr: 808006 | | |
| | | 96000 | | 0 |
| | | 2020-09-15 - Mileage: 772382 - Order nr: RE0017467 | | |
| | | 17744 | Basic service. Chassis lubrication and oil changes included only in some models | 0 |
| | | 17523 | Gearbox oil and filter, replace. Lube area | 0 |
| | | 56166 | Air drier cassette, replace | 0 |
| | | nU2-CnL85121782 | | 1 |
| | | 35102 | Bulb unspecified, replace | 0 |
| | | 22148 | | 0 |
| | | 23306 | Fuel filter, replace (one) | 0 |
| | | VO-22038908 | OIL FILTER KIT | 1 |
| | | VO-85129688 | AIR DRIER KIT | 1 |
| | | VO-3132932 | BULB | 1 |

| PC | Type | Code | Description (Original) | # |
|---|------|-------------------|---|-----|
| | | VO-21219529 | OIL FILLER CAP | 1 |
| | | 17513 | Engine, oil and filter, replace. Lube area | 0 |
| | | nU2-CnL85131754PO | | 16 |
| | | 23311 | Filter, water separator, replace | 0 |
| | | VO-85114535 | FILTER KIT | 1 |
| | | nU2-CnL85121795 | VDS4 BULK ENGINE O | 52 |
| | | nU2-WUR0892333 | CLNR-WSCRN-RAPID-3 | 1 |
| 2020-09-15 - Mileage: 772382 - Order nr: RE0017467 | | | | |
| | | VO-22987428 | MODULATOR | 1 |
| | | | C-air leak from RH chassis rail | |
| | | VO-5630000 | Brake valve and other valves. r&r valve and modulator | 0.5 |
| | | VO-21850098 | RELAY VALVE | 1 |
| 2020-09-08 - Mileage: 768322 - Order nr: R08025988 | | | | |
| | | 56100 | Compressor, regulator, anti-freeze unit. Secondary operation number | 0 |
| | | 26500 | Charge air cooler with connection. Secondary operation number | 0 |
| | | 56001 | Pressure drop in compressed air system, check | 0 |
| | | VO-85137462 | HOSE CLAMP | 1 |
| | | VO-22024367 | SAFETY VALVE | 1 |
| 2020-09-01 - Mileage: 755877 - Order nr: 808006 | | | | |
| | | 96000 | | 0 |
| 2020-08-21 - Mileage: 755876 - Order nr: R01077073 | | | | |
| | | VO-20592783 | V-CLAMP | 1 |
| 2020-08-03 - Mileage: 718015 - Order nr: 808006 | | | | |
| | | 96000 | | 0 |
| 2020-07-14 - Mileage: 718014 - Order nr: R01074169 | | | | |
| | | 31102 | Batteries, replace (all) | 0 |
| | | 31168 | Battery system, test. Battery tester | 0 |
| | | 32002 | Charging test, in vehicle | 0 |
| | | nU2-21209957 | | 4 |
| 2020-07-01 - Mileage: 715391 - Order nr: 808006 | | | | |
| | | 96000 | | 0 |
| 2020-06-22 - Mileage: 715390 - Order nr: RE0015206 | | | | |
| | | 17744 | Basic service. Chassis lubrication and oil changes included only in some models | 0 |
| | | 77145 | Wheel nuts, check tightening (all) | 0 |
| | | 56166 | Air drier cassette, replace | 0 |
| | | nU2-CnL85121777 | | 1 |
| | | 23306 | Fuel filter, replace (one) | 0 |

| PC | Type | Code | Description (Original) | # |
|---|------|-----------------|---|------|
| | | VO-85129688 | AIR DRIER KIT | 1 |
| | | 17513 | Engine, oil and filter, replace. Lube area | 0 |
| | | 23311 | Filter, water separator, replace | 0 |
| | | VO-85114535 | FILTER KIT | 1 |
| | | nU2-CnL85121795 | VDS4 BULK ENGINE O | 52 |
| | | nU2-WUR0892333 | CLNR-WSCRN-RAPID-3 | 1 |
| 2020-06-22 - Mileage: 715390 - Order nr: RE0015206 | | | | |
| | | | C: check engine oil leak | |
| | | VO-21780376 | SEALING RING | 1 |
| | | VO-2210000 | Oil pump and line. r/r filler tube o-ring | 0.4 |
| 2020-06-01 - Mileage: 681998 - Order nr: 808006 | | | | |
| | | 96000 | | 0 |
| 2020-05-05 - Mileage: 681997 - Order nr: R01072472 | | | | |
| | | 17586 | Top up oil and fluid levels. Secondary operation number, no time | 0 |
| | | 26006 | Cooling system, pressure test | 0 |
| | | nU2-CnL85112987 | | 1 |
| 2020-05-01 - Mileage: 658096 - Order nr: 808006 | | | | |
| | | 96000 | | 0 |
| 2020-04-01 - Mileage: 655573 - Order nr: 808006 | | | | |
| | | 96000 | | 0 |
| 2020-03-13 - Mileage: 658095 - Order nr: 2083592 | | | | |
| | | 560 | ABS WARNING | |
| | | 10 | SUBLET : TTH | |
| | | 19400 | ROAD SIDE ASSISTANCE | |
| | | 10 | SUBLET - TTH | |
| 2020-03-10 - Mileage: 655572 - Order nr: RE0012380 | | | | |
| | | 17744 | Basic service. Chassis lubrication and oil changes included only in some models | 0 |
| | | 25822 | Filter, AdBlue, replace | 0 |
| | | 56166 | Air drier cassette, replace | 0 |
| | | 64514 | Oil and filter, power steering, replace | 0 |
| | | 23306 | Fuel filter, replace (one) | 0 |
| | | VO-21516231 | FILTER | 1 |
| | | VO-85129688 | AIR DRIER KIT | 1 |
| | | MK-5839-870678n | | 1 |
| | | 17513 | Engine, oil and filter, replace. Lube area | 0 |
| | | nU2-CnL8394861 | ATF DEXRON III 208 | 0.03 |
| | | 23311 | Filter, water separator, replace | 0 |

| PC | Type | Code | Description (Original) | # |
|---|------|-----------------|--|----|
| | | VO-85114535 | FILTER KIT | 1 |
| | | nU2-CnL85121795 | VDS4 BULK ENGINE O | 52 |
| | | nU2-WUR0892333 | CLNR-WSCRN-RAPID-3 | 1 |
| 2020-03-02 - Mileage: 638802 - Order nr: 808006 | | | | |
| | | 96000 | | 0 |
| 2020-02-12 - Mileage: 638801 - Order nr: R01069384 | | | | |
| | | 25251 | Clamp, exhaust pipe, replace | 0 |
| | | VO-21029030 | V-CLAMP | 1 |
| 2020-02-03 - Mileage: 614809 - Order nr: 808006 | | | | |
| | | 96000 | | 0 |
| 2020-01-01 - Mileage: 611144 - Order nr: 808006 | | | | |
| | | 96000 | | 0 |
| 2019-12-20 - Mileage: 614808 - Order nr: R01066924 | | | | |
| | | 25900 | Inlet and exhaust systems, miscellaneous. Secondary operation number | 0 |
| 2019-12-16 - Mileage: 611143 - Order nr: RE0010544 | | | | |
| | | 25627 | Filter insert, air cleaner, replace. Only valid for primary filter | 0 |
| | | 77145 | Wheel nuts, check tightening (all) | 0 |
| | | 56166 | Air drier cassette, replace | 0 |
| | | 64525 | Oil filter, power steering, replace | 0 |
| | | nU2-CnL85121777 | | 1 |
| | | 76104 | Rear shock absorber, replace (one) | 0 |
| | | 35000 | Lighting, general. Secondary operation number | 0 |
| | | 17746 | Annual service. Chassis lubrication and oil changes included only in some models | 0 |
| | | MK-57MD42M | | 2 |
| | | VO-85129688 | AIR DRIER KIT | 1 |
| | | MK-5839-870678n | | 1 |
| | | VO-20585556 | SHOCK ABSORBER | 1 |
| | | MK-unRV17177BL | | 1 |
| | | 23306 | Fuel filter, replace (one) | 0 |
| | | 23311 | Filter, water separator, replace | 0 |
| | | 17513 | Engine, oil and filter, replace. Lube area | 0 |
| | | VO-85114535 | FILTER KIT | 1 |
| | | nU2-CnL85121795 | VDS4 BULK ENGINE O | 52 |
| | | nU2-WUR0892333 | CLNR-WSCRN-RAPID-3 | 1 |
| 2019-12-04 - Mileage: 603977 - Order nr: R01066231 | | | | |
| | | 51121 | Brake pads, replace (two front wheels). Wheels removed | 0 |
| | | 77040 | Front wheels, remove-install (two sides) | 0 |

| PC | Type | Code | Description (Original) | # |
|---|------|-----------------|--|----|
| | | 77036 | Driving wheels remove install (two sides) | 0 |
| | | 51190 | Brake pad, measurement of play between outer lining plate and brake caliper. Wheel removed | 0 |
| | | VO-21352570 | BRAKE PAD KIT | 1 |
| | | VO-23149532 | BRAKE PAD KIT | 2 |
| 2019-12-02 - Mileage: 583324 - Order nr: 808006 | | | | |
| | | 96000 | | 0 |
| 2019-11-01 - Mileage: 583323 - Order nr: R01064305 | | | | |
| | | 26006 | Cooling system, pressure test | 0 |
| | | 26026 | Cooling system, drain and refill coolant. Vacuum method | 0 |
| | | 26118 | Expansion tank, replace | 0 |
| | | VO-23059017 | EXPANSION TANK | 1 |
| 2019-11-01 - Mileage: 583323 - Order nr: R01064305 | | | | |
| | | VO-21344774 | FLANGE SCREW | 6 |
| | | VO-3092340 | SEALANT | 1 |
| | | VO-21503575 | SEALING RING | 1 |
| | | VO-20852764 | GASKET | 2 |
| | | VO-21539900 | GASKET KIT | 1 |
| | | VO-21006103 | BEARING SHELL KIT | 10 |
| | | VO-22824211 | INTERMEDIATE PIPE | 1 |
| | | VO-1161277 | SILICONE SEALANT | 1 |
| | | VO-983472 | CABLE TIE | 8 |
| | | VO-21154500 | RETAINER | 2 |
| | | VO-994445 | FLANGE SCREW | 1 |
| | | MK-NARV56308 | CABLE TIE 1=25K | 2 |
| | | AU2-CAL85112987 | MACK VCS COOLANT P | 2 |
| | | VO-20852765 | GASKET | 4 |
| | | VO-21053055 | HOSE,COOLANT | 1 |
| | | VO-21707135 | OIL FILTER | 1 |
| | | VO-23357176 | VALVE CALIPER | 2 |
| | | VO-21006109 | BEARING SHELL KIT | 1 |
| | | VO-21707136 | OIL FILTER | 2 |
| | | VO-23357176 | VALVE CALIPER | 4 |
| | | VO-22824211 | INTERMEDIATE PIPE | 1 |
| | | VO-21254035 | CYLINDER LINER KIT | 1 |
| | | VO-85000891 | EXCH UNIT INJECTO | 1 |
| | | VO-21638569 | EXCH TURBOCHARGER | 1 |
| | | VO-85022268 | EXCH CLY HEAD | 1 |

| PC | Type | Code | Description (Original) | # |
|---|------|-----------------|---|------|
| | | VO-2500500 | Response, test drive | 0.4 |
| | | VO-2370200 | Injectors, replace (all) | 5.2 |
| | | VO-2221000 | Oil filter, replace. Incl. by-pass filter | 0.4 |
| | | VO-2170200 | Oil pan gasket, replace | 1.6 |
| | | VO-2141300 | Valves and unit injectors, adjust | 2.1 |
| | | VO-2135700 | Piston and liner, replace (one). Cylinder head and sump removed | 1.5 |
| | | VO-1701000 | Connect-disconnect of diagnostic tool | 0.2 |
| | | | P- Engine rattle | |
| | | AU2-CAL85121776 | MACK ULTIMATE 15W | 2 |
| | | VO-1703000 | Parameter, programming | 0.1 |
| | | VO-2100600 | Cylinder Compression, test | 3.1 |
| | | VO-2112600 | Cylinder head, replace | 13.3 |
| | | VO-20938964 | SEAL | 1 |
| | | VO-23639642 | EXHAUST MANIFOLD | 1 |
| | | VO-21695684 | SEALING RING | 2 |
| | | | P- Check for cracked exhaust manifold | |
| | | VO-2510800 | Exhaust manifold, replace | 2.7 |
| | | VO-23638462 | EXHAUST MANIFOLD | 1 |
| | | VO-23639619 | EXHAUST MANIFOLD | 1 |
| | | VO-21582423 | KIT | 1 |
| | | VO-1701200 | Fault codes, reading | 0.2 |
| | | VO-2850800 | Exhaust back pressure sensor, replace | 0.2 |
| | | VO-1701000 | Connect-disconnect of diagnostic tool | 0.2 |
| | | VO-85139619 | PRESSURE SENSOR | 1 |
| | | | P- Exhaust back pressure sensor fault | |
| 2019-11-01 - Mileage: 582828 - Order nr: 808006 | | | | |
| | | 96000 | | 0 |
| 2019-10-24 - Mileage: 582827 - Order nr: R08019909 | | | | |
| | | 26522 | Charge air hose, replace | 0 |
| | | 25500 | Turbocharger. Secondary operation number | 0 |
| | | 25500 | Turbocharger. Secondary operation number | 0 |
| | | 25003 | Boost pressure, test drive | 0 |
| | | VO-20705900 | | 1 |
| | | 25003 | Boost pressure, test drive | 0 |
| | | 17010 | Connect-disconnect of diagnostic tool | 0 |
| | | 17010 | Connect-disconnect of diagnostic tool | 0 |
| | | VO-21638569 | TURBOCHARGER | 0 |
| | | VO-21638569 | TURBOCHARGER | 0 |

| PC | Type | Code | Description (Original) | # |
|---|------|-------------------|---|----|
| 2019-10-15 - Mileage: 577846 - Order nr: R01063816 | | | | |
| | | nU2-CnL85121777 | | 1 |
| 2019-10-01 - Mileage: 554627 - Order nr: 808006 | | | | |
| | | 96000 | | 0 |
| 2019-09-12 - Mileage: 554626 - Order nr: RE0008675 | | | | |
| | | 17744 | Basic service. Chassis lubrication and oil changes included only in some models | 0 |
| | | 17527 | Final drive oil, change. Lube area | 0 |
| | | 92202 | Fifth wheel, replace | 0 |
| | | 32123 | Alternator belt, replace | 0 |
| | | 26307 | Drive belts fan, replace | 0 |
| | | 56166 | Air drier cassette, replace | 0 |
| | | 26313 | Fan belt tensioner, replace | 0 |
| | | 32107 | Belt tensioner, alternator, replace | 0 |
| | | nU2-CnL85121777 | | 1 |
| | | 83400 | Lock, handle | 0 |
| | | 22100 | Oil pump and line. Secondary operation number | 0 |
| | | 23306 | Fuel filter, replace (one) | 0 |
| | | nU2-CnL85136280PO | | 17 |
| | | VO-22950621 | V-RIBBED BELT | 1 |
| | | VO-22950564 | V-RIBBED BELT | 1 |
| | | VO-85129688 | AIR DRIER KIT | 1 |
| | | VO-21631484 | BELT TENSIONER | 1 |
| | | VO-21422767 | BELT TENSIONER | 1 |
| | | VO-85113220 | STAY | 1 |
| | | VO-21780376 | SEALING RING | 1 |
| | | 17513 | Engine, oil and filter, replace. Lube area | 0 |
| | | 23311 | Filter, water separator, replace | 0 |
| | | VO-85114535 | FILTER KIT | 1 |
| | | nU2-CnL85121795 | VDS4 BULK ENGINE O | 52 |
| | | nU2-WUR0892333 | CLNR-WSCRN-RAPID-3 | 1 |
| 2019-09-02 - Mileage: 524008 - Order nr: 808006 | | | | |
| | | 96000 | | 0 |
| 2019-08-01 - Mileage: 524007 - Order nr: 808006 | | | | |
| | | 96000 | | 0 |
| 2019-07-30 - Mileage: 524006 - Order nr: RE0007815 | | | | |
| | | 36506 | Relay, replace | 0 |
| | | 37102 | Electric wires and connections, check | 0 |

| PC | Type | Code | Description (Original) | # |
|---|------|---------------------|---|---|
| | | nU2-4381-3016LED2 | | 1 |
| 2019-07-26 - Mileage: 522154 - Order nr: RE0007759 | | | | |
| | | 25251 | Clamp, exhaust pipe, replace | 0 |
| | | 36410 | Direction indicator stalk switch, replace | 0 |
| | | 17586 | Top up oil and fluid levels. Secondary operation number, no time | 0 |
| | | VO-25091425 | EXHAUST PIPE CLAMP | 1 |
| | | VO-20906004 | DIRECTION IND. SWITCH | 1 |
| | | nU2-CnL85121799 | VDS4 ENG OIL 15W-4 | 1 |
| 2019-07-01 - Mileage: 488897 - Order nr: 808006 | | | | |
| | | 96000 | | 0 |
| 2019-06-11 - Mileage: 449042 - Order nr: RE0006198 | | | | |
| | | 17744 | Basic service. Chassis lubrication and oil changes included only in some models | 0 |
| | | 17067 | 30 Months ECU download and oil sample. Only valid for Australian market | 0 |
| | | 92202 | Fifth wheel, replace | 0 |
| | | nU2-CnL85121777 | | 1 |
| | | 56300 | Brake valve and other valves. Secondary operation number | 0 |
| | | 26154 | Filler cap, replace | 0 |
| | | 56100 | Compressor, regulator, anti-freeze unit. Secondary operation number | 0 |
| | | 26012 | Cooling system, drain and refill | 0 |
| | | 77145 | Wheel nuts, check tightening (all) | 0 |
| | | 21413 | Valves and unit injectors, adjust | 0 |
| | | 56166 | Air drier cassette, replace | 0 |
| | | 25822 | Filter, AdBlue, replace | 0 |
| | | 26202 | Coolant pump, replace | 0 |
| | | 56111 | Compressor, replace | 0 |
| | | 26323 | Fan hub, replace | 0 |
| | | 17513 | Engine, oil and filter, replace. Lube area | 0 |
| | | MK-99SX29414 | | 2 |
| | | 72856 | Air pipes, check | 0 |
| | | VO-23059030 | FILLER CAP | 1 |
| | | VO-20448956 | FITTING | 1 |
| | | nU2-CnL85112988 | | 2 |
| | | VO-1677366 | SHIM | 1 |
| | | VO-85129688 | AIR DRIER KIT | 1 |
| | | VO-21516231 | FILTER | 1 |
| | | VO-85151110 | WATER PUMP KIT | 1 |
| | | MK-8235-S9125420070 | | 1 |

| PC | Type | Code | Description (Original) | # |
|----|------|---|--|-----|
| | | VO-22929437 | FAN HUB | 1 |
| | | 23354 | Fuel and water separator filter, replace | 0 |
| | | VO-23448457 | OIL SAMPLING KIT | 2 |
| | | VO-21850098 | RELAY VALVE | 1 |
| | | VO-984735 | FLANGE SCREW | 2 |
| | | VO-471708 | RUBBER MOULDING | 1 |
| | | 17589 | Lubrication of trailer hitch | 0 |
| | | VO-990950 | FLANGE LOCK NUT | 2 |
| | | VO-8082135 | ELBOW NIPPLE | 1 |
| | | VO-85114535 | FILTER KIT | 1 |
| | | VO-993451 | NIPPLE | 1 |
| | | nU2-CnL85121795 | VDS4 BULK ENGINE O | 47 |
| | | VO-992065 | O-RING | 1 |
| | | nU2-GROEuEVELD GREnSE | | 1 |
| | | VO-1075753 | CLAMP | 2 |
| | | nU2-CnL85121799 | VDS4 ENG OIL 15W-4 | 1 |
| | | nU2-WUR0892333 | CLNR-WSCRN-RAPID-3 | 1 |
| | | MK-unRV56308 | | 2 |
| | | 2019-06-03 - Mileage: 488896 - Order nr: 808006 | | |
| | | 96000 | | 0 |
| | | 2019-05-30 - Mileage: 488895 - Order nr: RE0006476 | | |
| | | 76102 | Front shock absorber, replace (one) | 0 |
| | | VO-23359394 | SHOCK ABSORBER | 2 |
| | | 2019-05-01 - Mileage: 432554 - Order nr: 808006 | | |
| | | 96000 | | 0 |
| | | 2019-04-01 - Mileage: 432553 - Order nr: 808006 | | |
| | | 96000 | | 0 |
| | | 2019-03-29 - Mileage: 449042 - Order nr: RE0005137 | | |
| | | VO-984849 | HOUSING | 1 |
| | | | Check engine light on dash | |
| | | VO-3985621 | ADAPTER | 1 |
| | | VO-970771 | CABLE SEAL | 1 |
| | | VO-2500500 | Response, test drive | 0.4 |
| | | VO-3710200 | Electric wires and connections, check | 0.4 |
| | | VO-1703700 | Sensor and parameter values, monitoring | 0.2 |
| | | VO-984846 | CABLE TERMINAL | 4 |
| | | VO-25159097 | CABLE, WASHER MOTO | 3 |

| PC | Type | Code | Description (Original) | # |
|---|------|-----------------|--|-----|
| | | VO-1701000 | Connect-disconnect of diagnostic tool | 0.2 |
| | | VO-85139619 | PRESSURE SENSOR | 1 |
| | | VO-2850800 | Exhaust back pressure sensor, replace | 0.2 |
| 🔍 📅 2019-03-08 - Mileage: 432552 - Order nr: R01053382 | | | | |
| | | 35200 | Lighting, front. Secondary operation number | 0 |
| | | VO-20902892 | HEADLAMP | 1 |
| | | VO-85109772 | BULB | 1 |
| | | VO-85124906 | BULB | 1 |
| | | MK-unRV17177BL | | 2 |
| | | VO-21133264 | DIRECTION INDICATOR | 1 |
| 🔍 📅 2019-03-01 - Mileage: 413962 - Order nr: 808006 | | | | |
| | | 96000 | | 0 |
| 🔍 📅 2019-02-28 - Mileage: 432552 - Order nr: RE0004263 | | | | |
| | | 17746 | Annual service. Chassis lubrication and oil changes included only in some models | 0 |
| | | 81005 | 24 Months cab inspection | 0 |
| | | 17527 | Final drive oil, change. Lube area | 0 |
| | | 56126 | Air drier, drier insert, replace | 0 |
| | | 31102 | Batteries, replace (all) | 0 |
| | | 51106 | Brake pads, replace (two front wheels) | 0 |
| | | 35106 | Bulb for interior light, replace | 0 |
| | | 17066 | 24 Months ECU download and oil sample. Only valid for Australian market | 0 |
| | | 25104 | Gaskets, exhaust manifold, replace | 0 |
| | | VO-85114535 | FILTER KIT | 1 |
| | | nU2-CnL85121715 | VOLVO 85W140 GEAR | 36 |
| | | VO-85129688 | AIR DRIER KIT | 1 |
| | | 31168 | Battery system, test. Battery tester | 0 |
| | | 51207 | Brake pads, replace (two driven wheel) | 0 |
| | | MK-unRV17177BL | | 1 |
| | | MK-99SX29414 | | 4 |
| | | 25006 | Inlet and exhaust systems, check | 0 |
| | | nU2-CnL85121795 | VDS4 BULK ENGINE O | 52 |
| | | nUS-SP0964460 | | 2 |
| | | nU2-21209957 | | 4 |
| | | 51245 | Brake disc rear wheel, replace. Wheels removed | 0 |
| | | VO-21352841 | GASKET | 6 |
| | | VO-20579690 | SEALING RING | 1 |
| | | 17010 | Connect-disconnect of diagnostic tool | 0 |

| PC | Type | Code | Description (Original) | # |
|----|---|--------------------------|---|-----|
| | | VO-22718181 | KIT | 1 |
| | | nU2-WUR0892333 | CLNR-WSCRN-RAPID-3 | 1 |
| | | 50006 | Brake pads, test | 0 |
| | | nU2-WUR0890200 | PENTOIL-(ROST-OFF- | 1 |
| | | VO-949329 | GASKET | 4 |
| | | 51288 | Brake disc, measurement of thickness and side throw | 0 |
| | | VO-22206133 | PLANE GASKET | 1 |
| | | nU2-GROEuEVELD GREnSE | | 1 |
| | | 51291 | Brake pad, measurement of play between outer lining plate and brake caliper | 0 |
| | | VO-470993 | GASKET | 1 |
| | | 51241 | Brake pads, rear axle, check | 0 |
| | | VO-469601 | RUBBER MOULDING | 1 |
| | | 51277 | Sliding sleeves, wear measurement. Wheel removed | 0 |
| | | VO-21940615 | SEALING RING | 1 |
| | | VO-23149532 | BRAKE PAD KIT | 3 |
| | | VO-20938964 | SEALING KIT | 1 |
| | | VO-3092710 | BRAKE DISC KIT | 1 |
| | | nU2-SPJnC071 | | 1 |
| | | VO-1076656 | SEAL | 1 |
| | | VO-994441 | FLANGE SCREW | 1 |
| | | VO-3199066 | SEALING RING | 1 |
| | | VO-990950 | FLANGE LOCK NUT | 1 |
| | | VO-994441 | FLANGE SCREW | 1 |
| | | VO-990950 | FLANGE LOCK NUT | 1 |
| | | VO-20784537 | PLANE GASKET | 1 |
| | | VO-467310 | V-CLAMP | 1 |
| | | VO-994441 | FLANGE SCREW | 1 |
| | | VO-990950 | FLANGE LOCK NUT | 1 |
| | 2019-02-28 - Mileage: 432552 - Order nr: RE0004263 | | | |
| | | VO-2534000 | Warm hold function, test | 0.2 |
| | | VO-2530400 | Solenoid valve exhaust brake, replace | 0.6 |
| | | VO-1701000 | Connect-disconnect of diagnostic tool | 0.2 |
| | | | CHECK air leak when engine brake applied | |
| | | VO-22823727 | EXHAUST BRAKE | 1 |
| | | VO-5602100 | APM, status | 0.3 |
| | 2019-02-01 - Mileage: 413961 - Order nr: 808006 | | | |

| PC | Type | Code | Description (Original) | # |
|---|------|--------------------------|---|----|
| | | 96000 | | 0 |
| 2019-01-23 - Mileage: 390799 - Order nr: R08014898 | | | | |
| | | 87208 | Air conditioning air filter, replace | 0 |
| | | VO-85113754 | FILTER | 1 |
| 2019-01-01 - Mileage: 396144 - Order nr: 808006 | | | | |
| | | 96000 | | 0 |
| 2018-12-17 - Mileage: 390799 - Order nr: RE0002789 | | | | |
| | | 17744 | Basic service. Chassis lubrication and oil changes included only in some models | 0 |
| | | 56126 | Air drier, drier insert, replace | 0 |
| | | 23414 | Filter for fuel tank ventilation, replace | 0 |
| | | 77145 | Wheel nuts, check tightening (all) | 0 |
| | | 64525 | Oil filter, power steering, replace | 0 |
| | | 17523 | Gearbox oil and filter, replace. Lube area | 0 |
| | | 92202 | Fifth wheel, replace | 0 |
| | | nU2-CnL85121795 | VDS4 BULK ENGINE O | 52 |
| | | VO-85129688 | AIR DRIER KIT | 1 |
| | | VO-21743197 | AIR CLEANER | 2 |
| | | MK-5839-870678n | | 1 |
| | | VO-20779040 | OIL FILTER KIT | 1 |
| | | 92200 | Fifth wheel, towing hitch with connectous | 0 |
| | | nU2-GROEuEVELD GREnSE | | 1 |
| | | nU2-CnL85121714 | VOLVO SAE50 TRANS | 17 |
| | | nU2-T1SK310594 | | 1 |
| | | VO-85114535 | FILTER KIT | 1 |
| | | nU2-WUR0892333 | CLNR-WSCRN-RAPID-3 | 1 |
| 2018-12-03 - Mileage: 393784 - Order nr: 808006 | | | | |
| | | 96000 | | 0 |
| 2018-11-21 - Mileage: 276906 - Order nr: R01048469 | | | | |
| | | nU2-CnL85121775 | | 1 |
| 2018-11-01 - Mileage: 374064 - Order nr: 808006 | | | | |
| | | 96000 | | 0 |
| 2018-10-01 - Mileage: 355576 - Order nr: 808006 | | | | |
| | | 96000 | | 0 |
| 2018-09-25 - Mileage: 355466 - Order nr: R08012843 | | | | |
| | | VO-993811 | FLANGE SCREW | 4 |
| | | VO-470993 | GASKET | 1 |





















| PC | Type | Code | Description (Original) | # |
|---|------|-----------------|---|------|
| | | VO-2551800 | Engine turbocharger, replace | 2.2 |
| | | VO-20573472 | SPACER SLEEVE | 4 |
| | | | NO BOOST | |
| | | VO-469601 | SEAL RING | 1 |
| | | VO-21940615 | SEALING RING | 1 |
| | | VO-20784537 | GASKET | 1 |
| | | | AFTER HOURS BREAKDOWN AT BLUE METAL PARKING BAY ON HUME HWY JUST BEFIORE HOLLBROOK | |
| | | VO-1921200 | TRAVEL TIME | 3.75 |
| 2018-09-06 - Mileage: 339256 - Order nr: R01038333 | | | | |
| | | | CHECK BOOST LEAK | |
| | | VO-22580992 | PIPE | 1 |
| | | VO-2650200 | Charge air cooler, replace | 1.2 |
| 2018-09-03 - Mileage: 338321 - Order nr: 808006 | | | | |
| | | 96000 | | 0 |
| 2018-08-17 - Mileage: 331543 - Order nr: RE0000176 | | | | |
| | | 17744 | Basic service. Chassis lubrication and oil changes included only in some models | 0 |
| | | 25822 | Filter, AdBlue, replace | 0 |
| | | 56126 | Air drier, drier insert, replace | 0 |
| | | 21413 | Valves and unit injectors, adjust | 0 |
| | | 92202 | Fifth wheel, replace | 0 |
| | | 77145 | Wheel nuts, check tightening (all) | 0 |
| | | nU2-CnL85121795 | VDS4 BULK ENGINE O | 52 |
| | | VO-21516231 | FILTER | 1 |
| | | VO-85129688 | AIR DRIER KIT | 1 |
| | | VO-20736230 | SEALING STRIP | 1 |
| | | nU2-WUR0892333 | CLNR-WSCRN-RAPID-3 | 1 |
| | | MK-342SX33 | | 1 |
| | | VO-85114535 | FILTER KIT | 1 |
| 2018-08-01 - Mileage: 315331 - Order nr: 808006 | | | | |
| | | 96000 | | 0 |
| 2018-07-02 - Mileage: 297643 - Order nr: 808006 | | | | |
| | | 96000 | | 0 |
| 2018-06-01 - Mileage: 277400 - Order nr: 808006 | | | | |
| | | 96000 | | 0 |
| 2018-05-23 - Mileage: 276906 - Order nr: R01038013 | | | | |
| | | 17744 | Basic service. Chassis lubrication and oil changes included only in some | 0 |

| PC | Type | Code | Description (Original) | # |
|----|------|---|---|-----|
| | | | models | |
| | | 17065 | 18 Months ECU download and oil sample. Only valid for Australian market | 0 |
| | | 32122 | Alternator drive belt, replace | 0 |
| | | 26304 | Drive belt, replace | 0 |
| | | 26313 | Fan belt tensioner, replace | 0 |
| | | 32107 | Belt tensioner, alternator, replace | 0 |
| | | 17511 | Lubrication of fifth wheel | 0 |
| | | 23303 | Fuel filter, replace (one) | 0 |
| | | MK-99SX29414 | | 4 |
| | | VO-22950621 | V-RIBBED BELT | 1 |
| | | VO-22950564 | V-RIBBED BELT | 1 |
| | | VO-21631484 | BELT TENSIONER | 1 |
| | | VO-21422767 | BELT TENSIONER | 1 |
| | | 23312 | Filter, water separator, replace | 0 |
| | | VO-85114535 | FILTER KIT | 1 |
| | | nU2-CnL85121773 | | 52 |
| | | nU2-WUR0892333 | CLNR-WSCRN-RAPID-3 | 1 |
| | | nU2-SPC3381100 | | 2 |
| | | 2018-05-01 - Mileage: 260063 - Order nr: 808006 | | |
| | | 96000 | | 0 |
| | | 2018-04-02 - Mileage: 242726 - Order nr: 808006 | | |
| | | 96000 | | 0 |
| | | 2018-03-01 - Mileage: 225388 - Order nr: 808006 | | |
| | | 96000 | | 0 |
| | | 2018-02-28 - Mileage: 225401 - Order nr: R01032801 | | |
| | | VO-7288100 | Level sensor, calibration | 0.3 |
| | | | Rectify air leak at transmission | |
| | | VO-7260300 | Air bellows, driven axle, check | 0.3 |
| | | VO-7282300 | Air suspension ECS ride height, check | 0.4 |
| | | VO-7285600 | Air pipes, check | 0.9 |
| | | VO-1701000 | Connect-disconnect of diagnostic tool | 0.2 |
| | | VO-7260300 | Air bellows, driven axle, check | 0.4 |
| | | | Rectify superliner MP10 intercooler pipe hose blowing off | |
| | | VO-2650000 | Modify intercooler pipe | 3.3 |
| | | VO-20592783 | CLAMP | 1 |
| | | VO-20705900 | CLAMP | 4 |
| | | VO-20550690 | HOSE | 2 |
| | | 2018-02-26 - Mileage: 225389 - Order nr: R01032039 | | |

| PC | Type | Code | Description (Original) | # |
|---|------|-----------------|--|------|
| | | 17744 | Basic service. Chassis lubrication and oil changes included only in some models | 0 |
| | | 56126 | Air drier, drier insert, replace | 0 |
| | | 36304 | Windscreen wiper blade, replace | 0 |
| | | 64525 | Oil filter, power steering, replace | 0 |
| | | VO-85114535 | FILTER KIT | 1 |
| | | VO-85129688 | AIR DRIER KIT | 1 |
| | | VO-82710488 | WIPER BLADE | 2 |
| | | MK-5839-870678n | | 1 |
| | | nU2-CnL85121773 | | 52 |
| | | nU2-WUR0892333 | CLNR-WSCRN-RAPID-3 | 1 |
| | | nU2-SPC3381100 | | 4 |
| | | nU2-CnL8394837 | CALTEX EPC GREASE | 0.01 |
| 2018-02-01 - Mileage: 204788 - Order nr: 808006 | | | | |
| | | 96000 | | 0 |
| 2018-01-25 - Mileage: 207373 - Order nr: R01030518 | | | | |
| | | VO-2152200 | Camshaft, replace | 5.5 |
| | | VO-21185132 | SEALING | 2 |
| | | VO-1677370 | SEALING RING | 2 |
| | | VO-20526428 | SEALING RING | 1 |
| | | VO-20736230 | SEALING STRIP | 1 |
| | | VO-20723207 | SEALING RING | 1 |
| | | VO-21415409 | ROCKER ARM | 6 |
| | | VO-21768034 | GASKET KIT | 1 |
| | | | KNOCK IN ENGINE | |
| | | VO-22431891 | CAMSHAFT AND BEARI | 1 |
| | | VO-20815558 | SEALING STRIP | 1 |
| 2018-01-01 - Mileage: 187723 - Order nr: 808006 | | | | |
| | | 96000 | | 0 |
| 2017-12-01 - Mileage: 170658 - Order nr: 808006 | | | | |
| | | 96000 | | 0 |
| 2017-11-27 - Mileage: 170658 - Order nr: R0102761 | | | | |
| | | 17746 | Annual service. Chassis lubrication and oil changes included only in some models | 0 |
| | | 25627 | Filter insert, air cleaner, replace | 0 |
| | | 21413 | Valves and unit injectors, adjust | 0 |
| | | 77145 | Wheel nuts, check tightening (all) | 0 |
| | | 17527 | Final drive oil, change. Lube area | 0 |

| PC | Type | Code | Description (Original) | # |
|----|------|--|---|------|
| | | 17523 | Gearbox oil and filter, replace. Lube area | 0 |
| | | 36304 | Windscreen wiper blade, replace | 0 |
| | | 56166 | Air drier cassette, replace | 0 |
| | | 25822 | Filter, AdBlue, replace | 0 |
| | | 64525 | Oil filter, power steering, replace | 0 |
| | | VO-85114535 | FILTER KIT | 1 |
| | | MK-57MD42M | | 2 |
| | | nU2-CnL85121710 | | 36 |
| | | VO-20779040 | OIL FILTER KIT | 1 |
| | | VO-85150334 | | 2 |
| | | VO-85129688 | AIR DRIER KIT | 1 |
| | | VO-21516231 | FILTER | 1 |
| | | MK-5839-870678n | | 1 |
| | | VO-1161963 | GREASE | 1 |
| | | nU2-CnL85121712 | | 17 |
| | | nU2-WUR0892333 | CLNR-WSCRN-RAPID-3 | 1 |
| | | VO-85113754 | FILTER | 1 |
| | | MK-99SX29414 | | 4 |
| | | nU2-CnL8394837 | CALTEX EPC GREASE | 0.01 |
| | | nU2-CnL85121773 | | 52 |
| | | 2017-11-01 - Mileage: 77148 - Order nr: 808006 | | |
| | | 96000 | | 0 |
| | | 2017-10-01 - Mileage: 68576 - Order nr: 808006 | | |
| | | 96000 | | 0 |
| | | 2017-09-05 - Mileage: 60001 - Order nr: R01020973 | | |
| | | 17744 | Basic service. Chassis lubrication and oil changes included only in some models | 0 |
| | | 77145 | Wheel nuts, check tightening (all) | 0 |
| | | 56166 | Air drier cassette, replace | 0 |
| | | VO-85114535 | FILTER KIT | 1 |
| | | nU2-CnL85121773 | | 52 |
| | | nU2-GREnSE - CnL8394837 | | 1 |
| | | nU2-CnL85121712 | | 1 |
| | | nU2-WUR0892333 | CLNR-WSCRN-RAPID-3 | 1 |
| | | VO-85129688 | AIR DRIER KIT | 1 |
| | | 2017-09-05 - Mileage: 60001 - Order nr: R01020973 | | |
| | | | C: Vehicle speed incorrect | |

| PC | Type | Code | Description (Original) | # |
|--|------|----------------------------|---|------|
| | | VO-1703000 | Parameter, programming | 0.2 |
| | | VO-3835600 | K Factor test | 0.6 |
| | | VO-6460000 | Steering damper | 1 |
| | | VO-22334478 | STEERING DAMPER | 1 |
| | | | C: Steering damper leaking | |
| 2017-09-01 - Mileage: 60004 - Order nr: 808006 | | | | |
| | | 96000 | | 0 |
| 2017-08-01 - Mileage: 60003 - Order nr: 808006 | | | | |
| | | 96000 | | 0 |
| 2017-07-01 - Mileage: 60002 - Order nr: 808006 | | | | |
| | | 96000 | | 0 |
| 2017-06-06 - Mileage: 60001 - Order nr: R05008252 | | | | |
| | | 17744 | Basic service. Chassis lubrication and oil changes included only in some models | 0 |
| | | 77145 | Wheel nuts, check tightening (all) | 0 |
| | | 56166 | Air drier cassette, replace | 0 |
| | | VO-85114535 | FILTER KIT | 1 |
| | | nU2-CnL85121773 | | 52 |
| | | nU2-WIuDSCREEu nDDITIVE | | 1 |
| | | MK-99SX29414 | | 1 |
| | | VO-85129688 | AIR DRIER KIT | 1 |
| | | nU2-CnL8394837 | CALTEX EPC GREASE | 0.01 |
| 2017-06-01 - Mileage: 48903 - Order nr: 808006 | | | | |
| | | 96000 | | 0 |
| 2017-05-18 - Mileage: 48902 - Order nr: R05007918 | | | | |
| | | 76400 | Level control (separate systems) | 0 |
| 2017-05-12 - Mileage: 45103 - Order nr: R05007778 | | | | |
| | | 76400 | Level control (separate systems) | 0 |
| 2017-05-01 - Mileage: 4 - Order nr: 808006 | | | | |
| | | 96000 | | 0 |
| 2017-04-01 - Mileage: 3 - Order nr: 808006 | | | | |
| | | 96000 | | 0 |
| 2017-03-30 - Mileage: 21082 - Order nr: R05006830 | | | | |
| | | | Ride height sitting to high | |
| | | VO-7640000 | Level control (separate systems) | 0.5 |
| 2017-03-14 - Mileage: 9749 - Order nr: R05006490 | | | | |
| | | 17200 | Warranty service | 0 |

| PC | Type | Code | Description (Original) | # |
|---|---|---|------------------------|----|
|  |  | VO-85114535 | FILTER KIT | 1 |
|  |  | nU2-CnL85121773 | | 52 |
|  |  | nU2-CnL85121712 | | 16 |
|  |  | nU2-CnL85121710 | | 36 |
|  |  | nU2-WIuDSCREEu nDDITIVE | | 1 |
|  |  | VO-20779040 | OIL FILTER KIT | 1 |
|  |  | 2017-03-01 - Mileage: 2 - Order nr: 808006 | | |
|  |  | 96000 | | 0 |
|  |  | 2017-02-28 - Mileage: 1 - Order nr: 808006 | | |
|  |  | VO-nGREEMEuT COMMISSIOu | | 1 |