

Transactions		
Job	Date	Details
WCA012 : Iveco Astra 8848	27/09/2013	Parts
WCA012 : Iveco Astra 8848	20/11/2013	Parts
WCA012 : Iveco Astra 8848	20/11/2013	Parts
WCA012 : Iveco Astra 8848	26/11/2013	Fabricate PTO pump mount
WCA012 : Iveco Astra 8848	26/11/2013	Parts
WCA012 : Iveco Astra 8848	27/11/2013	Parts
WCA012 : Iveco Astra 8848	30/11/2013	Parts
wca012 : Iveco Astra 8848	30/11/2013	Parts
wca012 : Iveco Astra 8848	30/11/2013	Parts
wca012 : Iveco Astra 8848	30/11/2013	Parts
wca012 : Iveco Astra 8848	30/11/2013	Parts
WCA012 : Iveco Astra 8848	3/12/2013	Parts
WCA012 : Iveco Astra 8848	12/12/2013	Parts
WCA012 : Iveco Astra 8848	28/02/2014	Parts
WCA012 : Iveco Astra 8848	18/03/2014	Check batteries for loose terminals jump start tru
WCA012 : Iveco Astra 8848	1/04/2014	Parts
WCA012 : Iveco Astra 8848	21/08/2014	Service
WCA012 : Iveco Astra 8848	16/06/2015	Water cart engeneering, make up materials list
WCA012 : Iveco Astra 8848	18/06/2015	Parts
WCA012 : Iveco Astra 8848	20/06/2015	Drop tyre down, move spare forward
WCA012 : Iveco Astra 8848	20/06/2015	Unbolt & move spare wheel holder, fabricate bar
WCA012 : Iveco Astra 8848	22/06/2015	Water truack, fabricate spray ba mount
WCA012 : Iveco Astra 8848	23/06/2015	Fabricate components for water truck
WCA012 : Iveco Astra 8848	24/06/2015	Fabricate components for water cart
WCA012 : Iveco Astra 8848	24/06/2015	Fabricate support bracket
WCA012 : Iveco Astra 8848	25/06/2015	Fabricate components for water cart, fot out
WCA012 : Iveco Astra 8848	25/06/2015	Fabricate pipe stands, fabricate stand braces
WCA012 : Iveco Astra 8848	25/06/2015	Fit in stand, mark holes, cut angle
WCA012 : Iveco Astra 8848	26/06/2015	Fabricate brackets & braces & weld & test
WCA012 : Iveco Astra 8848	26/06/2015	Fabricate components for water cart
WCA012 : Iveco Astra 8848	26/06/2015	Make up brace for cannon column, make up bracket
WCA012 : Iveco Astra 8848	29/06/2015	CUT 90X90 SQUARE TO LENGTH- CUT PLATE REDRILL HOLE
WCA012 : Iveco Astra 8848	29/06/2015	STARTED TO SORT OUT "FIT OUT" OF WATERCRAFT
WCA012 : Iveco Astra 8848	1/07/2015	Parts
WCA012 : Iveco Astra 8848	1/07/2015	Parts
WCA012 : Iveco Astra 8848	1/07/2015	Parts
WCA012 : Iveco Astra 8848	1/07/2015	PARTS ORDERING GOING THRU WCA013 DOCKETS FOR PAST
WCA012 : Iveco Astra 8848	2/07/2015	Parts
WCA012 : Iveco Astra 8848	2/07/2015	Parts
WCA012 : Iveco Astra 8848	2/07/2015	Parts
WCA012 : Iveco Astra 8848	3/07/2015	Parts
WCA012 : Iveco Astra 8848	3/07/2015	PIPEWORK & FITTINGS
WCA012 : Iveco Astra 8848	3/07/2015	Setting up water spray control panel running wires
WCA012 : Iveco Astra 8848	3/07/2015	Signage
WCA012 : Iveco Astra 8848	6/07/2015	Fabricate and fit mounts and fire hose
WCA012 : Iveco Astra 8848	6/07/2015	HOSE REEL AND ASSORTED FITTINGS
WCA012 : Iveco Astra 8848	6/07/2015	Parts
WCA012 : Iveco Astra 8848	6/07/2015	Parts
WCA012 : Iveco Astra 8848	6/07/2015	Sorted out parts

WCA012 : Iveco Astra 8848	7/07/2015	Fit out water cart
WCA012 : Iveco Astra 8848	7/07/2015	Running wires for cannon, also power feed wires
WCA012 : Iveco Astra 8848	7/07/2015	STAINLESS STEEL COVER
WCA012 : Iveco Astra 8848	8/07/2015	Fit out & plumb up pump
WCA012 : Iveco Astra 8848	8/07/2015	Make wiring up control box prep work for air valve
WCA012 : Iveco Astra 8848	8/07/2015	Parts
WCA012 : Iveco Astra 8848	9/07/2015	Parts
WCA012 : Iveco Astra 8848	9/07/2015	Plumb up water pipe
WCA012 : Iveco Astra 8848	9/07/2015	TOOLBOX
WCA012 : Iveco Astra 8848	10/07/2015	Fit out pump & pipe work, fit mounts
WCA012 : Iveco Astra 8848	14/07/2015	Fit out plumbing, drill and top mounting brackets
WCA012 : Iveco Astra 8848	14/07/2015	Parts
WCA012 : Iveco Astra 8848	15/07/2015	Drill hole in tank and weld in socket
WCA012 : Iveco Astra 8848	15/07/2015	Fit pipes remove hyd tank make up brakes
WCA012 : Iveco Astra 8848	15/07/2015	Fit toolbox
WCA012 : Iveco Astra 8848	15/07/2015	Fitting hyd components to truck working with enzed
WCA012 : Iveco Astra 8848	15/07/2015	FLANGES & GASKETS
WCA012 : Iveco Astra 8848	15/07/2015	Parts
WCA012 : Iveco Astra 8848	16/07/2015	Grind and paint new socket on tank
WCA012 : Iveco Astra 8848	16/07/2015	Install wiring and reverse camera
WCA012 : Iveco Astra 8848	16/07/2015	Mounted air valve bank to truck, mounted festo
WCA012 : Iveco Astra 8848	17/07/2015	Fabricate and weld toolbox holder, fabricate
WCA012 : Iveco Astra 8848	17/07/2015	Run hyd hose to pump weld on clamps
WCA012 : Iveco Astra 8848	17/07/2015	Setting up water cart assisting enzed wiring
WCA012 : Iveco Astra 8848	18/07/2015	Wired up air control box assisted enzed with hose
WCA012 : Iveco Astra 8848	20/07/2015	CABLE TIES
WCA012 : Iveco Astra 8848	20/07/2015	CAMERA CABLE
WCA012 : Iveco Astra 8848	20/07/2015	Fabricate & fit support tube, drill & fit cooker
WCA012 : Iveco Astra 8848	20/07/2015	Fabricate mount for dribble bar, set up and flag
WCA012 : Iveco Astra 8848	20/07/2015	Frame blast prime paint
WCA012 : Iveco Astra 8848	20/07/2015	Make balls
WCA012 : Iveco Astra 8848	20/07/2015	Parts
WCA012 : Iveco Astra 8848	20/07/2015	Started making isolator switch brakcet
WCA012 : Iveco Astra 8848	21/07/2015	Fabricated isolator mount & painted, made new
WCA012 : Iveco Astra 8848	21/07/2015	Make balls
WCA012 : Iveco Astra 8848	21/07/2015	Parts
WCA012 : Iveco Astra 8848	21/07/2015	Parts
WCA012 : Iveco Astra 8848	21/07/2015	Weld actuator mount, weld on stauff clamps
WCA012 : Iveco Astra 8848	22/07/2015	CABLE TIES
WCA012 : Iveco Astra 8848	22/07/2015	CLAMPS
WCA012 : Iveco Astra 8848	22/07/2015	Fit toolbox holder bolt on toolbox, weld on stauff
WCA012 : Iveco Astra 8848	22/07/2015	Make balls
WCA012 : Iveco Astra 8848	22/07/2015	Mounted & wired up isolators on battery box
WCA012 : Iveco Astra 8848	22/07/2015	Parts
WCA012 : Iveco Astra 8848	22/07/2015	Workshop Consumables
WCA012 : Iveco Astra 8848	23/07/2015	CABLE TIES
WCA012 : Iveco Astra 8848	23/07/2015	drill hole In cannon mount and grind, remove pump
WCA012 : Iveco Astra 8848	23/07/2015	Fitted dash back into cab, drilled holes to mount
WCA012 : Iveco Astra 8848	23/07/2015	Make balls
WCA012 : Iveco Astra 8848	23/07/2015	Parts
WCA012 : Iveco Astra 8848	23/07/2015	Subcontractor - Plant Maintenance

WCA012 : Iveco Astra 8848	24/07/2015	Drill holes in frame for pump mounting plate
WCA012 : Iveco Astra 8848	24/07/2015	Fitting water fittings, tidy up hyd hose
WCA012 : Iveco Astra 8848	24/07/2015	Ran air lines to rear of truck, put clamps on
WCA012 : Iveco Astra 8848	24/07/2015	Signage
WCA012 : Iveco Astra 8848	24/07/2015	TANK FITTINGS
WCA012 : Iveco Astra 8848	25/07/2015	Fit air lines
WCA012 : Iveco Astra 8848	25/07/2015	Fit out plumbing
WCA012 : Iveco Astra 8848	25/07/2015	Fitted bulkhead fitting in tank, set pressure r
WCA012 : Iveco Astra 8848	27/07/2015	Assemble pipe work
WCA012 : Iveco Astra 8848	27/07/2015	Bolted up hyd hoses & welded
wca012 : Iveco Astra 8848	27/07/2015	BOLTS
WCA012 : Iveco Astra 8848	27/07/2015	Maintenance Sundry
WCA012 : Iveco Astra 8848	28/07/2015	Assemble pipe work
WCA012 : Iveco Astra 8848	28/07/2015	Parts
WCA012 : Iveco Astra 8848	28/07/2015	Prepping calv steel work then
WCA012 : Iveco Astra 8848	29/07/2015	Assemble dribble bar
WCA012 : Iveco Astra 8848	29/07/2015	Fit sections to w/c
WCA012 : Iveco Astra 8848	29/07/2015	Fitted piping, fitted brackets & dribble bar
wca012 : Iveco Astra 8848	29/07/2015	Signage
WCA012 : Iveco Astra 8848	30/07/2015	Assemble watercart componets
WCA012 : Iveco Astra 8848	30/07/2015	Fit water pipes, fuse water pipes, fit filler coll
WCA012 : Iveco Astra 8848	30/07/2015	Fitting & fusion wekding water pipin, fited hyd
WCA012 : Iveco Astra 8848	30/07/2015	NUTS/BOLTS
WCA012 : Iveco Astra 8848	31/07/2015	Fuse water pipe, chnge nuts, drill holes in bar
WCA012 : Iveco Astra 8848	31/07/2015	U BOLTS
WCA012 : Iveco Astra 8848	3/08/2015	Running & mounting air lines, fitted sight
WCA012 : Iveco Astra 8848	4/08/2015	Tidy up work area fitted cannon to truck set up
WCA012 : Iveco Astra 8848	5/08/2015	Fabricate spray units
WCA012 : Iveco Astra 8848	5/08/2015	Fault fidning issues with cannn, back up work area
WCA012 : Iveco Astra 8848	5/08/2015	Workshop Consumables
WCA012 : Iveco Astra 8848	12/08/2015	Sorted out sticky batter sprays
WCA012 : Iveco Astra 8848	12/08/2015	Stickers & stripes
wca012 : Iveco Astra 8848	13/08/2015	Parts
WCA012 : Iveco Astra 8848	13/08/2015	Small jobs mount joystick in cab
WCA012 : Iveco Astra 8848	13/08/2015	Stickers stripes
WCA012 : Iveco Astra 8848	13/08/2015	Subcontractor - Plant Maintenance
WCA012 : Iveco Astra 8848	14/08/2015	Calibrate & set up water cannon
WCA012 : Iveco Astra 8848	17/08/2015	Load balls
WCA012 : Iveco Astra 8848	17/08/2015	Repairs to sprayers/ fill with baffle balls
WCA012 : Iveco Astra 8848	17/08/2015	Test water sprays & cannon fit bar into tanks
WCA012 : Iveco Astra 8848	18/08/2015	Finish check list, worked out piping adjustments
WCA012 : Iveco Astra 8848	18/08/2015	Modify pipe work to suit a/s
WCA012 : Iveco Astra 8848	18/08/2015	More stickers
WCA012 : Iveco Astra 8848	18/08/2015	Signage
WCA012 : Iveco Astra 8848	19/08/2015	Fit out pipe work/ weld out pipe work
WCA012 : Iveco Astra 8848	19/08/2015	Fusion welded filler pipe tidy up
WCA012 : Iveco Astra 8848	19/08/2015	Parts
WCA012 : Iveco Astra 8848	20/08/2015	Reassemble pipe work and brackets
WCA012 : Iveco Astra 8848	20/08/2015	Repaired flashing checked out injector light fault
WCA012 : Iveco Astra 8848	21/08/2015	Parts
WCA012 : Iveco Astra 8848	23/08/2015	Parts

WCA012 : Iveco Astra 8848	31/08/2015	Parts	PIPE FITTINGS
WCA012 : Iveco Astra 8848	19/09/2015	Cut back body	
WCA012 : Iveco Astra 8848	21/09/2015	Check over, strap down grill, cut out barrery spra	
WCA012 : Iveco Astra 8848	22/09/2015	Diagnose pto fault, remove destroyed coupling	
WCA012 : Iveco Astra 8848	23/09/2015	Disassemble pto pump, inspect, reassemble	
WCA012 : Iveco Astra 8848	24/09/2015	Measure up flange & ring through dimensions	
WCA012 : Iveco Astra 8848	24/09/2015	Parts	
WCA012 : Iveco Astra 8848	30/09/2015	Fit new & pump ect. Test	
WCA012 : Iveco Astra 8848	30/09/2015	Operate watercart for road works	
WCA012 : Iveco Astra 8848	1/10/2015	Realign PTO, modify everything to align couplings	
WCA012 : Iveco Astra 8848	15/10/2015	Subcontractor - Plant Maintenance	
WCA012 : Iveco Astra 8848	18/10/2015	Fabricate up leaks & damaged fittings	
WCA012 : Iveco Astra 8848	21/10/2015	Inspect fault lights & codes	
WCA012 : Iveco Astra 8848	27/10/2015	Repair beacon & mudflap	
WCA012 : Iveco Astra 8848	31/10/2015	Freight	
WCA012 : Iveco Astra 8848	13/11/2015	Inspect steering fault alarm	
WCA012 : Iveco Astra 8848	16/11/2015	Change flat front tyre	
WCA012 : Iveco Astra 8848	23/11/2015	RIM	
WCA012 : Iveco Astra 8848	1/12/2015	385/65 R22.5 Tyre	
WCA012 : Iveco Astra 8848	12/01/2016	Diagnose coupling fault test hyd, motor & pump	
WCA012 : Iveco Astra 8848	16/01/2016	Remove wheel & change tyre on rim & refit to truck	
WCA012 : Iveco Astra 8848	18/01/2016	Test water pump displacment & loosening output	
WCA012 : Iveco Astra 8848	19/01/2016	385/65 R22.5 Tyre	
WCA012 : Iveco Astra 8848	19/01/2016	Scrap Tyre 385/65 R22.5	
WCA012 : Iveco Astra 8848	4/02/2016	Fill & check over adblue syste,	
WCA012 : Iveco Astra 8848	9/02/2016	Check water outlet sizes for stabilizes	
WCA012 : Iveco Astra 8848	18/02/2016	Fit new water outlet couplings	
WCA012 : Iveco Astra 8848	19/02/2016	2992261 Cartridge Air Dry	
WCA012 : Iveco Astra 8848	19/02/2016	2992544 Oil Filter	
WCA012 : Iveco Astra 8848	19/02/2016	2995711 Fuel Filter	
WCA012 : Iveco Astra 8848	19/02/2016	2995964 Anti Pollen Filter	
WCA012 : Iveco Astra 8848	19/02/2016	2996234 Gasket	
WCA012 : Iveco Astra 8848	19/02/2016	2996238 Filtering Cartridge	
WCA012 : Iveco Astra 8848	19/02/2016	504153481 Filter Elem. Blowby	
WCA012 : Iveco Astra 8848	23/02/2016	Look for hyd fault, with hyd motor system	
WCA012 : Iveco Astra 8848	24/02/2016	Look for hyd faults with pump system	
WCA012 : Iveco Astra 8848	25/02/2016	Parts	
WCA012 : Iveco Astra 8848	25/02/2016	Refit filter heads	
WCA012 : Iveco Astra 8848	25/02/2016	Subcontractor - Plant Maintenance	
WCA012 : Iveco Astra 8848	3/03/2016	800hr service, fit new hyd pump motor and filters	
WCA012 : Iveco Astra 8848	4/03/2016	Reassemble water pump	
WCA012 : Iveco Astra 8848	18/03/2016	201748 110 Jaw Spider Insert	
WCA012 : Iveco Astra 8848	18/03/2016	202930 110 Jaw Hub 32mm bore x10mm Key	
WCA012 : Iveco Astra 8848	18/03/2016	203102 110 Martin Coupling Half 7/8" bore Keyed	
WCA012 : Iveco Astra 8848	18/03/2016	Freight	
WCA012 : Iveco Astra 8848	18/03/2016	Water pump- hyd motor	
WCA012 : Iveco Astra 8848	21/03/2016	Subcontractor - Plant Maintenance	
WCA012 : Iveco Astra 8848	25/03/2016	Fit new pump drive coupling	
WCA012 : Iveco Astra 8848	3/04/2016	Freight	
WCA012 : Iveco Astra 8848	27/05/2016	315/80 R22.5 BS M840 Tyres	
WCA012 : Iveco Astra 8848	30/05/2016	Parts	

WCA012 : Iveco Astra 8848	4/08/2016	Umawa to Kalka
WCA012 : Iveco Astra 8848	17/08/2016	Water cart pump not working
WCA012 : Iveco Astra 8848	25/08/2016	Look for eng fault
WCA012 : Iveco Astra 8848	26/08/2016	Parts
WCA012 : Iveco Astra 8848	10/10/2016	Drive water cart down battery float jump start wir
WCA012 : Iveco Astra 8848	10/10/2016	Tested battery jump started and moved into worksho
WCA012 : Iveco Astra 8848	11/10/2016	Assist NY with hyd diagnosing
WCA012 : Iveco Astra 8848	11/10/2016	Check and repair lights on water cart
WCA012 : Iveco Astra 8848	11/10/2016	Fault find hyd fault diassemble pump remove toolbo
WCA012 : Iveco Astra 8848	11/10/2016	Repair toolbox holder and refit toolbox
WCA012 : Iveco Astra 8848	12/10/2016	Fabricate and fit bracing for headboard
WCA012 : Iveco Astra 8848	12/10/2016	Fix up hyd tank brakets and fit water tank outlet
WCA012 : Iveco Astra 8848	12/10/2016	Look up & order parts
WCA012 : Iveco Astra 8848	12/10/2016	Parts
WCA012 : Iveco Astra 8848	12/10/2016	Toolbox/ headboard repairs
WCA012 : Iveco Astra 8848	13/10/2016	Fit water out let fit motor make new guards for pu
WCA012 : Iveco Astra 8848	13/10/2016	make tube WCA012 5/64428
WCA012 : Iveco Astra 8848	13/10/2016	Sticker
WCA012 : Iveco Astra 8848	13/10/2016	Stickers
WCA012 : Iveco Astra 8848	17/10/2016	Fix hyd pump, replace filters
WCA012 : Iveco Astra 8848	18/10/2016	30MR32x237HG hyd gear motor
WCA012 : Iveco Astra 8848	18/10/2016	Fit hyd hose, ov in pumps, test run, clean out
WCA012 : Iveco Astra 8848	18/10/2016	Freight
WCA012 : Iveco Astra 8848	18/10/2016	sunvisor
WCA012 : Iveco Astra 8848	19/10/2016	To Dependable/welland
WCA012 : Iveco Astra 8848	20/10/2016	Fill watercart and test operation of sprays and ca
WCA012 : Iveco Astra 8848	20/10/2016	Fit new hyd motor fill up with water/ test run
WCA012 : Iveco Astra 8848	21/10/2016	Clean tray and fix water leak
WCA012 : Iveco Astra 8848	28/10/2016	Investigate & Remove engine light on dash & fit parts
WCA012 : Iveco Astra 8848	31/10/2016	Jumpstart & test battery & alternator
WCA012 : Iveco Astra 8848	7/11/2016	Inspect tyres, load up punctured tyre
WCA012 : Iveco Astra 8848	8/11/2016	Drop off wheel at tailem bend
WCA012 : Iveco Astra 8848	8/11/2016	Inspect water pump fault, diagnose worn couplings
WCA012 : Iveco Astra 8848	10/11/2016	coupling
WCA012 : Iveco Astra 8848	10/11/2016	coupling elements
WCA012 : Iveco Astra 8848	10/11/2016	Freight
WCA012 : Iveco Astra 8848	10/11/2016	hyd motor
WCA012 : Iveco Astra 8848	10/11/2016	hyd pump
WCA012 : Iveco Astra 8848	10/11/2016	Load up drive to Tailem Bend and replace water pum
WCA012 : Iveco Astra 8848	10/11/2016	Parts
WCA012 : Iveco Astra 8848	16/11/2016	22.5 x 9.00 Steel Wheel
WCA012 : Iveco Astra 8848	17/11/2016	Repair fuel tank straps-both bolts broken, removed
WCA012 : Iveco Astra 8848	18/11/2016	Completed assembly of suction pipe
WCA012 : Iveco Astra 8848	1/12/2016	Remove rock from pos 5 tyre
WCA012 : Iveco Astra 8848	5/12/2016	Inspect sprays not working, replaced blown fuse
WCA012 : Iveco Astra 8848	13/12/2016	2992261 Cartridge Air Dry
WCA012 : Iveco Astra 8848	13/12/2016	2992544 Oil Filter
WCA012 : Iveco Astra 8848	13/12/2016	2995711 Fuel Filter
WCA012 : Iveco Astra 8848	13/12/2016	2995964 Antipollen Filter
WCA012 : Iveco Astra 8848	13/12/2016	2996234 Gasket
WCA012 : Iveco Astra 8848	13/12/2016	2996238 Filtering Cartridge

WCA012 : Iveco Astra 8848	13/12/2016	504153481 Filter Element Blow by
WCA012 : Iveco Astra 8848	13/12/2016	Inspect coolant leak, found top radiator hose
WCA012 : Iveco Astra 8848	3/01/2017	Inspect oil leak, suspect pump seal failure
WCA012 : Iveco Astra 8848	4/01/2017	Diagnose & try to rectify hyd issues
WCA012 : Iveco Astra 8848	4/01/2017	Wash truck, bring down, modify hydraulic system
WCA012 : Iveco Astra 8848	5/01/2017	Annual service & repairs
WCA012 : Iveco Astra 8848	5/01/2017	Annual service and repairs as per inspection
WCA012 : Iveco Astra 8848	5/01/2017	Batteries
WCA012 : Iveco Astra 8848	6/01/2017	Annual service and repairs as per inspection
WCA012 : Iveco Astra 8848	9/01/2017	Annual service & repairs as per service inspection
WCA012 : Iveco Astra 8848	9/01/2017	Finish off annual service
WCA012 : Iveco Astra 8848	9/01/2017	P777871 Air Filter OUT
WCA012 : Iveco Astra 8848	9/01/2017	P777875 Air Filter IN
WCA012 : Iveco Astra 8848	10/01/2017	Collect parts
WCA012 : Iveco Astra 8848	10/01/2017	Repair water leak, clean from service, drain water
WCA012 : Iveco Astra 8848	10/01/2017	Repairs/ redesign of PTO hyd system, cleaned up
WCA012 : Iveco Astra 8848	11/01/2017	Hyd system modification, machine pump aligning
WCA012 : Iveco Astra 8848	11/01/2017	Inspected pump elements, cleared out suction side
WCA012 : Iveco Astra 8848	12/01/2017	500055972 Filter Adblu
WCA012 : Iveco Astra 8848	12/01/2017	98168059 Filter
WCA012 : Iveco Astra 8848	12/01/2017	Hydraulic system modification & flush out
WCA012 : Iveco Astra 8848	12/01/2017	Removed hyd tank & mounting brackets
WCA012 : Iveco Astra 8848	13/01/2017	Fit hyd tank
WCA012 : Iveco Astra 8848	13/01/2017	Removed & rebuilt hyd DCU
WCA012 : Iveco Astra 8848	14/01/2017	Replace Front Windscreen
WCA012 : Iveco Astra 8848	16/01/2017	Install bypass hose for cooler piping, fabricate
WCA012 : Iveco Astra 8848	16/01/2017	make and fit parts to hydraulics
WCA012 : Iveco Astra 8848	16/01/2017	Signage
WCA012 : Iveco Astra 8848	16/01/2017	stainless angle 540mm long
WCA012 : Iveco Astra 8848	16/01/2017	To Pirtek
WCA012 : Iveco Astra 8848	16/01/2017	To Reynela steel
WCA012 : Iveco Astra 8848	17/01/2017	EFX5543 fan
WCA012 : Iveco Astra 8848	17/01/2017	Freight
WCA012 : Iveco Astra 8848	17/01/2017	Installing hyd cooler for PTO circuit
WCA012 : Iveco Astra 8848	17/01/2017	Parts
WCA012 : Iveco Astra 8848	17/01/2017	To Reynella steel & accumax
WCA012 : Iveco Astra 8848	17/01/2017	Wire up cooling fan, run supply cable wire
WCA012 : Iveco Astra 8848	18/01/2017	Complete repairs & testing to the hyd circuit
WCA012 : Iveco Astra 8848	18/01/2017	Wire up cooling fan connect to breaker & test
WCA012 : Iveco Astra 8848	19/01/2017	Completed testing of modifications to circuit, tid
WCA012 : Iveco Astra 8848	19/01/2017	Subcontractor - Plant Maintenance
WCA012 : Iveco Astra 8848	20/01/2017	Exit inspection and dropped upstairs
WCA012 : Iveco Astra 8848	23/01/2017	P171534 filter
WCA012 : Iveco Astra 8848	23/01/2017	Signage
WCA012 : Iveco Astra 8848	6/04/2017	Drain hyd oil x 2/ refull hyd oil x2 reseal sight
WCA012 : Iveco Astra 8848	21/04/2017	315/80R22.5 OB Tyres
WCA012 : Iveco Astra 8848	21/04/2017	385/65R22.5 Michelin Tyre
WCA012 : Iveco Astra 8848	3/05/2017	Inspect & make work plan
WCA012 : Iveco Astra 8848	18/05/2017	Cut out cracks & perform weld repair
WCA012 : Iveco Astra 8848	18/05/2017	Remove piping to repair crack
WCA012 : Iveco Astra 8848	4/07/2017	run up

WCA012 : Iveco Astra 8848	5/07/2017 full truck inspection,started repairs to truck
WCA012 : Iveco Astra 8848	6/07/2017 continued repairs as per list
WCA012 : Iveco Astra 8848	10/07/2017 remove driver door trim & Electric window
WCA012 : Iveco Astra 8848	10/07/2017 Window Regulator
WCA012 : Iveco Astra 8848	11/07/2017 removed spare tyre carrier,
WCA012 : Iveco Astra 8848	11/07/2017 replace electric window winder
WCA012 : Iveco Astra 8848	12/07/2017 repair chain on water cart
WCA012 : Iveco Astra 8848	13/07/2017 Arm rest
WCA012 : Iveco Astra 8848	13/07/2017 Door Seal
WCA012 : Iveco Astra 8848	13/07/2017 fabricate handle for spare wheel holder& repair
WCA012 : Iveco Astra 8848	13/07/2017 fitted spare tyre winch & spare tyre
WCA012 : Iveco Astra 8848	14/07/2017 fit drivers door trim & electric window
WCA012 : Iveco Astra 8848	14/07/2017 repair crack in chassis
WCA012 : Iveco Astra 8848	14/07/2017 repair cracks
WCA012 : Iveco Astra 8848	24/07/2017 remove dribble bar & plum up for stabilizer
WCA012 : Iveco Astra 8848	25/07/2017 Subcontractor - Plant Maintenance
WCA012 : Iveco Astra 8848	29/07/2017 fit new piping
WCA012 : Iveco Astra 8848	29/07/2017 sprayer mod
WCA012 : Iveco Astra 8848	3/08/2017 repair funnel
WCA012 : Iveco Astra 8848	10/08/2017 refit funnel
WCA012 : Iveco Astra 8848	11/08/2017 replace beacon globes, report cracks
WCA012 : Iveco Astra 8848	16/08/2017 2 x 315/80 R22.5 Tyres
WCA012 : Iveco Astra 8848	19/08/2017 air filter restriction,blow out filter
WCA012 : Iveco Astra 8848	31/08/2017 electrical fault
WCA012 : Iveco Astra 8848	16/09/2017 change flat tyre
WCA012 : Iveco Astra 8848	21/09/2017 Repair batter spray
WCA012 : Iveco Astra 8848	4/10/2017 Diagnose & repair electrical fault
WCA012 : Iveco Astra 8848	6/10/2017 Service
WCA012 : Iveco Astra 8848	8/10/2017 Change tyres
WCA012 : Iveco Astra 8848	8/10/2017 Repair tyres & change
WCA012 : Iveco Astra 8848	9/10/2017 Fit new tyre to rims & fit to truck
WCA012 : Iveco Astra 8848	9/10/2017 Fit tyre to rim & change onto truck
WCA012 : Iveco Astra 8848	9/10/2017 Tyres
WCA012 : Iveco Astra 8848	10/10/2017 Service, cannon repairs
WCA012 : Iveco Astra 8848	11/10/2017 Tyres
WCA012 : Iveco Astra 8848	17/10/2017 Re position bolt to prevent rubbing on tank
WCA012 : Iveco Astra 8848	25/10/2017 Change out pos 5,6 tyres
WCA012 : Iveco Astra 8848	25/10/2017 Change tyres
WCA012 : Iveco Astra 8848	27/10/2017 Batteries
WCA012 : Iveco Astra 8848	31/10/2017 Tyres
WCA012 : Iveco Astra 8848	8/11/2017 Hitch roblem
WCA012 : Iveco Astra 8848	20/11/2017 Hyd leak
WCA012 : Iveco Astra 8848	20/11/2017 Remove & wash hyd tank for repair
WCA012 : Iveco Astra 8848	21/11/2017 Assist refit Hyd tank
WCA012 : Iveco Astra 8848	21/11/2017 Fit hydraulic tank repair leaks
WCA012 : Iveco Astra 8848	21/11/2017 Hydraulic tank repair
WCA012 : Iveco Astra 8848	23/11/2017 Electrical fault
WCA012 : Iveco Astra 8848	24/11/2017 Change steer tyre refit on rim
WCA012 : Iveco Astra 8848	24/11/2017 Pos 1 tyre replace
WCA012 : Iveco Astra 8848	26/11/2017 Drive issue
WCA012 : Iveco Astra 8848	28/11/2017 Quote parts for window repairs

WCA012 : Iveco Astra 8848	28/11/2017	Refit hydraulic tank & plumb up
WCA012 : Iveco Astra 8848	1/12/2017	Remove hyd tank
WCA012 : Iveco Astra 8848	1/12/2017	Removed turntable jaws
WCA012 : Iveco Astra 8848	2/12/2017	Inspect rops carry out crack test & check
WCA012 : Iveco Astra 8848	2/12/2017	Remove lights & wiring from rops frame
WCA012 : Iveco Astra 8848	2/12/2017	Rmored rops & checked for cracks
WCA012 : Iveco Astra 8848	4/12/2017	Diagnose faults
WCA012 : Iveco Astra 8848	4/12/2017	Wash machinefit rotating light
WCA012 : Iveco Astra 8848	5/12/2017	Repair cracked hyd tank
WCA012 : Iveco Astra 8848	12/12/2017	Prep & paint rops
WCA012 : Iveco Astra 8848	12/12/2017	Sandblast/prime/paint
WCA012 : Iveco Astra 8848	14/12/2017	Sandblast rops
WCA012 : Iveco Astra 8848	22/12/2017	Fit hydro tank & ROPS
WCA012 : Iveco Astra 8848	23/12/2017	WCA012 - Repair Electrical Faults
WCA012 : Iveco Astra 8848	27/12/2017	Fit hyd tank & lines, replace beacon, fill water
WCA012 : Iveco Astra 8848	27/12/2017	Fit hydro tank, wire up lights & ram in rops
WCA012 : Iveco Astra 8848	2/01/2018	2992261 Cartridge Air Dry
WCA012 : Iveco Astra 8848	2/01/2018	2992544 Filter Oil
WCA012 : Iveco Astra 8848	2/01/2018	2992662 Fuel Filter ELEM
WCA012 : Iveco Astra 8848	2/01/2018	2994048 Fuel Filter ELEM.
WCA012 : Iveco Astra 8848	2/01/2018	2996234 Gasket
WCA012 : Iveco Astra 8848	2/01/2018	504153481 Filter Blowby
WCA012 : Iveco Astra 8848	2/01/2018	5801962827 Filtering Cartridge
WCA012 : Iveco Astra 8848	2/01/2018	Drain Water tanks, wash truck ready for serve & a
WCA012 : Iveco Astra 8848	2/01/2018	P777871 Air Filter OUT
WCA012 : Iveco Astra 8848	2/01/2018	P777875 Air Filter IN
WCA012 : Iveco Astra 8848	3/01/2018	Assist with annual service, organise incorrect fi
WCA012 : Iveco Astra 8848	4/01/2018	Annual service
WCA012 : Iveco Astra 8848	4/01/2018	Freight
WCA012 : Iveco Astra 8848	4/01/2018	P171551 Hydraulic Filter
WCA012 : Iveco Astra 8848	5/01/2018	Annual service
WCA012 : Iveco Astra 8848	5/01/2018	Annual service
WCA012 : Iveco Astra 8848	8/01/2018	Annual service
WCA012 : Iveco Astra 8848	8/01/2018	Fit tyresm electrical work on rear end, charge
WCA012 : Iveco Astra 8848	8/01/2018	P171532 Filters
WCA012 : Iveco Astra 8848	9/01/2018	Annual service
WCA012 : Iveco Astra 8848	9/01/2018	Annual service
WCA012 : Iveco Astra 8848	11/01/2018	40100963 Shaft Seal
WCA012 : Iveco Astra 8848	11/01/2018	504098575 Axle Interlock Sensor
WCA012 : Iveco Astra 8848	11/01/2018	Annual service
WCA012 : Iveco Astra 8848	11/01/2018	Diff Flange Locking Nut
WCA012 : Iveco Astra 8848	11/01/2018	Freight
WCA012 : Iveco Astra 8848	12/01/2018	Repairs from annual service
WCA012 : Iveco Astra 8848	15/01/2018	315/80R22.5 M840 Tyres
WCA012 : Iveco Astra 8848	15/01/2018	Exit inspection
WCA012 : Iveco Astra 8848	15/01/2018	Fill water trucks with JF & test sprays
WCA012 : Iveco Astra 8848	15/01/2018	Scrap Tyres
WCA012 : Iveco Astra 8848	15/01/2018	Tyre Fitting Charge
WCA012 : Iveco Astra 8848	16/01/2018	40101023 Pinion Seal Corteco#
WCA012 : Iveco Astra 8848	16/01/2018	Parts
WCA012 : Iveco Astra 8848	16/01/2018	Water cannon repairs

WCA012 : Iveco Astra 8848	17/01/2018	Water cannon repairs & test
WCA012 : Iveco Astra 8848	18/01/2018	Repair oil leak
WCA012 : Iveco Astra 8848	19/01/2018	Parts
WCA012 : Iveco Astra 8848	7/02/2018	Replace beacon on roof
WCA012 : Iveco Astra 8848	9/02/2018	Bolts on tray mount
WCA012 : Iveco Astra 8848	12/02/2018	Tighten up mounting bolts and clamps on dribble bar
WCA012 : Iveco Astra 8848	17/02/2018	Travel to site carry out plant inspections
WCA012 : Iveco Astra 8848	8/03/2018	Headlight
WCA012 : Iveco Astra 8848	13/03/2018	CHECKING OIL
WCA012 : Iveco Astra 8848	22/03/2018	WORK ON PLANT DRIBBLE BAR, TRAVEL TO SITE
WCA012 : Iveco Astra 8848	24/03/2018	DRIBBLE BAR
WCA012 : Iveco Astra 8848	24/03/2018	DRIVE BAR FAULT, TEST BAR, CLEAN OUT AND STRAIGHTEN
WCA012 : Iveco Astra 8848	27/03/2018	Inspect dribble bar not working
WCA012 : Iveco Astra 8848	28/03/2018	Carry out repairs to dribble bar
wca012 : Iveco Astra 8848	5/04/2018	Carry out repairs to lights as required
WCA012 : Iveco Astra 8848	20/04/2018	LOCATED WATER CART, REPAIR OIL LEAK AND TOPPED UP GE
WCA012 : Iveco Astra 8848	26/04/2018	JUMP START
WCA012 : Iveco Astra 8848	20/05/2018	Travel to village, free up ringfeder, check plumb
wca012 : Iveco Astra 8848	21/05/2018	Cam lock fittings
wca012 : Iveco Astra 8848	22/05/2018	Fittings
WCA012 : Iveco Astra 8848	22/05/2018	INSTALL MALE CAM LOCK
WCA012 : Iveco Astra 8848	23/05/2018	FIT CAMLOCK FITTINGS
WCA012 : Iveco Astra 8848	27/05/2018	ASSIST WITH TYRE REMOVAL TO WATERCART
wca012 : Iveco Astra 8848	29/05/2018	GME hand piece
WCA012 : Iveco Astra 8848	30/06/2018	INSPECT PTO OIL LEAK
WCA012 : Iveco Astra 8848	3/07/2018	AIR CLEANERS OUTER
wca012 : Iveco Astra 8848	17/07/2018	800HR SERV KIT
WCA012 : Iveco Astra 8848	19/07/2018	MAINTENANCE ON WCA
WCA012 : Iveco Astra 8848	19/07/2018	TRANS & HYD OIL LEAK
WCA012 : Iveco Astra 8848	20/07/2018	REPAIR TRANS OIL LEAK
WCA012 : Iveco Astra 8848	20/07/2018	TRANS LEAK
WCA012 : Iveco Astra 8848	22/07/2018	800HR SERVICE
WCA012 : Iveco Astra 8848	22/07/2018	800HR SERVICE
WCA012 : Iveco Astra 8848	23/07/2018	FINISH SERVICE/FIT BELLY PLATE
WCA012 : Iveco Astra 8848	26/07/2018	2 X 315/80R22.5 1 X RIM 22.5X9 SECOND HAND
WCA012 : Iveco Astra 8848	26/07/2018	REMOVE PUMP
WCA012 : Iveco Astra 8848	1/08/2018	BEARINGS FOR PUMP
WCA012 : Iveco Astra 8848	3/08/2018	PUMP & FAILED BEARING
WCA012 : Iveco Astra 8848	3/08/2018	PUMP INOP
WCA012 : Iveco Astra 8848	6/08/2018	PUMP REPAIRS
WCA012 : Iveco Astra 8848	6/08/2018	REPAIR/REASSEMBLE WATER PUMP
WCA012 : Iveco Astra 8848	7/08/2018	PUMP REFIT
WCA012 : Iveco Astra 8848	7/08/2018	REFIT WATER PUMP
WCA012 : Iveco Astra 8848	9/08/2018	Parts
WCA012 : Iveco Astra 8848	11/08/2018	REAR PUMP ISSUE
WCA012 : Iveco Astra 8848	13/08/2018	ROCK JAMMED IN DUALS
WCA012 : Iveco Astra 8848	14/08/2018	PUMP COUPLING
WCA012 : Iveco Astra 8848	15/08/2018	DRIVE COUPLING PTO
WCA012 : Iveco Astra 8848	19/08/2018	FIT POWER STEER FILTERS
WCA012 : Iveco Astra 8848	21/08/2018	FAILED PUMP COUPLING
WCA012 : Iveco Astra 8848	21/08/2018	REMOVE HYDRAULIC MOTOR & INSPECT PUMP

WCA012 : Iveco Astra 8848	22/08/2018	INSTALL NEW PUMP
WCA012 : Iveco Astra 8848	22/08/2018	REPLACE PUMP & COUPLING
WCA012 : Iveco Astra 8848	24/08/2018	DRIBBLE BAR FAULT
WCA012 : Iveco Astra 8848	25/08/2018	Luke Tonkin
WCA012 : Iveco Astra 8848	26/08/2018	Repair in oil, horn and flashing light.
WCA012 : Iveco Astra 8848	29/08/2018	DRIVE COUPLINGS NOLATHANE
WCA012 : Iveco Astra 8848	29/08/2018	Exit inspection & repair
WCA012 : Iveco Astra 8848	29/08/2018	Exit inspection, repair lights wiring repair wheel
WCA012 : Iveco Astra 8848	29/08/2018	Exit inspection, repair lights wiring, wheel
WCA012 : Iveco Astra 8848	29/08/2018	NUMBER PLATE LIGHT / H7
WCA012 : Iveco Astra 8848	31/08/2018	Freight
WCA012 : Iveco Astra 8848	3/09/2018	Fit lights & coupler
WCA012 : Iveco Astra 8848	3/09/2018	REPAIRS FOR MCRIVER
WCA012 : Iveco Astra 8848	6/09/2018	Tyres X 5 , ROTATION AND BALANCE
WCA012 : Iveco Astra 8848	13/09/2018	Cannon
WCA012 : Iveco Astra 8848	13/09/2018	Check cannon
WCA012 : Iveco Astra 8848	18/09/2018	Drop box
WCA012 : Iveco Astra 8848	18/09/2018	Look at issue with high range got no drive
WCA012 : Iveco Astra 8848	20/09/2018	800HR SERVICE
WCA012 : Iveco Astra 8848	26/10/2018	Inflate tyres
WCA012 : Iveco Astra 8848	31/10/2018	Parts
WCA012 : Iveco Astra 8848	16/11/2018	Fit new tail light covers
WCA012 : Iveco Astra 8848	30/11/2018	Drop box fault
WCA012 : Iveco Astra 8848	1/12/2018	Assist refit drop box
WCA012 : Iveco Astra 8848	1/12/2018	Remove & inspect drop box, check over system
WCA012 : Iveco Astra 8848	2/12/2018	Assist repairs
WCA012 : Iveco Astra 8848	2/12/2018	Gearbox problem
WCA012 : Iveco Astra 8848	2/12/2018	High/low range fault
WCA012 : Iveco Astra 8848	2/12/2018	Remove drop box & disassemble
WCA012 : Iveco Astra 8848	4/12/2018	Tyres
WCA012 : Iveco Astra 8848	7/12/2018	Drive to hotshot
WCA012 : Iveco Astra 8848	8/12/2018	Parts
WCA012 : Iveco Astra 8848	8/12/2018	Parts collection
WCA012 : Iveco Astra 8848	9/12/2018	Prep drop box for assembly
WCA012 : Iveco Astra 8848	9/12/2018	Return parts
WCA012 : Iveco Astra 8848	10/12/2018	Overhaul & refit drop box, demobe work
WCA012 : Iveco Astra 8848	10/12/2018	Refit dribble baro valve
WCA012 : Iveco Astra 8848	10/12/2018	Remove pos 7,10 tyres help install rear dribble
WCA012 : Iveco Astra 8848	11/12/2018	Change out tyres & pick up from KAL TYRES
WCA012 : Iveco Astra 8848	11/12/2018	Put together transfer box fitted to truck
WCA012 : Iveco Astra 8848	13/12/2018	Remove rear spray & bumper try lading up
WCA012 : Iveco Astra 8848	15/12/2018	Fill with water, test machine, fixed leak
WCA012 : Iveco Astra 8848	15/12/2018	Start exit inspection
WCA012 : Iveco Astra 8848	16/12/2018	Help check over & inspect
WCA012 : Iveco Astra 8848	21/12/2018	Inspect pump fault, show operators how to use
WCA012 : Iveco Astra 8848	23/12/2018	Inspect faults
WCA012 : Iveco Astra 8848	3/01/2019	Pick up tyres from Bridgestone
WCA012 : Iveco Astra 8848	4/01/2019	Organise tyres, top up Addblue
WCA012 : Iveco Astra 8848	5/01/2019	Water pump coupling fault, investigate parts
WCA012 : Iveco Astra 8848	7/01/2019	organise drive couplings for water pump
WCA012 : Iveco Astra 8848	8/01/2019	Load tyres for Bridgestone

WCA012 : Iveco Astra 8848	8/01/2019	Load tyres onto float & ongoing tyre repairs
WCA012 : Iveco Astra 8848	8/01/2019	Tyres for WCA012
WCA012 : Iveco Astra 8848	9/01/2019	Parts
WCA012 : Iveco Astra 8848	10/01/2019	Collect parts
WCA012 : Iveco Astra 8848	11/01/2019	Oil & Lubricants
WCA012 : Iveco Astra 8848	12/01/2019	Carry out repairs to water truck, pump coupling
WCA012 : Iveco Astra 8848	12/01/2019	Replace water pump coupling
WCA012 : Iveco Astra 8848	14/01/2019	Check pos 4 wheel tension
WCA012 : Iveco Astra 8848	22/01/2019	Parts
WCA012 : Iveco Astra 8848	24/01/2019	Organise coupling/travel to get parts
WCA012 : Iveco Astra 8848	24/01/2019	Parts
WCA012 : Iveco Astra 8848	25/01/2019	Change pump coupling,pick up parts from Toll
WCA012 : Iveco Astra 8848	26/01/2019	Change out pos 7 tyre,coupling fault
WCA012 : Iveco Astra 8848	29/01/2019	Organise tyres
WCA012 : Iveco Astra 8848	29/01/2019	Tyres
WCA012 : Iveco Astra 8848	30/01/2019	Order parts
WCA012 : Iveco Astra 8848	30/01/2019	Pick up parts in town
WCA012 : Iveco Astra 8848	31/01/2019	Parts
WCA012 : Iveco Astra 8848	1/02/2019	Parts
WCA012 : Iveco Astra 8848	6/02/2019	Parts
WCA012 : Iveco Astra 8848	14/02/2019	Parts
WCA012 : Iveco Astra 8848	25/02/2019	Spray fault,top up add blue
WCA012 : Iveco Astra 8848	1/03/2019	Replace front pump coupling element
WCA012 : Iveco Astra 8848	1/03/2019	Replace PTO element
WCA012 : Iveco Astra 8848	1/03/2019	Water pump element
WCA012 : Iveco Astra 8848	2/03/2019	Coupling alignment pto
WCA012 : Iveco Astra 8848	2/03/2019	PTO coupling alignment
WCA012 : Iveco Astra 8848	2/03/2019	Water cannon
WCA012 : Iveco Astra 8848	3/03/2019	Hyd pump alignent
WCA012 : Iveco Astra 8848	3/03/2019	PTO coupling alignment
WCA012 : Iveco Astra 8848	3/03/2019	PTO couplng alignment
WCA012 : Iveco Astra 8848	4/03/2019	Cannon wiring
WCA012 : Iveco Astra 8848	4/03/2019	Inspect machine
WCA012 : Iveco Astra 8848	4/03/2019	Repair cannon wiring.inspect
WCA012 : Iveco Astra 8848	5/03/2019	Warning light issues
WCA012 : Iveco Astra 8848	6/03/2019	Service
WCA012 : Iveco Astra 8848	13/03/2019	Parts
WCA012 : Iveco Astra 8848	15/03/2019	Parts
WCA012 : Iveco Astra 8848	18/03/2019	Parts
WCA012 : Iveco Astra 8848	21/03/2019	Service
WCA012 : Iveco Astra 8848	23/03/2019	Warning light
WCA012 : Iveco Astra 8848	29/03/2019	Parts
WCA012 : Iveco Astra 8848	30/03/2019	Repair water leaks
WCA012 : Iveco Astra 8848	6/04/2019	Change POS 1 Tyre
WCA012 : Iveco Astra 8848	6/04/2019	Remove and replace tyre
WCA012 : Iveco Astra 8848	9/04/2019	Parts
WCA012 : Iveco Astra 8848	10/04/2019	Tyre repair
WCA012 : Iveco Astra 8848	14/04/2019	Key switch P6 tier
WCA012 : Iveco Astra 8848	16/04/2019	C/O W/pump
WCA012 : Iveco Astra 8848	16/04/2019	Parts
WCA012 : Iveco Astra 8848	21/04/2019	1600 service/change waterpump & motor

WCA012 : Iveco Astra 8848	21/04/2019	C/O hyd pumps
WCA012 : Iveco Astra 8848	21/04/2019	Service water pump
WCA012 : Iveco Astra 8848	22/04/2019	Fit pump & drive motor, hose connections, hyd filt
WCA012 : Iveco Astra 8848	22/04/2019	hyd pump 7 water pump repairs
WCA012 : Iveco Astra 8848	23/04/2019	Pos 4 tyre
WCA012 : Iveco Astra 8848	23/04/2019	Repair hyd pump
WCA012 : Iveco Astra 8848	23/04/2019	Spray fault.change 1x steer tyre
WCA012 : Iveco Astra 8848	25/04/2019	Check cannon
WCA012 : Iveco Astra 8848	26/04/2019	Tyre repair
WCA012 : Iveco Astra 8848	27/04/2019	Blown fuse, damaged elec loom
WCA012 : Iveco Astra 8848	30/04/2019	Parts
wca012 : Iveco Astra 8848	30/04/2019	Tyres
WCA012 : Iveco Astra 8848	1/05/2019	Fault find hose problem
WCA012 : Iveco Astra 8848	4/05/2019	PTO coupling
WCA012 : Iveco Astra 8848	4/05/2019	Remove hyd pump/repairs
WCA012 : Iveco Astra 8848	5/05/2019	Complete service & repairs
WCA012 : Iveco Astra 8848	5/05/2019	Finish 1600hr SVC & repairs
WCA012 : Iveco Astra 8848	5/05/2019	Pump coupling air cables
WCA012 : Iveco Astra 8848	5/05/2019	Remove hyd pump mountning plate & fabricate
WCA012 : Iveco Astra 8848	6/05/2019	Air dryer etc
WCA012 : Iveco Astra 8848	6/05/2019	Complete hyd pump mouting plate repairs/test
WCA012 : Iveco Astra 8848	6/05/2019	Parts
WCA012 : Iveco Astra 8848	15/05/2019	Parts
WCA012 : Iveco Astra 8848	17/05/2019	Spray fault
WCA012 : Iveco Astra 8848	18/05/2019	Repair elec fault
WCA012 : Iveco Astra 8848	23/05/2019	Parts
WCA012 : Iveco Astra 8848	24/05/2019	Prep fopr transport, wash
WCA012 : Iveco Astra 8848	25/05/2019	Disassemble, load on float
WCA012 : Iveco Astra 8848	25/05/2019	Prep & load on float for transport
WCA012 : Iveco Astra 8848	25/05/2019	Remove rear fill point/load float
WCA012 : Iveco Astra 8848	26/05/2019	Parts
WCA012 : Iveco Astra 8848	29/05/2019	Parts
WCA012 : Iveco Astra 8848	14/06/2019	Check sheet delivery inspection,fill tank,check
WCA012 : Iveco Astra 8848	14/06/2019	Entry inspection,live test water system
WCA012 : Iveco Astra 8848	14/06/2019	Tick sheet
WCA012 : Iveco Astra 8848	17/06/2019	Annual service
WCA012 : Iveco Astra 8848	17/06/2019	Annual service
WCA012 : Iveco Astra 8848	17/06/2019	Annual service dran fluids remove hyd tank, check
WCA012 : Iveco Astra 8848	17/06/2019	Annual Service kit
WCA012 : Iveco Astra 8848	17/06/2019	Parts
WCA012 : Iveco Astra 8848	18/06/2019	Annual service
WCA012 : Iveco Astra 8848	18/06/2019	Annual service
WCA012 : Iveco Astra 8848	18/06/2019	Annual service, hyd tank strip & grease tension
WCA012 : Iveco Astra 8848	19/06/2019	A/C & Serpentine Belt
WCA012 : Iveco Astra 8848	19/06/2019	Annual service
WCA012 : Iveco Astra 8848	19/06/2019	Annual service
WCA012 : Iveco Astra 8848	19/06/2019	Annual service/jack up on stands
WCA012 : Iveco Astra 8848	19/06/2019	Parts
WCA012 : Iveco Astra 8848	20/06/2019	Annual service/clean & inspect wheel hubs
WCA012 : Iveco Astra 8848	20/06/2019	Assist with annual repairs
WCA012 : Iveco Astra 8848	20/06/2019	Fab of wheel hub socket

WCA012 : Iveco Astra 8848	20/06/2019	Stripped P2 wheel further down, start cleaning par
WCA012 : Iveco Astra 8848	21/06/2019	Ad Blue Filter
WCA012 : Iveco Astra 8848	21/06/2019	Annual service
WCA012 : Iveco Astra 8848	21/06/2019	Clean planetary & hubs/inspect
WCA012 : Iveco Astra 8848	21/06/2019	Finish cleaning all hib reduction parts & inspect
wca012 : Iveco Astra 8848	24/06/2019	add blue filter
WCA012 : Iveco Astra 8848	24/06/2019	Annual service, rear wiring circuit repair
WCA012 : Iveco Astra 8848	24/06/2019	Fit/secure hyd tank
WCA012 : Iveco Astra 8848	24/06/2019	Remove radiator & changed fan belts, removed
WCA012 : Iveco Astra 8848	25/06/2019	4pk1160 belt
WCA012 : Iveco Astra 8848	25/06/2019	Cleaned, removed radiator, finished refitting fan b
WCA012 : Iveco Astra 8848	25/06/2019	Fit & check for leaks hyd tank, fit trams under gu
WCA012 : Iveco Astra 8848	25/06/2019	Repair & install rear tail light circuits/annual s
WCA012 : Iveco Astra 8848	25/06/2019	Sort out parts
WCA012 : Iveco Astra 8848	26/06/2019	Annual service
WCA012 : Iveco Astra 8848	26/06/2019	Annual Service Parts
WCA012 : Iveco Astra 8848	26/06/2019	Annual Service Parts
WCA012 : Iveco Astra 8848	26/06/2019	Fit 4 test 2 beacons
WCA012 : Iveco Astra 8848	26/06/2019	Parts
WCA012 : Iveco Astra 8848	26/06/2019	Refit radiator, blew intercooler & condensor
WCA012 : Iveco Astra 8848	27/06/2019	Annual service, repair clearance lights
WCA012 : Iveco Astra 8848	27/06/2019	Finish refitting radiator, grease nipples blocked
WCA012 : Iveco Astra 8848	27/06/2019	Organise replacement for incorrect parts
WCA012 : Iveco Astra 8848	27/06/2019	Parts
WCA012 : Iveco Astra 8848	27/06/2019	Parts
WCA012 : Iveco Astra 8848	27/06/2019	Pos 6 Wheel Bearings
WCA012 : Iveco Astra 8848	27/06/2019	Repluee side mirror
WCA012 : Iveco Astra 8848	28/06/2019	Annual service, remove u/s dribble bar
WCA012 : Iveco Astra 8848	28/06/2019	Diagnosed & repaired multiple air leaks
WCA012 : Iveco Astra 8848	28/06/2019	Repair number plate, repair water pipes & leaks
WCA012 : Iveco Astra 8848	1/07/2019	Annual Service Parts
WCA012 : Iveco Astra 8848	1/07/2019	Annual service, remove mudguard in prep
WCA012 : Iveco Astra 8848	1/07/2019	Investigate & repair modify rear water spreader
WCA012 : Iveco Astra 8848	1/07/2019	Parts
WCA012 : Iveco Astra 8848	1/07/2019	Signage
WCA012 : Iveco Astra 8848	1/07/2019	Wheel Seals. Planetary O-Rings
WCA012 : Iveco Astra 8848	2/07/2019	Annual service
WCA012 : Iveco Astra 8848	2/07/2019	Fit hoses, bearings, seals
WCA012 : Iveco Astra 8848	2/07/2019	Parts
WCA012 : Iveco Astra 8848	2/07/2019	Repair welds on tray
WCA012 : Iveco Astra 8848	2/07/2019	RingFeder Hitch, Mudflaps
WCA012 : Iveco Astra 8848	3/07/2019	2nd Axle Suspension Pins/Bushes
WCA012 : Iveco Astra 8848	4/07/2019	Prep for wheel bearing adjustments
WCA012 : Iveco Astra 8848	5/07/2019	Adjust wheel bearings, assemble final drives, fit
WCA012 : Iveco Astra 8848	5/07/2019	Annual service
WCA012 : Iveco Astra 8848	5/07/2019	Annual service, fit all okanetary suts, brake drum
WCA012 : Iveco Astra 8848	5/07/2019	Assisy assembling wheel ends
WCA012 : Iveco Astra 8848	5/07/2019	Fit signs/hitch
WCA012 : Iveco Astra 8848	5/07/2019	Wheel hubs, clean & wash wheel hubs, refit
WCA012 : Iveco Astra 8848	6/07/2019	Finish off repairs, test drive, fill with water
WCA012 : Iveco Astra 8848	6/07/2019	Remove cannon, diagnose cannon fault, fix pipe

WCA012 : Iveco Astra 8848	6/07/2019	Tension wheel nuts
WCA012 : Iveco Astra 8848	6/07/2019	Top up final drive levels, test drive, water water
WCA012 : Iveco Astra 8848	8/07/2019	Check over faults, organise repairs at ADL Iveco
WCA012 : Iveco Astra 8848	8/07/2019	Parts
WCA012 : Iveco Astra 8848	8/07/2019	Test water squirters & dribble bars
WCA012 : Iveco Astra 8848	8/07/2019	Test water system, test drive, deliver to iveco
WCA012 : Iveco Astra 8848	11/07/2019	Travel to ADL Iveco/test drive truck after repairs
WCA012 : Iveco Astra 8848	12/07/2019	Assemble baffles & place in tanks
WCA012 : Iveco Astra 8848	12/07/2019	Assemble baffles & place in tanks
WCA012 : Iveco Astra 8848	12/07/2019	Cannon Elbow, Rebuild Kit, Antenna
WCA012 : Iveco Astra 8848	12/07/2019	Drained steer hubs & resealed hub caps, fill
WCA012 : Iveco Astra 8848	12/07/2019	Finish prepping
WCA012 : Iveco Astra 8848	12/07/2019	Prepped machine for sale
WCA012 : Iveco Astra 8848	12/07/2019	Repairs
WCA012 : Iveco Astra 8848	12/07/2019	Reseal front axles outer hub seals, clean station
WCA012 : Iveco Astra 8848	12/07/2019	Spot scissor lift, installed reverse camera
WCA012 : Iveco Astra 8848	13/07/2019	Inflate tyres
WCA012 : Iveco Astra 8848	13/07/2019	Repaired quick fill mounting brackets, was chassis
WCA012 : Iveco Astra 8848	13/07/2019	Repairs
WCA012 : Iveco Astra 8848	15/07/2019	Reverse Camera
WCA012 : Iveco Astra 8848	17/07/2019	Air leak repairs and water leak repairs
WCA012 : Iveco Astra 8848	17/07/2019	Water leak and air leak
WCA012 : Iveco Astra 8848	18/07/2019	Check gear smell, service, transfer case and repla
WCA012 : Iveco Astra 8848	18/07/2019	Collect new trans sensors, assist Mark with repair
WCA012 : Iveco Astra 8848	18/07/2019	Repair water cannon
WCA012 : Iveco Astra 8848	20/07/2019	Pick up parts from Coober Pedy
WCA012 : Iveco Astra 8848	21/07/2019	Maintenance Sundry
WCA012 : Iveco Astra 8848	21/07/2019	Replace beacon codes
WCA012 : Iveco Astra 8848	22/07/2019	Carry out entry inspection, replace beacon
WCA012 : Iveco Astra 8848	22/07/2019	Change flashing lights
WCA012 : Iveco Astra 8848	22/07/2019	Entry inspection/flashing light
WCA012 : Iveco Astra 8848	23/07/2019	Parts
WCA012 : Iveco Astra 8848	26/07/2019	Parts
WCA012 : Iveco Astra 8848	27/07/2019	Check PTO noisy, remove and dismantle PTO
WCA012 : Iveco Astra 8848	27/07/2019	Scope engine light on
WCA012 : Iveco Astra 8848	28/07/2019	Dismantle PTO, Clean parts, modify clutch for
WCA012 : Iveco Astra 8848	31/07/2019	Drive Brake Shoes
WCA012 : Iveco Astra 8848	2/08/2019	Wiring repair for RH beacon light
WCA012 : Iveco Astra 8848	7/08/2019	Air leak
WCA012 : Iveco Astra 8848	7/08/2019	Rectify air leak from transfer case
WCA012 : Iveco Astra 8848	8/08/2019	20Ton Jack
WCA012 : Iveco Astra 8848	8/08/2019	Remove and replace trans speed sensor
WCA012 : Iveco Astra 8848	17/08/2019	Diagnose transfer fault
WCA012 : Iveco Astra 8848	17/08/2019	Drop box fault
WCA012 : Iveco Astra 8848	17/08/2019	Help fitters with breakdown
WCA012 : Iveco Astra 8848	17/08/2019	Inspect driveline noise, drain oil found metal
WCA012 : Iveco Astra 8848	18/08/2019	Diagnose drive line fault/make fittings for pump
WCA012 : Iveco Astra 8848	18/08/2019	Fill drop box with oil
WCA012 : Iveco Astra 8848	20/08/2019	Remove exhaust and fill hose for transport
WCA012 : Iveco Astra 8848	20/08/2019	Remove rill pipe prom
WCA012 : Iveco Astra 8848	21/08/2019	Load for transport

WCA012 : Iveco Astra 8848	23/08/2019	Bring truck into workshop, begin removing drop box
WCA012 : Iveco Astra 8848	23/08/2019	Started removing drop box
WCA012 : Iveco Astra 8848	24/08/2019	Remove & wash drop box
WCA012 : Iveco Astra 8848	24/08/2019	Remove drop box from truck, cleaned drop box
WCA012 : Iveco Astra 8848	26/08/2019	Inspect blown transfer box, Order new one
WCA012 : Iveco Astra 8848	26/08/2019	Strip down drop box & inspect
WCA012 : Iveco Astra 8848	26/08/2019	Stripped drop box & inspected failed components
WCA012 : Iveco Astra 8848	27/08/2019	Assess failed transfer box/order new
WCA012 : Iveco Astra 8848	27/08/2019	Tets air controls for drop box
WCA012 : Iveco Astra 8848	29/08/2019	New Dropbox P/N: 42128067
WCA012 : Iveco Astra 8848	30/08/2019	Fit new drop box
WCA012 : Iveco Astra 8848	30/08/2019	Prep parts to fit new drop box
WCA012 : Iveco Astra 8848	31/08/2019	Fit drop box
WCA012 : Iveco Astra 8848	31/08/2019	Fit drop box
WCA012 : Iveco Astra 8848	2/09/2019	Failure analysis of transfer
WCA012 : Iveco Astra 8848	2/09/2019	Finished refitting drop box, zip tied looms in pla
WCA012 : Iveco Astra 8848	2/09/2019	Fit drop box/check operation
WCA012 : Iveco Astra 8848	3/09/2019	Check.top up drop box oil level road test truck &
WCA012 : Iveco Astra 8848	3/09/2019	Drop off at Iveco for repairs/fault lights
WCA012 : Iveco Astra 8848	4/09/2019	Diagnose & Repair Engine Light Active
WCA012 : Iveco Astra 8848	4/09/2019	Pick up from Ivenco
WCA012 : Iveco Astra 8848	11/09/2019	Check over
WCA012 : Iveco Astra 8848	11/09/2019	Refit tank fill pipe and reverse camera
WCA012 : Iveco Astra 8848	11/09/2019	Repair air leak/check oil leak
WCA012 : Iveco Astra 8848	20/09/2019	Repalce 2x blown drive tyres
WCA012 : Iveco Astra 8848	20/09/2019	Replace blown tyres
WCA012 : Iveco Astra 8848	21/09/2019	Rectify ROPS lockpin fault, replace P6 outer tyre
WCA012 : Iveco Astra 8848	21/09/2019	Swap tyre
WCA012 : Iveco Astra 8848	30/09/2019	Replace pos 3 tyre
WCA012 : Iveco Astra 8848	2/10/2019	Remove and assess reverse camera screen
WCA012 : Iveco Astra 8848	3/10/2019	Recitfy reverse camera fault
WCA012 : Iveco Astra 8848	4/10/2019	Disposal
WCA012 : Iveco Astra 8848	4/10/2019	Replaced damaged tyre
WCA012 : Iveco Astra 8848	4/10/2019	Strip & fit Tyre
WCA012 : Iveco Astra 8848	12/10/2019	Change pos 8 outer tyre
WCA012 : Iveco Astra 8848	12/10/2019	Replace rear tyre
WCA012 : Iveco Astra 8848	15/10/2019	Swap centre spray nozzle wth LH spray nozzle
WCA012 : Iveco Astra 8848	21/10/2019	Diagnose oil leak from aux water pump motor
WCA012 : Iveco Astra 8848	21/10/2019	Inspect oil leak and blown tyre
WCA012 : Iveco Astra 8848	22/10/2019	Repalce blown tyre
WCA012 : Iveco Astra 8848	22/10/2019	Repalce pos 3 tyre, remove blown hyd hose
WCA012 : Iveco Astra 8848	8/11/2019	Remove broken flashing light
WCA012 : Iveco Astra 8848	9/11/2019	Fabricate flashing light bracket
WCA012 : Iveco Astra 8848	10/11/2019	Fabricate batter sprays, test and remove
WCA012 : Iveco Astra 8848	11/11/2019	Parts
WCA012 : Iveco Astra 8848	11/11/2019	Repalce spray heads, top up adblue
WCA012 : Iveco Astra 8848	13/11/2019	Change pos 5 tyre
WCA012 : Iveco Astra 8848	13/11/2019	Service
WCA012 : Iveco Astra 8848	14/11/2019	Fit new sprays
WCA012 : Iveco Astra 8848	14/11/2019	Fit water spray heads on rear
WCA012 : Iveco Astra 8848	17/11/2019	Modify new spray heads

WCA012 : Iveco Astra 8848	17/11/2019	Repair spray head
WCA012 : Iveco Astra 8848	21/11/2019	Freight
WCA012 : Iveco Astra 8848	21/11/2019	Parts
WCA012 : Iveco Astra 8848	21/11/2019	Tyres
WCA012 : Iveco Astra 8848	22/11/2019	Freight
WCA012 : Iveco Astra 8848	23/11/2019	Weld up canon piping bracket
WCA012 : Iveco Astra 8848	25/11/2019	Service
WCA012 : Iveco Astra 8848	26/11/2019	Change pipework to suit stabilser
WCA012 : Iveco Astra 8848	26/11/2019	Remove dribble bar and attach to stabilser
WCA012 : Iveco Astra 8848	26/11/2019	Remove dribble bar piping and replumb to stabilser
WCA012 : Iveco Astra 8848	27/11/2019	Change outlet for stabilser from 3 to 4
WCA012 : Iveco Astra 8848	29/11/2019	800hr service
WCA012 : Iveco Astra 8848	29/11/2019	Reaplace pos 4 tyre, look at batter sprays leaking
WCA012 : Iveco Astra 8848	3/12/2019	Repair hydraulic leak
WCA012 : Iveco Astra 8848	6/12/2019	Check clutch smell fault
WCA012 : Iveco Astra 8848	7/12/2019	Inspect clutch smell
WCA012 : Iveco Astra 8848	9/12/2019	Grease drive train
WCA012 : Iveco Astra 8848	11/12/2019	Check clutch fault
WCA012 : Iveco Astra 8848	15/12/2019	Check and prep for towing
WCA012 : Iveco Astra 8848	15/12/2019	Check and prepare plan for towing
WCA012 : Iveco Astra 8848	17/12/2019	Recover watercart from TN115
WCA012 : Iveco Astra 8848	10/01/2020	Load on float
WCA012 : Iveco Astra 8848	10/01/2020	Load onto float
WCA012 : Iveco Astra 8848	13/01/2020	Assist unloading & moving into workshop
WCA012 : Iveco Astra 8848	13/01/2020	Flywheel, clutch, bearing
WCA012 : Iveco Astra 8848	13/01/2020	Pressure clean/remove from float/move into w/s
WCA012 : Iveco Astra 8848	13/01/2020	Remove tray
WCA012 : Iveco Astra 8848	13/01/2020	W/S clutch-remove tray body casr access for clutch
WCA012 : Iveco Astra 8848	14/01/2020	Flywheel, clutch, bearing
WCA012 : Iveco Astra 8848	14/01/2020	Remove gearbox & clutch
WCA012 : Iveco Astra 8848	14/01/2020	Remove trans clutch & clutch drive plate
WCA012 : Iveco Astra 8848	15/01/2020	Fab spring loaded chassis mounts
WCA012 : Iveco Astra 8848	15/01/2020	Parts
WCA012 : Iveco Astra 8848	15/01/2020	Parts
WCA012 : Iveco Astra 8848	15/01/2020	Parts- CHASSIS BOLTS
WCA012 : Iveco Astra 8848	15/01/2020	Piack up parts for gawler
WCA012 : Iveco Astra 8848	15/01/2020	Prep & sort out parts/trans repairs
WCA012 : Iveco Astra 8848	15/01/2020	Prep of components for new clutchn install
WCA012 : Iveco Astra 8848	16/01/2020	2x Hoses
WCA012 : Iveco Astra 8848	16/01/2020	Bearing
WCA012 : Iveco Astra 8848	16/01/2020	Fab & modify chassis to try and mounts
WCA012 : Iveco Astra 8848	16/01/2020	Fab new tray mounts & paint/cut off old mounts
WCA012 : Iveco Astra 8848	16/01/2020	Fit put up clutch drive plate clutch
WCA012 : Iveco Astra 8848	16/01/2020	Install clutch & gearbox
WCA012 : Iveco Astra 8848	16/01/2020	Machine clutch drive plate
WCA012 : Iveco Astra 8848	17/01/2020	Batteries
WCA012 : Iveco Astra 8848	17/01/2020	Cross member repairs
WCA012 : Iveco Astra 8848	17/01/2020	Fit clutch & gearbox & alll associated components
WCA012 : Iveco Astra 8848	17/01/2020	Install trans run up/moved to painters
WCA012 : Iveco Astra 8848	17/01/2020	Parts
WCA012 : Iveco Astra 8848	17/01/2020	Sandblast/prime & paint chsis

WCA012 : Iveco Astra 8848	17/01/2020	Weld on new tray mounts repair cracks in tray
WCA012 : Iveco Astra 8848	18/01/2020	Prep chassis for tray to be fitted & fit tray
WCA012 : Iveco Astra 8848	18/01/2020	Repair cracks in tray/weld on new stauff clamp
WCA012 : Iveco Astra 8848	18/01/2020	Repaired faulty clearance lights/refitted tray to
WCA012 : Iveco Astra 8848	18/01/2020	Wiring repairs/prepped tray/sintalled ump & isntal
WCA012 : Iveco Astra 8848	20/01/2020	Clutch & gearbox install/fit tray & all wiring
WCA012 : Iveco Astra 8848	20/01/2020	Engine blow by filter & Gaskets.
WCA012 : Iveco Astra 8848	20/01/2020	Installing tray modified tray mounts
WCA012 : Iveco Astra 8848	21/01/2020	Finish tray install resealed P6 & P8 hubs
WCA012 : Iveco Astra 8848	21/01/2020	Repair rear wiring issue/fit new engine & breather
WCA012 : Iveco Astra 8848	22/01/2020	Exit check list & repairs to belly guard
WCA012 : Iveco Astra 8848	22/01/2020	Test watereing components/fit exhaust & stack
WCA012 : Iveco Astra 8848	23/01/2020	Install new UHF arrial
WCA012 : Iveco Astra 8848	29/01/2020	Entry inspection, refit water pipe at rear
WCA012 : Iveco Astra 8848	29/01/2020	Fit back on feed pipe to stabiliser
WCA012 : Iveco Astra 8848	29/01/2020	Strip & Fit
WCA012 : Iveco Astra 8848	29/01/2020	Supply new tyre for spare
WCA012 : Iveco Astra 8848	31/01/2020	Clutch adjustment/calibration
WCA012 : Iveco Astra 8848	31/01/2020	Parts
WCA012 : Iveco Astra 8848	13/02/2020	Parts
WCA012 : Iveco Astra 8848	14/02/2020	Insepct UHF
WCA012 : Iveco Astra 8848	19/02/2020	Remove ad blue cap lock
WCA012 : Iveco Astra 8848	19/02/2020	Repair ring feeder
WCA012 : Iveco Astra 8848	10/03/2020	315/80R22.5
WCA012 : Iveco Astra 8848	13/03/2020	Check clutch issue
WCA012 : Iveco Astra 8848	13/03/2020	Check clutch smell
WCA012 : Iveco Astra 8848	20/03/2020	Repalce flat tyre
WCA012 : Iveco Astra 8848	20/03/2020	Steering fault light
WCA012 : Iveco Astra 8848	24/03/2020	Retension belly plate bolts
WCA012 : Iveco Astra 8848	24/03/2020	Tighten up belly plate
WCA012 : Iveco Astra 8848	2/04/2020	Diagnose and repair beacon
WCA012 : Iveco Astra 8848	2/04/2020	Repair flashing light and wipers
WCA012 : Iveco Astra 8848	3/04/2020	Tyres
WCA012 : Iveco Astra 8848	9/04/2020	Repalce aerial, top up coolant, change globe
WCA012 : Iveco Astra 8848	11/04/2020	Pos 1 flat tyre
WCA012 : Iveco Astra 8848	17/04/2020	Diagnose and attempt repair to PTO speed
WCA012 : Iveco Astra 8848	17/04/2020	Diagnose and repair PTO fault
WCA012 : Iveco Astra 8848	21/04/2020	385/65R22.5 160K 18 BS M748
WCA012 : Iveco Astra 8848	27/04/2020	Exit inspection
WCA012 : Iveco Astra 8848	29/04/2020	Organise collection of parts at Port Augusta
WCA012 : Iveco Astra 8848	30/04/2020	Remove PTO Drive for repair
WCA012 : Iveco Astra 8848	1/05/2020	Assist with tyre change out
WCA012 : Iveco Astra 8848	1/05/2020	PTO Drive, ignition, wiring fault, light on dash
WCA012 : Iveco Astra 8848	2/05/2020	Wash vehicle, fix air leaks, refit PTO assem
WCA012 : Iveco Astra 8848	15/05/2020	Parts
WCA012 : Iveco Astra 8848	26/05/2020	Annual service
WCA012 : Iveco Astra 8848	26/05/2020	Start annual service
WCA012 : Iveco Astra 8848	27/05/2020	Annual service, remove all hubs and adjust heels b
WCA012 : Iveco Astra 8848	27/05/2020	Continue annual service, replace diff lock switch
WCA012 : Iveco Astra 8848	27/05/2020	Help fitters with repairs and service
wca012 : Iveco Astra 8848	27/05/2020	Service

WCA012 : Iveco Astra 8848	28/05/2020	Annual service, adjust all rear wheel brgs
WCA012 : Iveco Astra 8848	28/05/2020	Continue annual service
WCA012 : Iveco Astra 8848	29/05/2020	Disassemble and assemble PTO, drain and clean filt
WCA012 : Iveco Astra 8848	29/05/2020	PTO Repairs
WCA012 : Iveco Astra 8848	29/05/2020	Remove PTO assembly and idsassemble
WCA012 : Iveco Astra 8848	30/05/2020	Annual service
WCA012 : Iveco Astra 8848	30/05/2020	Finish annual service, fit PTO and check for leaks
WCA012 : Iveco Astra 8848	30/05/2020	Pick up freight
WCA012 : Iveco Astra 8848	1/06/2020	Sort out dribble bar components, plumbing repairs
WCA012 : Iveco Astra 8848	2/06/2020	Reseal final drive cover
WCA012 : Iveco Astra 8848	15/06/2020	1x 385/65 R22.5 Steer
WCA012 : Iveco Astra 8848	16/06/2020	Repalce pump coupling, check over
WCA012 : Iveco Astra 8848	23/06/2020	Freight
WCA012 : Iveco Astra 8848	23/06/2020	PTO Housing
WCA012 : Iveco Astra 8848	25/06/2020	Freight
WCA012 : Iveco Astra 8848	25/06/2020	PTO Housing
WCA012 : Iveco Astra 8848	29/06/2020	Freight
WCA012 : Iveco Astra 8848	18/07/2020	Repair coolant header tank, 2x drive tyres to rims
WCA012 : Iveco Astra 8848	26/07/2020	Tight trans guard bolts
WCA012 : Iveco Astra 8848	31/07/2020	Coolant leak, investigate
WCA012 : Iveco Astra 8848	31/07/2020	DO GREYHOUND FREIGHT
WCA012 : Iveco Astra 8848	31/07/2020	Header Tank
WCA012 : Iveco Astra 8848	1/08/2020	Removed PTO and disassemble, rebuild PTO, refit
WCA012 : Iveco Astra 8848	2/08/2020	Continue installing PTO
WCA012 : Iveco Astra 8848	2/08/2020	Finish installing PTO, remove and replace header t
WCA012 : Iveco Astra 8848	3/08/2020	Freight
WCA012 : Iveco Astra 8848	4/08/2020	PTO Sender
WCA012 : Iveco Astra 8848	6/08/2020	Ian Fleming
WCA012 : Iveco Astra 8848	7/08/2020	Fit PTO spool sensor
WCA012 : Iveco Astra 8848	7/08/2020	Fit PTO spool sensor
WCA012 : Iveco Astra 8848	12/08/2020	Inspect no water flow, broken coupling
WCA012 : Iveco Astra 8848	14/08/2020	Exit sheet, repair air leaks, filler pipe on tank
WCA012 : Iveco Astra 8848	14/08/2020	Fit filler pipe to back of tank
WCA012 : Iveco Astra 8848	15/08/2020	Repair lights
WCA012 : Iveco Astra 8848	16/08/2020	Deflate all tyres
WCA012 : Iveco Astra 8848	16/08/2020	Lower tyre pressure
WCA012 : Iveco Astra 8848	18/08/2020	Sort out breakdown/oil leaks alics springs
WCA012 : Iveco Astra 8848	19/08/2020	Subcontractor - Plant Maintenance
WCA012 : Iveco Astra 8848	1/09/2020	Remove cannon from WCA013, take to Marla
WCA012 : Iveco Astra 8848	6/09/2020	Coolant hose
WCA012 : Iveco Astra 8848	7/09/2020	Order tyres & rims
WCA012 : Iveco Astra 8848	9/09/2020	PTO
WCA012 : Iveco Astra 8848	9/09/2020	Remove PTO for repairs
WCA012 : Iveco Astra 8848	10/09/2020	Pump, tank etc
WCA012 : Iveco Astra 8848	10/09/2020	Remove & disassemble PTO, replace release fork
WCA012 : Iveco Astra 8848	10/09/2020	Remove broken couplings for sizing, remove hyd
WCA012 : Iveco Astra 8848	11/09/2020	Hyd issue
WCA012 : Iveco Astra 8848	11/09/2020	Parts
WCA012 : Iveco Astra 8848	13/09/2020	Clean & inspect hyd tank
WCA012 : Iveco Astra 8848	13/09/2020	Parts
WCA012 : Iveco Astra 8848	13/09/2020	Tank ect

WCA012 : Iveco Astra 8848	15/09/2020	Pick up hyd tank, remove baffle, clean tank
WCA012 : Iveco Astra 8848	18/09/2020	Defect list
WCA012 : Iveco Astra 8848	18/09/2020	Remove & change flat tyre
WCA012 : Iveco Astra 8848	20/09/2020	Check wont start fault, diagnose eng issue
WCA012 : Iveco Astra 8848	21/09/2020	Cont diagnosing start issue
WCA012 : Iveco Astra 8848	21/09/2020	Parts
WCA012 : Iveco Astra 8848	21/09/2020	Parts
WCA012 : Iveco Astra 8848	21/09/2020	Parts
WCA012 : Iveco Astra 8848	21/09/2020	Parts
WCA012 : Iveco Astra 8848	22/09/2020	385/65R22.5 160K 18 BS M748
WCA012 : Iveco Astra 8848	22/09/2020	Inspect for problem with engine
WCA012 : Iveco Astra 8848	23/09/2020	Inspect eng etc manufacture valve to change brake
WCA012 : Iveco Astra 8848	25/09/2020	Recovery of vehicle & laoding
WCA012 : Iveco Astra 8848	30/09/2020	Unload dead truck off float
WCA012 : Iveco Astra 8848	30/09/2020	Unload from float
WCA012 : Iveco Astra 8848	1/10/2020	Remove water filler pipe and dribble bar mount
WCA012 : Iveco Astra 8848	1/10/2020	Remove water filler pipe, exhaust stack and tow to
WCA012 : Iveco Astra 8848	2/10/2020	Off load water bouxer in w/bay
WCA012 : Iveco Astra 8848	2/10/2020	Unload
WCA012 : Iveco Astra 8848	6/10/2020	Order filters
WCA012 : Iveco Astra 8848	6/10/2020	Wash & inspect engine to transmission fault
WCA012 : Iveco Astra 8848	6/10/2020	Wash/look for bearing noise in gearbox
WCA012 : Iveco Astra 8848	7/10/2020	Eng/gear box fault, tray removal
WCA012 : Iveco Astra 8848	7/10/2020	Inspect & fault find engine/trans faults
WCA012 : Iveco Astra 8848	7/10/2020	Look for gearbox fault, start removing tray
WCA012 : Iveco Astra 8848	7/10/2020	Oil Filters
WCA012 : Iveco Astra 8848	7/10/2020	Order & chase up eng filters & confirm correct oil
WCA012 : Iveco Astra 8848	7/10/2020	Parts
WCA012 : Iveco Astra 8848	8/10/2020	Assist with removal of body
WCA012 : Iveco Astra 8848	8/10/2020	Process SOS
WCA012 : Iveco Astra 8848	8/10/2020	Remove tray from truck/wash truck, drian gear ox
WCA012 : Iveco Astra 8848	8/10/2020	Removed tray off truck/pressure wash truck/chassis
WCA012 : Iveco Astra 8848	9/10/2020	Disconnected everything off gearbox
WCA012 : Iveco Astra 8848	9/10/2020	Fab lifting lugs for tray/tack weld in place
WCA012 : Iveco Astra 8848	9/10/2020	Fit & weld ufting lugs to tank frame
WCA012 : Iveco Astra 8848	9/10/2020	Pick up parts
WCA012 : Iveco Astra 8848	9/10/2020	Remove transmission
WCA012 : Iveco Astra 8848	9/10/2020	Remove watertanks & gear box
WCA012 : Iveco Astra 8848	12/10/2020	Courier
WCA012 : Iveco Astra 8848	12/10/2020	Courier
WCA012 : Iveco Astra 8848	12/10/2020	Parts
WCA012 : Iveco Astra 8848	12/10/2020	Remove flange sand prep to remove water tank
WCA012 : Iveco Astra 8848	12/10/2020	Remove water tanks form truck tray
WCA012 : Iveco Astra 8848	12/10/2020	Repairs to tray & water tanks
WCA012 : Iveco Astra 8848	13/10/2020	Inductions
WCA012 : Iveco Astra 8848	13/10/2020	Remove air bag, remove PTO, disassemble PTO
WCA012 : Iveco Astra 8848	13/10/2020	Remove rear watertank, cut off flange, clean up
WCA012 : Iveco Astra 8848	13/10/2020	Remove water tank from frame remove fittings
WCA012 : Iveco Astra 8848	14/10/2020	Clean live driver parts
WCA012 : Iveco Astra 8848	14/10/2020	Clean PTO parts
WCA012 : Iveco Astra 8848	14/10/2020	Parts

WCA012 : Iveco Astra 8848	14/10/2020	Remove flange front tank, remove pipes
WCA012 : Iveco Astra 8848	14/10/2020	Remove water tank & brackets
WCA012 : Iveco Astra 8848	15/10/2020	Clean live drive parts, disassemble,move up toolin
WCA012 : Iveco Astra 8848	15/10/2020	CLEAN PARTS, INSTALL AIRBAG, DISSASSEMBLE PTO
WCA012 : Iveco Astra 8848	15/10/2020	Fip water tank, remove & sort water balls
WCA012 : Iveco Astra 8848	15/10/2020	Order tyres
WCA012 : Iveco Astra 8848	15/10/2020	Remove balls from tank
wca012 : Iveco Astra 8848	16/10/2020	315/80R22.5 156/150J BS M840
wca012 : Iveco Astra 8848	16/10/2020	Rotate Tube & Tyre
wca012 : Iveco Astra 8848	16/10/2020	SCRAP 1 x Held for Runout
wca012 : Iveco Astra 8848	16/10/2020	Strip & Fit
WCA012 : Iveco Astra 8848	19/10/2020	Move ahead in wokrshop/fit wheels
WCA012 : Iveco Astra 8848	19/10/2020	Refit drive wheels to truck & tension/push truck
WCA012 : Iveco Astra 8848	20/10/2020	Make parts list for live drive/clutch
WCA012 : Iveco Astra 8848	20/10/2020	oil cooler hoses
WCA012 : Iveco Astra 8848	22/10/2020	Order tyres
wca012 : Iveco Astra 8848	23/10/2020	Scrap
wca012 : Iveco Astra 8848	23/10/2020	Strip & Fit Runout Tyre
WCA012 : Iveco Astra 8848	27/10/2020	Bonnet catch per quote 256113
WCA012 : Iveco Astra 8848	27/10/2020	clutch parts per quote 256110
WCA012 : Iveco Astra 8848	27/10/2020	Parts
WCA012 : Iveco Astra 8848	27/10/2020	PTO parts per quote 256106
WCA012 : Iveco Astra 8848	29/10/2020	Adjust rear susp trunnions
WCA012 : Iveco Astra 8848	29/10/2020	Parts list
WCA012 : Iveco Astra 8848	4/11/2020	Parts
WCA012 : Iveco Astra 8848	5/11/2020	Parts
WCA012 : Iveco Astra 8848	9/11/2020	5M-6509 Orings
WCA012 : Iveco Astra 8848	9/11/2020	Parts
WCA012 : Iveco Astra 8848	9/11/2020	Start assembling live drive
WCA012 : Iveco Astra 8848	10/11/2020	Finish assembling live drive, install, make clutch
WCA012 : Iveco Astra 8848	11/11/2020	clutch parts per quote 256110
WCA012 : Iveco Astra 8848	11/11/2020	Prep
WCA012 : Iveco Astra 8848	13/11/2020	Fit new oil pump to sump of live drive/fit sump
WCA012 : Iveco Astra 8848	13/11/2020	Prep chassis plates
WCA012 : Iveco Astra 8848	13/11/2020	Repair chassis of tray
WCA012 : Iveco Astra 8848	16/11/2020	Parts
WCA012 : Iveco Astra 8848	16/11/2020	Parts for PTO re quote 257564
WCA012 : Iveco Astra 8848	16/11/2020	strip and quote ZF gearbox
WCA012 : Iveco Astra 8848	17/11/2020	Set up tray for repairs
WCA012 : Iveco Astra 8848	17/11/2020	Tray repairs
WCA012 : Iveco Astra 8848	18/11/2020	Assist with trans fitment/prep for fitment
WCA012 : Iveco Astra 8848	18/11/2020	Deck frame repairs
WCA012 : Iveco Astra 8848	18/11/2020	Fit gear box
WCA012 : Iveco Astra 8848	18/11/2020	Help Nathan fit gearbpx/fit tailshaft
WCA012 : Iveco Astra 8848	18/11/2020	P/U parts
WCA012 : Iveco Astra 8848	18/11/2020	Refit gear box
WCA012 : Iveco Astra 8848	18/11/2020	Tray repair
WCA012 : Iveco Astra 8848	22/11/2020	Freight
WCA012 : Iveco Astra 8848	23/11/2020	Fit & tensioned driveshaft botls/fit hoses.pipes/l
WCA012 : Iveco Astra 8848	23/11/2020	Refit gear box/reassemble PTO drive with new bear
WCA012 : Iveco Astra 8848	24/11/2020	20L G/box oil. ZF Eco fluid M

WCA012 : Iveco Astra 8848	24/11/2020	Complete install clutch top up power steering
WCA012 : Iveco Astra 8848	24/11/2020	Parts
WCA012 : Iveco Astra 8848	24/11/2020	PTO repairs/removed damaged ring feeder
WCA012 : Iveco Astra 8848	25/11/2020	50mm Ringfeder
WCA012 : Iveco Astra 8848	25/11/2020	Move water tank
WCA012 : Iveco Astra 8848	25/11/2020	P/U parts
WCA012 : Iveco Astra 8848	25/11/2020	Removed balls from tank/use franna to move & flip
WCA012 : Iveco Astra 8848	25/11/2020	Repair of tray chassis
WCA012 : Iveco Astra 8848	25/11/2020	Sort through tank balls disassemble tank balls
WCA012 : Iveco Astra 8848	26/11/2020	Fan Belt, Stop/Start Buttons
WCA012 : Iveco Astra 8848	26/11/2020	Fit new ring feeder, fit gear box with oil/clean
WCA012 : Iveco Astra 8848	26/11/2020	LED Beacons
WCA012 : Iveco Astra 8848	26/11/2020	P/U parts
WCA012 : Iveco Astra 8848	26/11/2020	Parts
WCA012 : Iveco Astra 8848	26/11/2020	PTO Shaft Seal
WCA012 : Iveco Astra 8848	26/11/2020	Repair cracks in under side of tray
WCA012 : Iveco Astra 8848	27/11/2020	Repair cracks in tray & watertank subframe
WCA012 : Iveco Astra 8848	28/11/2020	Fit new fan belts, refit eng fan/cooler pack
WCA012 : Iveco Astra 8848	28/11/2020	Fit seal to PTO & assembled PTO, clean surfaces
WCA012 : Iveco Astra 8848	28/11/2020	Repair cracks in subframe, repair cracks in hyd ta
WCA012 : Iveco Astra 8848	30/11/2020	Assist with PTO drive coupling, replacment & tray
WCA012 : Iveco Astra 8848	30/11/2020	Check over repairs, removed & replaced worn pump
WCA012 : Iveco Astra 8848	30/11/2020	Fab tank access ladder, test ladder
WCA012 : Iveco Astra 8848	30/11/2020	Move truck to under crane, fit tray
WCA012 : Iveco Astra 8848	30/11/2020	P/U parts
WCA012 : Iveco Astra 8848	30/11/2020	Parts
WCA012 : Iveco Astra 8848	30/11/2020	Prep & parts
WCA012 : Iveco Astra 8848	1/12/2020	4x Container Locks
WCA012 : Iveco Astra 8848	1/12/2020	Assist with tray fitment, plumbing, order parts
WCA012 : Iveco Astra 8848	1/12/2020	Finished off mounting tray, repaired/reconnected
WCA012 : Iveco Astra 8848	1/12/2020	Fit all bolts for tray mounting, tightened, elec r
WCA012 : Iveco Astra 8848	1/12/2020	Help do up up tray mounts & weld moutning plates
WCA012 : Iveco Astra 8848	1/12/2020	P/U Parts
WCA012 : Iveco Astra 8848	1/12/2020	Prep
WCA012 : Iveco Astra 8848	1/12/2020	Risk assessment, rescue plan, JSEA
WCA012 : Iveco Astra 8848	2/12/2020	Complete Airbox
WCA012 : Iveco Astra 8848	2/12/2020	Diagnose faulty beacon wiring, remove & rewire
WCA012 : Iveco Astra 8848	2/12/2020	Fab light brackets
WCA012 : Iveco Astra 8848	2/12/2020	Fit container locks, clean out holes
WCA012 : Iveco Astra 8848	2/12/2020	LED Beacons
WCA012 : Iveco Astra 8848	2/12/2020	P/U parts
WCA012 : Iveco Astra 8848	3/12/2020	Confined space, safety watcher, assist with s/up
WCA012 : Iveco Astra 8848	3/12/2020	Finish off moutning & rewire becon lights
WCA012 : Iveco Astra 8848	3/12/2020	Refit tank subframe to truck, fit supports
WCA012 : Iveco Astra 8848	3/12/2020	Set up for confined space work, undo all tank work
WCA012 : Iveco Astra 8848	3/12/2020	Start isntalling hose clamp brackets, move tanks
WCA012 : Iveco Astra 8848	3/12/2020	Tanks
WCA012 : Iveco Astra 8848	3/12/2020	V-Band Exhaust Clamp
WCA012 : Iveco Astra 8848	4/12/2020	Assist with repairs
WCA012 : Iveco Astra 8848	4/12/2020	Complete removing all glands & fittings/sort parts
WCA012 : Iveco Astra 8848	4/12/2020	Confined space, safety watcher

WCA012 : Iveco Astra 8848	4/12/2020	Make sandwich plate for hyd tank/cut out holes
wca012 : Iveco Astra 8848	4/12/2020	Parts
wca012 : Iveco Astra 8848	4/12/2020	Parts
WCA012 : Iveco Astra 8848	4/12/2020	Prep
WCA012 : Iveco Astra 8848	4/12/2020	Repair intake pipes, routed new hyd hoses & mount i
WCA012 : Iveco Astra 8848	4/12/2020	Tank fittings
WCA012 : Iveco Astra 8848	4/12/2020	Undo all tank fittings to be resealed fab spanner
WCA012 : Iveco Astra 8848	5/12/2020	Adjusted hoses, tightened stauff clamp
WCA012 : Iveco Astra 8848	5/12/2020	Mounted hyd hoses, stripped hyd tank & clean
WCA012 : Iveco Astra 8848	5/12/2020	Order hyd filter
WCA012 : Iveco Astra 8848	7/12/2020	Cont installing water pipes to rear of truck etc
WCA012 : Iveco Astra 8848	7/12/2020	Fab tools to reseal tanks
WCA012 : Iveco Astra 8848	7/12/2020	Hydraulic Filter
WCA012 : Iveco Astra 8848	7/12/2020	Order filter/parts
WCA012 : Iveco Astra 8848	7/12/2020	Parts
WCA012 : Iveco Astra 8848	7/12/2020	Parts
WCA012 : Iveco Astra 8848	7/12/2020	Reassembled hyd tank, reconnect & mounted hyd hose
WCA012 : Iveco Astra 8848	7/12/2020	Replace marker plates/assist refit hyd tank & rcon
WCA012 : Iveco Astra 8848	8/12/2020	Cleaned & repaired fittings before install
WCA012 : Iveco Astra 8848	8/12/2020	Fab tools
WCA012 : Iveco Astra 8848	8/12/2020	Fab tools to reseal tank fittings
WCA012 : Iveco Astra 8848	8/12/2020	Fit flanges & barb fittings to inside of tanks
WCA012 : Iveco Astra 8848	8/12/2020	Refitted mudguards/removed & replaced damaged
WCA012 : Iveco Astra 8848	8/12/2020	Repairs to water tanks
WCA012 : Iveco Astra 8848	9/12/2020	Assist remove hyd oil tank for repair & refit to p
WCA012 : Iveco Astra 8848	9/12/2020	Prep & parts
WCA012 : Iveco Astra 8848	9/12/2020	Refit toolbox, clean parts ready to reassembly
WCA012 : Iveco Astra 8848	9/12/2020	Remove & disassemble water pump, remove piping
WCA012 : Iveco Astra 8848	9/12/2020	Repair cracked hyd tank
WCA012 : Iveco Astra 8848	9/12/2020	Repairs to water tanks
WCA012 : Iveco Astra 8848	9/12/2020	Replace Hydraulic Hoses
WCA012 : Iveco Astra 8848	10/12/2020	D/O gas detector
WCA012 : Iveco Astra 8848	10/12/2020	Finished off refitting hyd tank & fitted, diagnose
WCA012 : Iveco Astra 8848	10/12/2020	Mount quick-fill bracket, cut gaskets for pumpage
WCA012 : Iveco Astra 8848	10/12/2020	Plumbing Fittings For Dribble Bar & Sprays
WCA012 : Iveco Astra 8848	10/12/2020	Repairs to water tanks
WCA012 : Iveco Astra 8848	10/12/2020	Weld plumbing/pipe work order more
WCA012 : Iveco Astra 8848	11/12/2020	Assist refit pray pipes to plant/straighten no. pl
WCA012 : Iveco Astra 8848	11/12/2020	Diagnosed & repaired air leaks, removed air tanks
WCA012 : Iveco Astra 8848	11/12/2020	plumbing fittings
WCA012 : Iveco Astra 8848	11/12/2020	plumbing fittings
WCA012 : Iveco Astra 8848	11/12/2020	order parts, assist with repairs
WCA012 : Iveco Astra 8848	11/12/2020	Repairs to water tanks
WCA012 : Iveco Astra 8848	11/12/2020	Weld repairs
WCA012 : Iveco Astra 8848	12/12/2020	Finish off water tank plumbing, fit new spray head
WCA012 : Iveco Astra 8848	12/12/2020	Repairs to water tanks
WCA012 : Iveco Astra 8848	14/12/2020	Assist removing front water tank/resealing/modify
WCA012 : Iveco Astra 8848	14/12/2020	Remove water tank to modify tray crossmember
WCA012 : Iveco Astra 8848	14/12/2020	Removed faulty butterfly valves, remove front tank
WCA012 : Iveco Astra 8848	15/12/2020	3" & 4" Butterfly Valves
WCA012 : Iveco Astra 8848	15/12/2020	Calibrate Clutch, Diagnose Engine Light On

WCA012 : Iveco Astra 8848	15/12/2020	Diagnose internal air leak in transfer case
WCA012 : Iveco Astra 8848	15/12/2020	Electro Fusion Fittings
WCA012 : Iveco Astra 8848	15/12/2020	Gear box crunshing when shifting, air leaks
WCA012 : Iveco Astra 8848	15/12/2020	Guards
WCA012 : Iveco Astra 8848	15/12/2020	Parts
WCA012 : Iveco Astra 8848	15/12/2020	Parts & prep
WCA012 : Iveco Astra 8848	15/12/2020	Repairs to water tanks
WCA012 : Iveco Astra 8848	16/12/2020	Assist with repairs & re-assembly of WCA
WCA012 : Iveco Astra 8848	16/12/2020	D/O parts
WCA012 : Iveco Astra 8848	16/12/2020	Guards/mount hose reel
WCA012 : Iveco Astra 8848	16/12/2020	Hose Nozzle
WCA012 : Iveco Astra 8848	16/12/2020	Refit dribble bar & butterfly valve, fit hose reel
WCA012 : Iveco Astra 8848	17/12/2020	Grundfos Water Pump P/N 96771353
WCA012 : Iveco Astra 8848	17/12/2020	hose reel
WCA012 : Iveco Astra 8848	17/12/2020	Remove batler sprays & plumbing, replace pump
WCA012 : Iveco Astra 8848	17/12/2020	Transfer Case High/Low Piston O-rings
WCA012 : Iveco Astra 8848	17/12/2020	Water pump replacment, modified new water pumps
WCA012 : Iveco Astra 8848	18/12/2020	Cont re-assembly, test drive
WCA012 : Iveco Astra 8848	18/12/2020	Parts
WCA012 : Iveco Astra 8848	18/12/2020	Replace high & low selector piston seals & check
WCA012 : Iveco Astra 8848	19/12/2020	Cont refitting external components/plumbing
WCA012 : Iveco Astra 8848	19/12/2020	Function tested new water pump & hose reel, refit
WCA012 : Iveco Astra 8848	21/12/2020	1" Hose For Hose Reel + Fittings
WCA012 : Iveco Astra 8848	21/12/2020	90mm to 2" BSP Branch Tee
WCA012 : Iveco Astra 8848	21/12/2020	Courier duties
WCA012 : Iveco Astra 8848	21/12/2020	Finish assembly of truck, fit cannon that arrived
WCA012 : Iveco Astra 8848	21/12/2020	Removed & replaced faulty branch
WCA012 : Iveco Astra 8848	22/12/2020	daignose and rectify harsh shifting at Darlington
WCA012 : Iveco Astra 8848	22/12/2020	Exit inspection, put all parts away, clean work ar
WCA012 : Iveco Astra 8848	23/12/2020	Wash down tray
WCA012 : Iveco Astra 8848	29/12/2020	Water tank repairs
WCA012 : Iveco Astra 8848	30/12/2020	Make up liquid hocker balls, fill water tank
WCA012 : Iveco Astra 8848	30/12/2020	Watertank repairs
WCA012 : Iveco Astra 8848	31/12/2020	Make up balls liquid hocker repairs to watertank
WCA012 : Iveco Astra 8848	31/12/2020	Repairs to watertanks
WCA012 : Iveco Astra 8848	4/01/2021	Load new programming files in cannon, test
WCA012 : Iveco Astra 8848	4/01/2021	Prep
WCA012 : Iveco Astra 8848	4/01/2021	Repaired lights & park up top, clean area, new par
WCA012 : Iveco Astra 8848	8/01/2021	Check dropbox for leak
WCA012 : Iveco Astra 8848	11/01/2021	Repair water pump drive coupling
WCA012 : Iveco Astra 8848	12/01/2021	Remove broken pump coupling
WCA012 : Iveco Astra 8848	13/01/2021	Fit drive coupling on coater pump
WCA012 : Iveco Astra 8848	14/01/2021	Water pump coupling
WCA012 : Iveco Astra 8848	15/01/2021	Inspect coupling or water pump, flip spray head to
WCA012 : Iveco Astra 8848	15/01/2021	Look at pump alig,ent
WCA012 : Iveco Astra 8848	16/01/2021	Parts
WCA012 : Iveco Astra 8848	16/01/2021	Try fit new coupling water pump
WCA012 : Iveco Astra 8848	18/01/2021	Start fitting coupling
WCA012 : Iveco Astra 8848	26/01/2021	PTO fault
WCA012 : Iveco Astra 8848	26/01/2021	Repairs and mods to pump
WCA012 : Iveco Astra 8848	27/01/2021	Look into PTO fault, clear codes and repair fault

WCA012 : Iveco Astra 8848	27/01/2021	PARTS RUN- PICK UP WCA012
WCA012 : Iveco Astra 8848	27/01/2021	PICK UP VEHICLE FROM LACEY ST
WCA012 : Iveco Astra 8848	28/01/2021	REAR WATER PUMP COUPLING FAULT
WCA012 : Iveco Astra 8848	28/01/2021	RECTIFY PTO COUPLING FAULT
WCA012 : Iveco Astra 8848	29/01/2021	'DRIVE ISSUES'
WCA012 : Iveco Astra 8848	29/01/2021	MOVE, ADJUST CENTRE SPRAY & TEST
WCA012 : Iveco Astra 8848	2/02/2021	Tyres
WCA012 : Iveco Astra 8848	5/02/2021	Defect list, file DOIS ect
WCA012 : Iveco Astra 8848	7/02/2021	LH SPRAY LEAKING
WCA012 : Iveco Astra 8848	8/02/2021	SOURCE FITTINGS TO BLOCK OFF SPRAY
WCA012 : Iveco Astra 8848	15/02/2021	CHANGE OUT POS 7 TYRE, PICK UP / DROP OFF IN PORTA
WCA012 : Iveco Astra 8848	16/02/2021	Tyres
WCA012 : Iveco Astra 8848	19/02/2021	Parts
wca012 : Iveco Astra 8848	21/02/2021	Freight APCOC0000356
WCA012 : Iveco Astra 8848	24/02/2021	CHANGE P2 TYRE
WCA012 : Iveco Astra 8848	25/02/2021	REPLACE P8 OUTER TYRE
WCA012 : Iveco Astra 8848	25/02/2021	REPLACE TYRE
WCA012 : Iveco Astra 8848	26/02/2021	Transfer Case High/Low Piston O-rings
WCA012 : Iveco Astra 8848	26/02/2021	Tyres
WCA012 : Iveco Astra 8848	26/02/2021	Tyres
WCA012 : Iveco Astra 8848	3/03/2021	REMOVE & REFIT FLAT TYRE
WCA012 : Iveco Astra 8848	3/03/2021	REPLACE TYRE
WCA012 : Iveco Astra 8848	7/03/2021	REMOUNT CANNON SUPPORT
WCA012 : Iveco Astra 8848	8/03/2021	CHANGE OUT POS 7 TYRE, RADIO FAULT
WCA012 : Iveco Astra 8848	12/03/2021	800HR SERVICE, PATCH UP HYD TANK CRACK
WCA012 : Iveco Astra 8848	12/03/2021	START 800HR SERVICE
WCA012 : Iveco Astra 8848	13/03/2021	FINISH SERVICE, REPLACE PTO MOTOR COUPLING ASSY
WCA012 : Iveco Astra 8848	13/03/2021	HYD COUPLING ON PUMP
WCA012 : Iveco Astra 8848	13/03/2021	Parts
WCA012 : Iveco Astra 8848	14/03/2021	ORDER PARTS
WCA012 : Iveco Astra 8848	16/03/2021	AIR LEAK
WCA012 : Iveco Astra 8848	17/03/2021	Service
WCA012 : Iveco Astra 8848	19/03/2021	DOIS DEFECT LIST
WCA012 : Iveco Astra 8848	19/03/2021	REPLACE P8 OUTER TYRE
WCA012 : Iveco Astra 8848	25/03/2021	REPAIR AIR LEAK
WCA012 : Iveco Astra 8848	26/03/2021	Subcontractor - Plant Maintenance
WCA012 : Iveco Astra 8848	27/03/2021	CHECK OIL LEAKS
WCA012 : Iveco Astra 8848	30/03/2021	Subcontractor - Plant Maintenance
WCA012 : Iveco Astra 8848	20/04/2021	DIAGNOSE AIR LEAK & REMOVE HOSE
WCA012 : Iveco Astra 8848	20/04/2021	PLANT ACTIONS
WCA012 : Iveco Astra 8848	22/04/2021	REPLACE P4 TYRE
WCA012 : Iveco Astra 8848	23/04/2021	Parts
WCA012 : Iveco Astra 8848	23/04/2021	Parts for cab mount
WCA012 : Iveco Astra 8848	23/04/2021	REPAIR HYD TANK, UHF AERIAL, REPLACE LH REAR CAB S
WCA012 : Iveco Astra 8848	23/04/2021	REPLACE LHR CAB STRUT
WCA012 : Iveco Astra 8848	24/04/2021	RECTIFY UHF RECEPTION FAULT
WCA012 : Iveco Astra 8848	24/04/2021	TOP UP HYD OIL, RUN UP & TEST
WCA012 : Iveco Astra 8848	26/04/2021	UHF FAULT, CHECK LEAK
WCA012 : Iveco Astra 8848	14/05/2021	ORGANISE NEW FITTINGS FOR FILL PIPE
WCA012 : Iveco Astra 8848	14/05/2021	SORT OUT WATER HOSE, PIPE FITTING
WCA012 : Iveco Astra 8848	17/05/2021	Assist with faults

WCA012 : Iveco Astra 8848	17/05/2021	Replace PTO pump switch and test
WCA012 : Iveco Astra 8848	19/05/2021	PLANT ACTIONS DOIS
WCA012 : Iveco Astra 8848	2/06/2021	CHASE UP CAB SHOCKER
WCA012 : Iveco Astra 8848	4/06/2021	Parts
WCA012 : Iveco Astra 8848	8/06/2021	REPLACE RH CAB SHOCK ABSORBER, REPLACE LH HEADLAMP
WCA012 : Iveco Astra 8848	28/06/2021	CHECKED PLANT ACTIONS
WCA012 : Iveco Astra 8848	28/06/2021	ENTRY INSPECTION / UPDATE DEFECT LIST
WCA012 : Iveco Astra 8848	8/07/2021	DOIS/PLANT DEFECTS
WCA012 : Iveco Astra 8848	17/08/2021	FILL & REPAIR ADD BLUE TANK
WCA012 : Iveco Astra 8848	18/08/2021	ADD BLUE SYSTEM & DEFECTS
WCA012 : Iveco Astra 8848	18/08/2021	REPAIR DEFECTS
WCA012 : Iveco Astra 8848	18/08/2021	WCA REPAIRS, ELECTRICAL
WCA012 : Iveco Astra 8848	30/08/2021	CANNON REPAIRS
WCA012 : Iveco Astra 8848	30/08/2021	PARTS ORDER FOR WATER CANNON
WCA012 : Iveco Astra 8848	2/09/2021	LOOK AT ACNNON FAULT
WCA012 : Iveco Astra 8848	7/09/2021	INSPECTIONS & REPAIUR LIST
WCA012 : Iveco Astra 8848	8/09/2021	REFIT REAR BUMPER
WCA012 : Iveco Astra 8848	8/09/2021	REPAIR REAR FRAME
WCA012 : Iveco Astra 8848	8/09/2021	WELD ON REAR BUMPER
WCA012 : Iveco Astra 8848	9/09/2021	INSPECT & REPAIR TAIL GATE
WCA012 : Iveco Astra 8848	13/09/2021	PARTS ORDER
WCA012 : Iveco Astra 8848	14/09/2021	SORT REPLACEMENT PUM
WCA012 : Iveco Astra 8848	17/09/2021	FOLLOW UP NEW PUM ETA
WCA012 : Iveco Astra 8848	18/09/2021	TEMP REPAIR & DRIBBLE BAR
WCA012 : Iveco Astra 8848	21/09/2021	FOLLOW UP PARTS
WCA012 : Iveco Astra 8848	23/09/2021	PICK & SORT NEW WATER PUMP
WCA012 : Iveco Astra 8848	23/09/2021	PREP SERVICE PAPERWORK & FILTERS
WCA012 : Iveco Astra 8848	23/09/2021	PU PERFORMANCE
wca012 : Iveco Astra 8848	23/09/2021	replacement pumps
WCA012 : Iveco Astra 8848	24/09/2021	FAULT FIND, NO DRIVE
WCA012 : Iveco Astra 8848	24/09/2021	MOD PUM TO FIT
WCA012 : Iveco Astra 8848	24/09/2021	REMOVED & FITTED NEW WATER PUMP
WCA012 : Iveco Astra 8848	25/09/2021	C/O DRIVE SHAFT, REPAIR HYD LEAKS
WCA012 : Iveco Astra 8848	25/09/2021	FAULT FIND, REMOVE DRIVE SHAFT, CLEAN PARTS
WCA012 : Iveco Astra 8848	27/09/2021	1600hr service filters
WCA012 : Iveco Astra 8848	27/09/2021	1600Hr service filters
WCA012 : Iveco Astra 8848	27/09/2021	DO HARDY SPICER
WCA012 : Iveco Astra 8848	27/09/2021	PARTS
WCA012 : Iveco Astra 8848	28/09/2021	1600hr service filters
WCA012 : Iveco Astra 8848	5/10/2021	DIAGNOSE pto FAULT
WCA012 : Iveco Astra 8848	6/10/2021	QUOTE & ORER PARTS
WCA012 : Iveco Astra 8848	6/10/2021	REBUILD PTO
WCA012 : Iveco Astra 8848	7/10/2021	PU HARDY SPICER
wca012 : Iveco Astra 8848	7/10/2021	tail shaft repairs
WCA012 : Iveco Astra 8848	8/10/2021	PTO Repair Parts
WCA012 : Iveco Astra 8848	11/10/2021	INSPECT OIL PRESSURE FAULT
WCA012 : Iveco Astra 8848	11/10/2021	INSPECT OIL PRESSURE FAULT
WCA012 : Iveco Astra 8848	13/10/2021	PLANT ACTIONS / DOIS SHEETS
WCA012 : Iveco Astra 8848	19/10/2021	REBUILD PTO
WCA012 : Iveco Astra 8848	19/10/2021	REFURB
WCA012 : Iveco Astra 8848	20/10/2021	pto build

wca012 : Iveco Astra 8848	5/11/2021	call out to Linwood for hose repairs
WCA012 : Iveco Astra 8848	6/11/2021	CONTINUE HOSE REPAIR
WCA012 : Iveco Astra 8848	8/11/2021	CLEAN & REFILL ADD BLUE SYSTEM
WCA012 : Iveco Astra 8848	9/11/2021	JUMP START & FIX BATTERY
WCA012 : Iveco Astra 8848	10/11/2021	WINDOW FAULT
WCA012 : Iveco Astra 8848	10/11/2021	WINDOW REGULATOR FAULT
WCA012 : Iveco Astra 8848	11/11/2021	WINDOW FAULT
WCA012 : Iveco Astra 8848	15/11/2021	AIR LEAKS, U/S DRAIN PLUGS
WCA012 : Iveco Astra 8848	16/11/2021	GENERAL INSPECTION
WCA012 : Iveco Astra 8848	17/11/2021	HYD DRIVE MOTOR
WCA012 : Iveco Astra 8848	29/11/2021	FAB, WELD & HYD TANK
WCA012 : Iveco Astra 8848	29/11/2021	Pressed sections
WCA012 : Iveco Astra 8848	30/11/2021	FAB / WE'D HYD TANK
WCA012 : Iveco Astra 8848	30/11/2021	HYD TANKS
WCA012 : Iveco Astra 8848	1/12/2021	FAB/WELD/HYD TANKS
WCA012 : Iveco Astra 8848	2/12/2021	FAB/WELD ALU HYD TANKS
WCA012 : Iveco Astra 8848	2/12/2021	HYD TANKS
WCA012 : Iveco Astra 8848	3/12/2021	FAB HYD TAN
wca012 : Iveco Astra 8848	3/12/2021	Sockets
WCA012 : Iveco Astra 8848	3/12/2021	WCA TANKS
WCA012 : Iveco Astra 8848	4/12/2021	FAB BRACKS FOR HYD TANKS
WCA012 : Iveco Astra 8848	6/12/2021	FAB SUPPORT FEET
WCA012 : Iveco Astra 8848	7/12/2021	FIT & WELD SUPPORT FEET
WCA012 : Iveco Astra 8848	8/12/2021	FAB HOLD POINT BRACKETS
WCA012 : Iveco Astra 8848	8/12/2021	HYD TANKS
WCA012 : Iveco Astra 8848	9/12/2021	Cushions
WCA012 : Iveco Astra 8848	9/12/2021	Freight
WCA012 : Iveco Astra 8848	9/12/2021	HYD TANKS
WCA012 : Iveco Astra 8848	9/12/2021	WELD SUPPORT BRACKETS, TRIM MOUNTING
WCA012 : Iveco Astra 8848	10/12/2021	REMOVE MOUNTS, FIT TANKS,
WCA012 : Iveco Astra 8848	15/12/2021	ENTRY INSPECTION, PRESSURE WASH
WCA012 : Iveco Astra 8848	15/12/2021	ENTRY INSPECTION, WASH MACHINE
WCA012 : Iveco Astra 8848	15/12/2021	WEIGH & CALCULATE GVM
WCA012 : Iveco Astra 8848	16/12/2021	ASSIST ASSESSING TRUCK DAMAGE
WCA012 : Iveco Astra 8848	16/12/2021	DRAIN TANKS, WASH, MOVE TO W/SHOP
WCA012 : Iveco Astra 8848	16/12/2021	PRESSURE WASH MACHINE
WCA012 : Iveco Astra 8848	17/12/2021	ANNUAL SERVICE
WCA012 : Iveco Astra 8848	17/12/2021	ANNUAL SERVICE & REPAIRS
WCA012 : Iveco Astra 8848	17/12/2021	INSPECT TRUCK & START PARTS LIST
WCA012 : Iveco Astra 8848	17/12/2021	PROCESS OIL SAMPLE
WCA012 : Iveco Astra 8848	20/12/2021	ANNUAL SERVICE
WCA012 : Iveco Astra 8848	20/12/2021	ANNUAL SERVICE & REPAIRS
WCA012 : Iveco Astra 8848	20/12/2021	ASSIST W/ REPAIRS
WCA012 : Iveco Astra 8848	21/12/2021	ANNUAL SERVICE
WCA012 : Iveco Astra 8848	21/12/2021	ANNUAL SERVICE
WCA012 : Iveco Astra 8848	21/12/2021	ASSIST/W REPAIRS
WCA012 : Iveco Astra 8848	21/12/2021	O Rings power steer tank
WCA012 : Iveco Astra 8848	22/12/2021	ANNUAL SERVICE
WCA012 : Iveco Astra 8848	22/12/2021	ANNUAL SERVICE
WCA012 : Iveco Astra 8848	4/01/2022	ANNUAL SERVICE
WCA012 : Iveco Astra 8848	4/01/2022	ANNUAL SERVICE & REPAIRS

WCA012 : Iveco Astra 8848	5/01/2022 ANNUAL SERVICE & REPAIRS
WCA012 : Iveco Astra 8848	5/01/2022 ANNUAL SERVICE & REPAIRS TO DRIB BOX
WCA012 : Iveco Astra 8848	5/01/2022 MAXILAMPC5XRW LED Taillight
WCA012 : Iveco Astra 8848	6/01/2022 Ad Blue Filter
WCA012 : Iveco Astra 8848	6/01/2022 ANNUAL SERVICE & REPAIRS
WCA012 : Iveco Astra 8848	6/01/2022 ORDER ADDBLUE FILTERS
WCA012 : Iveco Astra 8848	25/01/2022 HYD TANK
WCA012 : Iveco Astra 8848	1/02/2022 HYD TANK SUPPORT FRAME
WCA012 : Iveco Astra 8848	1/02/2022 Parts per Quote 302906
WCA012 : Iveco Astra 8848	3/02/2022 HYD TANKS
WCA012 : Iveco Astra 8848	5/02/2022 PLACE TANK ON FRAME
WCA012 : Iveco Astra 8848	7/02/2022 FAB ASSOCIATED MOUNTING
WCA012 : Iveco Astra 8848	15/02/2022 ASSIST W/ REPAIRS
WCA012 : Iveco Astra 8848	22/02/2022 ASSIST W/ REPAIRS
WCA012 : Iveco Astra 8848	9/03/2022 Parts
WCA012 : Iveco Astra 8848	10/03/2022 ASSIST W/ SERVICE & REPAIRS
WCA012 : Iveco Astra 8848	10/03/2022 MOVE TO W/SHOP, SET PARTS UP
WCA012 : Iveco Astra 8848	11/03/2022 ASSIST W/ REPAIRS
WCA012 : Iveco Astra 8848	11/03/2022 REMOVE TANK, MOVE TRACKS
WCA012 : Iveco Astra 8848	11/03/2022 REMOVE WATER TANK
WCA012 : Iveco Astra 8848	15/03/2022 ASSIST W/ REPAIRS
WCA012 : Iveco Astra 8848	15/03/2022 CLEAN INTERCOOLER PIPES
WCA012 : Iveco Astra 8848	16/03/2022 ASSIST W/ REPAIRS
WCA012 : Iveco Astra 8848	16/03/2022 REMOVAL OF COMPRESSOR
WCA012 : Iveco Astra 8848	17/03/2022 ASSIST W/ REPAIRS
WCA012 : Iveco Astra 8848	17/03/2022 C/O ROCK GASKET, CAB LOCKS, FIT STEER PUM
WCA012 : Iveco Astra 8848	18/03/2022 ASSIST WITH REPAIRS, CHASE UP PARTS
WCA012 : Iveco Astra 8848	18/03/2022 COURIER
WCA012 : Iveco Astra 8848	18/03/2022 REBUILD OF TURBO SETUP
WCA012 : Iveco Astra 8848	18/03/2022 Replace Power Steering Hoses
WCA012 : Iveco Astra 8848	19/03/2022 ASSIST WITH REPAIRS
WCA012 : Iveco Astra 8848	19/03/2022 TURBO ASSY, REMOVAL OF WHEELS, FIT INTAKE ASSY
WCA012 : Iveco Astra 8848	21/03/2022 Assist with repairs
WCA012 : Iveco Astra 8848	21/03/2022 HYD TANK SUPPORT PRIME
WCA012 : Iveco Astra 8848	21/03/2022 Turbo, Gaskets, Nuts
WCA012 : Iveco Astra 8848	22/03/2022 ASSIST WITH REPAIRS
WCA012 : Iveco Astra 8848	22/03/2022 FAB FITTING, TRY REMOVAL OF U BOLTS
WCA012 : Iveco Astra 8848	22/03/2022 P/U NE ISUZU
WCA012 : Iveco Astra 8848	22/03/2022 P/U TRUCKLINE
WCA012 : Iveco Astra 8848	22/03/2022 P/U TRUCKLINE
WCA012 : Iveco Astra 8848	23/03/2022 ASSIST W/ REPAIRS
WCA012 : Iveco Astra 8848	23/03/2022 FIT TURBOS & OIL REQ
WCA012 : Iveco Astra 8848	24/03/2022 ASSIST W/ REPAIRS
WCA012 : Iveco Astra 8848	25/03/2022 HYD OIL TANK SUPPORT
WCA012 : Iveco Astra 8848	25/03/2022 Mudguards, Rear U-Bolts, Nuts & Washers
WCA012 : Iveco Astra 8848	25/03/2022 PU PARTS, NE ISUZU
WCA012 : Iveco Astra 8848	25/03/2022 PU U BOLTS
WCA012 : Iveco Astra 8848	28/03/2022 CLEAN & PRIME PAINT TANK
WCA012 : Iveco Astra 8848	28/03/2022 PU NE ISUZU
WCA012 : Iveco Astra 8848	29/03/2022 Barb Fitting
WCA012 : Iveco Astra 8848	29/03/2022 CHASE UP PARTS

WCA012 : Iveco Astra 8848	29/03/2022	P/U NE ISUZU
WCA012 : Iveco Astra 8848	31/03/2022	REPAIRS
WCA012 : Iveco Astra 8848	1/04/2022	ADD DEFECTS FROM DOIDS
WCA012 : Iveco Astra 8848	1/04/2022	ASSIST W/ REPAIRS
WCA012 : Iveco Astra 8848	1/04/2022	M20 x 90mm zinc plated 10.9
WCA012 : Iveco Astra 8848	1/04/2022	PU BAXTERS
WCA012 : Iveco Astra 8848	1/04/2022	raise po
WCA012 : Iveco Astra 8848	1/04/2022	REMOVE U BOLTS
WCA012 : Iveco Astra 8848	4/04/2022	ASSIST WITH REPAIRS, CHASE UP PARTS
WCA012 : Iveco Astra 8848	4/04/2022	DRIN REAR LUBE/REMOVE REAR LEAF
WCA012 : Iveco Astra 8848	4/04/2022	REMOVE REAR LEAF SPRING DOG BONES
WCA012 : Iveco Astra 8848	4/04/2022	REPAIRS
WCA012 : Iveco Astra 8848	5/04/2022	ASSIST WITH REPAIRS
WCA012 : Iveco Astra 8848	5/04/2022	DISASSEMBLE REAR END, PRESS OUT TRUNNION SUPPORT P
WCA012 : Iveco Astra 8848	5/04/2022	Rear Trunnion Housings, Dowels
WCA012 : Iveco Astra 8848	5/04/2022	REMOVE TRUNNION SUPPORT, PRESS PINS OUT OF TRUNNIO
WCA012 : Iveco Astra 8848	5/04/2022	REPAIRS
WCA012 : Iveco Astra 8848	6/04/2022	ASSIST W/ REPAIRS, CHASE UP PARTS
WCA012 : Iveco Astra 8848	6/04/2022	DISASSY HUBS, CLEAN PARTS
WCA012 : Iveco Astra 8848	6/04/2022	DISASSY, CLEAN & INSPECT BRAKES
WCA012 : Iveco Astra 8848	6/04/2022	REPAIRS & ANNUAL SERVICE
WCA012 : Iveco Astra 8848	7/04/2022	ANNUAL & REPAIRS
WCA012 : Iveco Astra 8848	7/04/2022	BRAKES & SUSPENSION, CLEAN UP
WCA012 : Iveco Astra 8848	7/04/2022	CHASE UP PARTS FOR POSSIBLE AFTER MARKET ALTERNATI
WCA012 : Iveco Astra 8848	7/04/2022	CLEAN PARTS
WCA012 : Iveco Astra 8848	8/04/2022	DISASSY & CLEAN INSPECT BRAKES
WCA012 : Iveco Astra 8848	11/04/2022	Plumb Up New Hyd Tank
WCA012 : Iveco Astra 8848	12/04/2022	CRACK REPAIRS
WCA012 : Iveco Astra 8848	12/04/2022	INSPECT CHASSIS CRACKS
WCA012 : Iveco Astra 8848	13/04/2022	Mudguards, Rear U-Bolts, Nuts & Washers
WCA012 : Iveco Astra 8848	13/04/2022	Parts
WCA012 : Iveco Astra 8848	13/04/2022	REMOVE REAR TRACK RODS
WCA012 : Iveco Astra 8848	13/04/2022	REPAIR CRACKS ON TRUCK
WCA012 : Iveco Astra 8848	13/04/2022	REPAIRS
WCA012 : Iveco Astra 8848	13/04/2022	Wheel Bearings, Brakes, Diff Lock Switch
WCA012 : Iveco Astra 8848	14/04/2022	P/U BEARINGS - NORTHEAST ISUZU
WCA012 : Iveco Astra 8848	14/04/2022	P/U PARTS - NORTHEAST ISUZU
WCA012 : Iveco Astra 8848	14/04/2022	Wheel Bearings, Brakes, Diff Lock Switch
WCA012 : Iveco Astra 8848	19/04/2022	START ASSEMBLING FRONT HUBS
WCA012 : Iveco Astra 8848	19/04/2022	START POS 1 NUB/BRAKE ASSEMBLY, ORGANISE PARTS
WCA012 : Iveco Astra 8848	20/04/2022	ASSIST W/ REPAIRS, CHASE UP PARTS
WCA012 : Iveco Astra 8848	20/04/2022	ASSY FRONT BRAKES, HUBS
WCA012 : Iveco Astra 8848	20/04/2022	FIT FRONT HUBS
WCA012 : Iveco Astra 8848	20/04/2022	PUT HUBS TOGETHER, SEAL UP PARTS
WCA012 : Iveco Astra 8848	21/04/2022	ASSIST W/ REPAIRS
WCA012 : Iveco Astra 8848	21/04/2022	REPAIRS
WCA012 : Iveco Astra 8848	21/04/2022	REPLACE BRAKE SENSOR, DIFF LOCK, MUDGUARDS
WCA012 : Iveco Astra 8848	21/04/2022	TOP UP FRONT HUBS, SERVICE & REPAIRS
WCA012 : Iveco Astra 8848	22/04/2022	ASSIST W/ REPAIRS, REASSY REAR TRUNNIONS
WCA012 : Iveco Astra 8848	22/04/2022	ASSY POS 2 HUB
WCA012 : Iveco Astra 8848	22/04/2022	DO CIB

WCA012 : Iveco Astra 8848	22/04/2022 REPAIRS
WCA012 : Iveco Astra 8848	22/04/2022 REPAIRS, DROP CAB, TORQUE UP
WCA012 : Iveco Astra 8848	26/04/2022 ANNUAL SERVICE, PUT TRUNNING IN, TORQUE UP BOLTS
WCA012 : Iveco Astra 8848	26/04/2022 ASSY OF PIN SUPPORTS
WCA012 : Iveco Astra 8848	26/04/2022 M20 Nyloc Nuts
WCA012 : Iveco Astra 8848	26/04/2022 P/U UNITED
WCA012 : Iveco Astra 8848	26/04/2022 SASSIST REASSEMBLIG REAR SUSP, PURCHASE REQUIRED B
WCA012 : Iveco Astra 8848	27/04/2022 ASSIST W/REPAIRS
WCA012 : Iveco Astra 8848	27/04/2022 FIT BEARING, REAR SPRINGS, CLEAN UP
WCA012 : Iveco Astra 8848	27/04/2022 GREASE PARTS, BEARING TRUNNION
WCA012 : Iveco Astra 8848	28/04/2022 ASSIST WITH REPAIRS
WCA012 : Iveco Astra 8848	28/04/2022 Rear Suspension Artic Pins
WCA012 : Iveco Astra 8848	2/05/2022 4" Tank Fitting & Bellow
WCA012 : Iveco Astra 8848	6/05/2022 P/U NE ISUZU
WCA012 : Iveco Astra 8848	6/05/2022 P/U UES
WCA012 : Iveco Astra 8848	6/05/2022 Parts
WCA012 : Iveco Astra 8848	6/05/2022 Wheel Bearings, Brakes, Diff Lock Switch
WCA012 : Iveco Astra 8848	9/05/2022 FIR REAR WHEEL BEARINGS, FIT HIBS TO REAR AXLE
WCA012 : Iveco Astra 8848	9/05/2022 ASSEMBLE POS 5,6,7,8 F/DRIVE & HIB ASSEMBLIES
WCA012 : Iveco Astra 8848	9/05/2022 ASSIST WITH REPAIRS
WCA012 : Iveco Astra 8848	10/05/2022 ASSEM REPAIRS
WCA012 : Iveco Astra 8848	10/05/2022 ASSIST WITH REPAIRS
WCA012 : Iveco Astra 8848	10/05/2022 FINISH INSTALLING REAR SUSPENSION, HIBS & WHEELS E
WCA012 : Iveco Astra 8848	10/05/2022 FINISH REAR END ASSEMBLY, FILL & CHECK OIL LEVELS
WCA012 : Iveco Astra 8848	11/05/2022 A/C Belt, Tensioner, Inter Axle Lock Sensor
WCA012 : Iveco Astra 8848	11/05/2022 ASSIST WITH REPAIRS
WCA012 : Iveco Astra 8848	11/05/2022 DIAGNOSE FAULT WITH ROPS, LOCK WATER, ROAD TEST
WCA012 : Iveco Astra 8848	11/05/2022 FINISH ANNUAL SERVICE, REPAIR CANNON, WASH MACHINE
WCA012 : Iveco Astra 8848	12/05/2022 ASSIST WIITH REPAIRS
WCA012 : Iveco Astra 8848	12/05/2022 FAB GUARD FOR WATER PUMP DRIVE COUPLING
wca012 : Iveco Astra 8848	12/05/2022 Parts
WCA012 : Iveco Astra 8848	12/05/2022 REPAIR WIRING FOR CANNON CONTROL & REFIT CANNON
WCA012 : Iveco Astra 8848	14/05/2022 Subcontractor - Plant Maintenance
WCA012 : Iveco Astra 8848	17/05/2022 Parts
WCA012 : Iveco Astra 8848	18/05/2022 PU NE ISUZU
WCA012 : Iveco Astra 8848	27/05/2022 FIT PIPE FITTINGS - TURN OVER
WCA012 : Iveco Astra 8848	27/05/2022 PUMP DRIVE SHAFT
WCA012 : Iveco Astra 8848	28/05/2022 ASSIST W/ FITTING WATER TANK
WCA012 : Iveco Astra 8848	28/05/2022 INSTALL FITTING INTO TANK, FIT TANK TO TRUCK
wca012 : Iveco Astra 8848	30/05/2022 door lock rhs
WCA012 : Iveco Astra 8848	30/05/2022 FIT TANK & FITTINGS, REPAIR LOOM
WCA012 : Iveco Astra 8848	31/05/2022 ASSIST W/ REPAIRS
WCA012 : Iveco Astra 8848	31/05/2022 ASSIST W/ REPAIRS
WCA012 : Iveco Astra 8848	31/05/2022 FINAL CHECKS, INSTALL MONITOR
WCA012 : Iveco Astra 8848	31/05/2022 FIT CAMERA SCREEN, REMOVE TINT & GLUE
WCA012 : Iveco Astra 8848	1/06/2022 ASSIST W/ REPAIRS
WCA012 : Iveco Astra 8848	1/06/2022 FINAL CHECKS, REVERSE CAMERA, FIX SIDE LIGHTS
WCA012 : Iveco Astra 8848	1/06/2022 PREP FOR USE,
wca012 : Iveco Astra 8848	1/06/2022 reverse camera
WCA012 : Iveco Astra 8848	2/06/2022 CLOSE SERVICE & PLANT ACTIONS
WCA012 : Iveco Astra 8848	2/06/2022 FIT DOOR LOCK, C/O TYRES

WCA012 : Iveco Astra 8848	3/06/2022	DIAGNOSE NO START
WCA012 : Iveco Astra 8848	7/06/2022	ENTRY INSPECTION AND FIT RADIO, CHECK SPRAY OPERAT
WCA012 : Iveco Astra 8848	10/06/2022	HYDRAULIC LEAK FROM FITTING
WCA012 : Iveco Astra 8848	11/06/2022	REPAIR LEAKING HYDRAULIC FITTING AND FIT CAMLOCK F
WCA012 : Iveco Astra 8848	23/06/2022	BEACON LIGHT
WCA012 : Iveco Astra 8848	26/06/2022	PROTECT FILL POINT PIPEWORK
WCA012 : Iveco Astra 8848	10/07/2022	REMOVE AND INSPECT PTO FOR NOISY ENGAGEMENT
WCA012 : Iveco Astra 8848	11/07/2022	DISMANTLE AND DIAGNOSE RTO NOT ENGAGING
WCA012 : Iveco Astra 8848	11/07/2022	PTO REMOVAL ISMANTLE, ORDER PARTS
WCA012 : Iveco Astra 8848	12/07/2022	PLACE PTO HOSING BACK ON
WCA012 : Iveco Astra 8848	13/07/2022	GET DRIBBLE BAR OPERATIONAL
WCA012 : Iveco Astra 8848	19/07/2022	MODIFY SHIFT FORK, ASSEMBLE PTO BOX AND FIT, REMOV
WCA012 : Iveco Astra 8848	19/07/2022	REASSEMBLE PTO REMOVE FLAT TYRE GET REPAIRED
WCA012 : Iveco Astra 8848	19/07/2022	REFIT POS 5 WHEEL
WCA012 : Iveco Astra 8848	26/07/2022	1x 17257870 Dowel
WCA012 : Iveco Astra 8848	26/07/2022	1x 8850798 Fork
WCA012 : Iveco Astra 8848	26/07/2022	1x 885084 Bearing
WCA012 : Iveco Astra 8848	26/07/2022	1x 8850842 Bearing
WCA012 : Iveco Astra 8848	26/07/2022	2x 17282481 O ring
WCA012 : Iveco Astra 8848	26/07/2022	2x 601673636 O ring
WCA012 : Iveco Astra 8848	26/07/2022	Freight
WCA012 : Iveco Astra 8848	29/07/2022	REPAIRS TO RH SWITCH FOR SPRAY
WCA012 : Iveco Astra 8848	5/08/2022	CHECK TYRE PRESSURE
WCA012 : Iveco Astra 8848	7/08/2022	CHECK CANNON
WCA012 : Iveco Astra 8848	15/08/2022	PT SENSOR FAULT
WCA012 : Iveco Astra 8848	29/08/2022	CLEARANCE LIGHT OUT REPAIR
WCA012 : Iveco Astra 8848	1/09/2022	FIT NEW HEADLIGHT GLOBE AND REPAIR NUMBER PLATE
WCA012 : Iveco Astra 8848	20/09/2022	REMOVE WHEEL
WCA012 : Iveco Astra 8848	20/09/2022	REMOVE WHEEL FOR REPAIR AND DROP INTO BRIDGESTONE
WCA012 : Iveco Astra 8848	21/09/2022	REMOVE FLAT TYRE AND REFIT
WCA012 : Iveco Astra 8848	24/09/2022	FIT POS 8 TYRE
WCA012 : Iveco Astra 8848	27/09/2022	FIT NEW CANON SWITCH, REPAIR PTO GUARD AND REFIT
WCA012 : Iveco Astra 8848	29/09/2022	Tyre puncture repair
wca012 : Iveco Astra 8848	30/09/2022	cam lock/ hose fittings
WCA012 : Iveco Astra 8848	9/10/2022	CHECKED INOP WATER PUMP
WCA012 : Iveco Astra 8848	16/10/2022	REBUILD PTO
WCA012 : Iveco Astra 8848	16/10/2022	REMOVE PTO AND STRIP DOWN, FOUND SELECTOR FORK U/S
WCA012 : Iveco Astra 8848	25/10/2022	TRAVEL KNIGHT/ DUKE AND RETURN, ESCORT FLOAT TO PI
WCA012 : Iveco Astra 8848	27/10/2022	ASSIST WITH REPAIRS
WCA012 : Iveco Astra 8848	27/10/2022	RDTO REPAIRS
WCA012 : Iveco Astra 8848	27/10/2022	WAHS AND REMOVE BROKEN FORK
WCA012 : Iveco Astra 8848	28/10/2022	42563106 Filter
WCA012 : Iveco Astra 8848	28/10/2022	ASSIST WITH REPAIRS
WCA012 : Iveco Astra 8848	28/10/2022	Parts
WCA012 : Iveco Astra 8848	28/10/2022	REPAIRS
WCA012 : Iveco Astra 8848	28/10/2022	REPAIRS, REPLACE OIL, OIL FILTER
WCA012 : Iveco Astra 8848	31/10/2022	Workshop Consumables
WCA012 : Iveco Astra 8848	10/11/2022	Workshop Consumables
WCA012 : Iveco Astra 8848	16/11/2022	Balance
WCA012 : Iveco Astra 8848	16/11/2022	Supply new steer tyre
WCA012 : Iveco Astra 8848	9/12/2022	Workshop Consumables

WCA012 : Iveco Astra 8848	12/12/2022	STRIPPED PARTS OUT OF DOOR
WCA012 : Iveco Astra 8848	13/12/2022	ASSIST WITH CLEAN UP
WCA012 : Iveco Astra 8848	13/12/2022	EXIT INSPECTION, FINAL CHECK OVER AND LOAD ONTO TR
WCA012 : Iveco Astra 8848	13/12/2022	WEED AND SEED
WCA012 : Iveco Astra 8848	14/12/2022	ORGANISE CODE CLEARING FOR DRY HIRE
wca012 : Iveco Astra 8848	16/12/2022	door handle ad blue parts wca012
WCA012 : Iveco Astra 8848	20/12/2022	INNER DOOR HANDLE REPAIRS
WCA012 : Iveco Astra 8848	5/01/2023	ACX1942RBL 24V Relay
WCA012 : Iveco Astra 8848	7/03/2023	SEARCH FOR DOIS SHEETS FOR BRENTON
WCA012 : Iveco Astra 8848	8/03/2023	P/U NE ISUSU
WCA012 : Iveco Astra 8848	8/03/2023	P/U NE ISUZU
WCA012 : Iveco Astra 8848	9/03/2023	D/O GREYHOUND
WCA012 : Iveco Astra 8848	9/03/2023	PACK AND SEND GOODS
WCA012 : Iveco Astra 8848	18/03/2023	A/C Belts & Fan Belts
WCA012 : Iveco Astra 8848	13/04/2023	ASSIST WITH ENTRY INSPECTIONS
WCA012 : Iveco Astra 8848	13/04/2023	ENTRY INSPECTION
WCA012 : Iveco Astra 8848	17/04/2023	Repairs as per invoice 399
WCA012 : Iveco Astra 8848	21/04/2023	Freight parts;
WCA012 : Iveco Astra 8848	3/05/2023	22300 DIAGNOSE AND REPAIR FAULTS AS ON INSPECTION LIST
WCA012 : Iveco Astra 8848	3/05/2023	298959 ASSIST WITH REPAIRS
WCA012 : Iveco Astra 8848	4/05/2023	23501 ADJUST DOOR LATCH ASSEMBLY WELD GUARDS REROU
WCA012 : Iveco Astra 8848	4/05/2023	24113 REPAIRS
WCA012 : Iveco Astra 8848	4/05/2023	298960 ASSIST WITH REPAIRS
WCA012 : Iveco Astra 8848	4/05/2023	319938 ORDER PARTS
WCA012 : Iveco Astra 8848	5/05/2023	23502 REPAIR AIR LEAKS FIT CANNON MAKE MOUNT FOR REV
WCA012 : Iveco Astra 8848	5/05/2023	24114 WATER CART REPAIRS
WCA012 : Iveco Astra 8848	5/05/2023	298961 ASSIST WITH REPAIRS
WCA012 : Iveco Astra 8848	5/05/2023	319939 WHYALLA HOSE AND NATRAD FOR PARTS
WCA012 : Iveco Astra 8848	6/05/2023	23503 CHECK AIR LEAKS
WCA012 : Iveco Astra 8848	6/05/2023	24115 WATER CART REPAIRS
WCA012 : Iveco Astra 8848	7/05/2023	24116 WASH WATERCART
WCA012 : Iveco Astra 8848	8/05/2023	23505 PREP FOR SITE
WCA012 : Iveco Astra 8848	8/05/2023	24117 WATER CART EXIT

CREATE PARTS LIST

ITE COMPRESSOR

ERSE CAMERA CLEAN ENGINE BREATHER