



View Plant and Equipment

Fri Mar 19 2021 08:36 AM

View Plant and Equipment

[Perform Maintenance](#)

[Upload Document](#)

[Generate PDF](#)

[Back](#)

Machine Name: Mitsubishi Service Truck P19

Site: STILLER S Pty Ltd

Activity: Truck and Trailer Operation

Asset Number: P19

Serial Number: J1ffk617h0kk00638

Model Number: MITSUBISHI FK617 SERVICE TRUCK

Machine Use: Equipment servicing

Qualifications required: MR truck Licence,Truck VOC

Training required: Truck and trailer SWMS

Qualified Employees: [Linden Stiller](#)

Plant Item Cost: N/A

Purchase Date: N/A

Place Of Purchase: N/A

Date Of Sale/Disposal: N/A

Sale Price (if applicable): N/A

Buyer/Place Of Disposal: N/A

Next Maintenance Date: 28-02-2021

Maintenance Person: Linden Stiller

Email address: stillersearthworx@hotmail.com

Review Date: N/A

Future Maintenance Schedule: N/A

Responsible Person: Linden Stiller

Image:

[Print QR Code](#)



59999 ACT

Truck and Trailer Operation

Common QR Codes links

Incident Form

Hazard Form

Selected Qualifications for Plant

MR truck Licence

Truck VOC

Selected General Induction and Training Requirements

Truck and trailer SWMS

Email Ids for Expired Review Date Alert:

Quick Links:

View Hazards associated with this Machine

View Incidents associated with this Machine

View maintenance items associated with this Machine

[Show Document\(s\)](#)

[Show Log](#)

[Show Maintenance](#)

[Show Checklist\(s\)](#)

[Compliance\(s\)](#)

[Procedure\(s\)](#)

[Induction Log](#)

Details	Date	Completed By	Additional Notes	Attachment(s)
New tires fitted	06-07-2018	Linden Stiller		N/A
168 000 km service, engine oil, filter, fuel filter, air filter, grease, check brakes	18-10-2018	Linden Stiller		N/A
178 000km service, engine oil, filter, fuel filter, air filter, grease, check brakes, grease crane.	06-05-2019	Linden Stiller		N/A
180 000km, general check over, grease, wash	13-10-2020	Linden Stiller		N/A

Edit

Cancel

