

2/1/2021

Invoice Detail

Ship To
N/A

Location

[REDACTED]		
Date	Time	Page
07/17/17	19:29:34 (B)	01
Account Number	Phone Number	Invoice Number
[REDACTED]	[REDACTED]	[REDACTED]
Ship Via	Purchase Order	
[REDACTED]	[REDACTED]	
Tax Exemption Number	Federal ID Number	
[REDACTED]	[REDACTED]	
Salesperson		
[REDACTED]		

Sold To

[REDACTED]
[REDACTED]
[REDACTED]

Description

STK#/FLEET#	HRS	PIN/EIN	WARRANTY DATE	HRS
[REDACTED] JD 770G 770G	283	1DW770GXCHF679168	03/03/18 03/01/22	5000 H

**Take advantage of 10% OFF TK Teeth through July 31, 2017.
offer valid at participating locations.
Not valid with any other coupons or discounts.
See store for more details.

REPAIR# 1 C [REDACTED] 09290N100 06/27/17 06/27/17 3.37 HRS
MISCELLANEOUS DIAGNOSTICS
CONDITION:

TRANSMISSION IS JUMPING OUT OF GEAR
CAUSE:

known issue with the x41 connector vibrating wires loose
pip is soon to come out on this repair, until then service
parts needed and filed under normal warranty
CORRECTION:

6/27: Performed solution [REDACTED] on the unit
Gained access to the x41 connector
Turned master power off to the unit
Removed the connector from the mounting bracket
Removed mounting bracket to ease in repair
Cut the male and female connector from the wiring harness
Prepped and soldered 15 wires together
shrink wrapped all wires individually
Taped harness
Reinstalled bracket back on the machine
Ran and tested to verify proper operation of machine until
replacement parts could be installed.

LABOR Warranty
REPAIR TOTAL==> Warranty

CONTINUED ON PAGE 02

STK#/FLEET#	HRS	PIN/EIN	WARRANTY DATE	HRS
[REDACTED] JD 770G 770G 770G	283	1DW770GXCHF679168	03/03/18 03/01/22 03/01/22	5000 H 5000 H

REPAIR# 2 C [REDACTED] 06/27/17 07/07/17 3.05 HRS
Round trip travel to and from location.
CONDITION:

SHIP/HANDLING	1	Internal	Internal
		PARTS	Internal
		LABOR	Internal
REPAIR TOTAL==>			Internal

REPAIR# 3 C [REDACTED] 06/27/17 06/27/17 14.30 HRS
WARRANTY - FULL MACHINE
CORRECTION:

7/7: Disconnected lines, mounting bolts for ripper, and
removed ripper. 1.5
Removed bottom covers, disconnected lines and wiring from

2/1/2021

Invoice Detail

Ship To
N/A

Location

[REDACTED]		
Date	Time	Page
07/17/17	19:29:34 (B)	01
Account Number	Phone Number	Invoice Number
[REDACTED]	[REDACTED]	[REDACTED]
Ship Via	Purchase Order	
[REDACTED]	[REDACTED]	
Tax Exemption Number	Federal ID Number	
[REDACTED]	[REDACTED]	
Salesperson		
[REDACTED]		

Sold To

[REDACTED]
[REDACTED]
[REDACTED]

Description

STK#/FLEET#	HRS	PIN/EIN	WARRANTY DATE	HRS
[REDACTED] JD 770G 770G	283	1DW770GXCHF679168	03/03/18 03/01/22	5000 H

**Take advantage of 10% OFF TK Teeth through July 31, 2017.
offer valid at participating locations.
Not valid with any other coupons or discounts.
See store for more details.

REPAIR# 1 C [REDACTED] 09290N100 06/27/17 06/27/17 3.37 HRS
MISCELLANEOUS DIAGNOSTICS
CONDITION:

TRANSMISSION IS JUMPING OUT OF GEAR
CAUSE:

known issue with the x41 connector vibrating wires loose
pip is soon to come out on this repair, until then service
parts needed and filed under normal warranty
CORRECTION:

6/27: Performed solution [REDACTED] on the unit
Gained access to the x41 connector
Turned master power off to the unit
Removed the connector from the mounting bracket
Removed mounting bracket to ease in repair
Cut the male and female connector from the wiring harness
Prepped and soldered 15 wires together
shrink wrapped all wires individually
Taped harness
Reinstalled bracket back on the machine
Ran and tested to verify proper operation of machine until
replacement parts could be installed.

LABOR Warranty
REPAIR TOTAL==> Warranty

CONTINUED ON PAGE 02

STK#/FLEET#	HRS	PIN/EIN	WARRANTY DATE	HRS
[REDACTED] JD 770G 770G 770G	283	1DW770GXCHF679168	03/03/18 03/01/22 03/01/22	5000 H 5000 H

REPAIR# 2 C [REDACTED] 06/27/17 07/07/17 3.05 HRS
Round trip travel to and from location.
CONDITION:

SHIP/HANDLING	1	Internal	Internal
		PARTS	Internal
		LABOR	Internal
REPAIR TOTAL==>			Internal

REPAIR# 3 C [REDACTED] 06/27/17 06/27/17 14.30 HRS
WARRANTY - FULL MACHINE
CORRECTION:

7/7: Disconnected lines, mounting bolts for ripper, and
removed ripper. 1.5
Removed bottom covers, disconnected lines and wiring from

2/1/2021

Invoice Detail

Ship To
N/A

Location

[REDACTED]		
Date	Time	Page
07/17/17	19:29:34 (B)	01
Account Number	Phone Number	Invoice Number
[REDACTED]	[REDACTED]	[REDACTED]
Ship Via	Purchase Order	
[REDACTED]	[REDACTED]	
Tax Exemption Number	Federal ID Number	
[REDACTED]	[REDACTED]	
Salesperson		
[REDACTED]		

Sold To

[REDACTED]
[REDACTED]
[REDACTED]

Description

STK#/FLEET#	HRS	PIN/EIN	WARRANTY DATE	HRS
[REDACTED] JD 770G 770G	283	1DW770GXCHF679168	03/03/18 03/01/22	5000 H

**Take advantage of 10% OFF TK Teeth through July 31, 2017.
offer valid at participating locations.
Not valid with any other coupons or discounts.
See store for more details.

REPAIR# 1 C [REDACTED] 09290N100 06/27/17 06/27/17 3.37 HRS
MISCELLANEOUS DIAGNOSTICS
CONDITION:

TRANSMISSION IS JUMPING OUT OF GEAR
CAUSE:

known issue with the x41 connector vibrating wires loose
pip is soon to come out on this repair, until then service
parts needed and filed under normal warranty
CORRECTION:

6/27: Performed solution [REDACTED] on the unit
Gained access to the x41 connector
Turned master power off to the unit
Removed the connector from the mounting bracket
Removed mounting bracket to ease in repair
Cut the male and female connector from the wiring harness
Prepped and soldered 15 wires together
shrink wrapped all wires individually
Taped harness
Reinstalled bracket back on the machine
Ran and tested to verify proper operation of machine until
replacement parts could be installed.

LABOR Warranty
REPAIR TOTAL==> Warranty

CONTINUED ON PAGE 02

STK#/FLEET#	HRS	PIN/EIN	WARRANTY DATE	HRS
[REDACTED] JD 770G 770G 770G	283	1DW770GXCHF679168	03/03/18 03/01/22 03/01/22	5000 H 5000 H

REPAIR# 2 C [REDACTED] 06/27/17 07/07/17 3.05 HRS
Round trip travel to and from location.
CONDITION:

[REDACTED] SHIP/HANDLING 1 Internal Internal
PARTS Internal
LABOR Internal
REPAIR TOTAL==> Internal

REPAIR# 3 C [REDACTED] 06/27/17 06/27/17 14.30 HRS
WARRANTY - FULL MACHINE
CORRECTION:

7/7: Disconnected lines, mounting bolts for ripper, and
removed ripper. 1.5
Removed bottom covers, disconnected lines and wiring from

Ship To
N/A

Location

[REDACTED]		
Date	Time	Page
11/15/17	19:36:46 (B)	01
Account Number	Phone Number	Invoice Number
[REDACTED]	[REDACTED]	[REDACTED]
Ship Via	Purchase Order	
[REDACTED]	[REDACTED]	
Tax Exemption Number	Federal ID Number	
[REDACTED]	[REDACTED]	
Salesperson		
[REDACTED]		

Sold To
[REDACTED]
[REDACTED]
[REDACTED]

Description

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
[REDACTED]	JD 770G	517	1DW770GXCHF679168	03/03/18	
	770G			03/01/22	5000 H

**Take advantage of 10% OFF TK Teeth through July 31, 2017.
 Offer valid at participating locations.
 Not valid with any other coupons or discounts.
 See store for more details.

SEGMENT# 1 C [REDACTED] RDO-070-DIAG 11/13/17 11/13/17
 HYDRAULIC DIAGNOSTICS 1.25 HRS
 CONDITION:

verify machine operation and check pressures
 CORRECTION:

Ran machine to warm hydraulic oil to 150 degrees.
 Tested pump load sense pressures
 Found pressure to be around 2240
 Spec is 2240 to 2470
 Made several adjustments to the load sense valve on the machine
 Obtained 2470 psi.
 Tested for pump output and verified that pump out put and differential pressures where now in specifications.

LABOR Internal
 SEGMENT TOTAL=> Internal

***** WORK ORDER TOTALS *****
 INTERNAL INTERNAL CUSTOMER
 INTERNAL LABOR Internal
 INTERNAL TOTAL Internal

Ship To
N/A

Location		
[REDACTED]		
Date	Time	Page
08/24/18	19:25:57 (B)	01
Account Number	Phone Number	Invoice Number
[REDACTED]	[REDACTED]	[REDACTED]
Ship Via	Purchase Order	
[REDACTED]	[REDACTED]	
Tax Exemption Number	Federal ID Number	
[REDACTED]	[REDACTED]	
Salesperson		
[REDACTED]		

Sold To
[REDACTED]
[REDACTED]
[REDACTED]

Description

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
[REDACTED]	JD 770G	1339	1DW770GXCHF679168	03/03/18	
	770G			03/01/22	5000 H

*****Check out our quality used equipment at www.rdousedequipment.com****
 SEGMENT# 1 C [REDACTED] WARR DFERE 08/08/18 08/08/18
 WARRANTY - Deere Machine warranty
 CONDITION:

machine will stop moving and has multiple codes for can loss

- hwd 2003.9 x14 occur 1112 first 1209 last
- vcu 2003.9 x12 occur same
- ecu 2003.9 x 5 occur 1116 - 1209
- ssm 523862.09 x2 occur 1204-1209
- vcu 639.14 x54 occur 960-1209
- hwd 639.14 x58 occur 960-1209
- ecu 2033.9 x68 occur 960-1209
- ssm 639.14 x34 occur 1012-1209
- tcu 639.14 x51 occur 960-1209
- tcu 2000.9 x60 occur 960-1209
- tcu 2161.9 x45 occur 960-1209
- hwd 2009.9 x21 occur 960-1209
- vcu 2000.9 x21 occur 960-1209
- vcu 2040.9 x14 occur 1112-1209
- vcu 2141.9 x15 occur 1112-1209
- ssm 2033.9 x5 occur 1116-1209
- tcu 2225.9 x28 occur 1028-1198
- tcu 522517.31 x20 occur 956-1195
- tcu 2033.9 x9 occur 1112-1173
- tcu 2141 x13 occur 1112-1173

CAUSE:

Contacted DTAC and they suggested replacing the

CONTINUED ON PAGE 02

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
[REDACTED]	JD 770G	1339	1DW770GXCHF679168	03/03/18	
	770G			03/01/22	5000 H

transmission harness AT452937 and controller DZ103963 for possible internal failures.
 Ordered parts for repair.
 CORRECTION:

Removed and replaced harness and controller. Ran machine and checked operation and no issues so far.
 ADDITIONAL DESCRIPTION:

Failure Part #:AT452937
 General Repair (Fail) Area:1674 wiring harness
 Failure Type Code:11
 DTAC Case / Solution #: [REDACTED]
 AT452937 Wiring Harness
 CRDZ103963 core
 DZ103963 ELECTRONIC CONT

1 N	Warranty	Warranty
1-	Warranty	Warranty
1 N	Warranty	Warranty
	PARTS	Warranty
	LABOR	Warranty
	SEGMENT TOTAL==>	Warranty

10501020

2/1/2021

Invoice Detail

Ship To
N/A

Location		
[REDACTED]		
Date	Time	Page
12/10/18	20:03:45 (B)	01
Account Number	Phone Number	Invoice Number
[REDACTED]	[REDACTED]	[REDACTED]
Ship Via	Purchase Order	
ORIG WO: W51892	[REDACTED]	
Tax Exemption Number	Federal ID Number	
[REDACTED]	[REDACTED]	
Salesperson		
[REDACTED]		

Sold To
[REDACTED]
[REDACTED]
[REDACTED]

Description

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
7602545	JD 770G	1526	1DW770GXCHF679168	03/03/18	
	770G			03/01/22	5000 H

***Check out our quality used equipment at www.rdousedequipment.com
 ***view your invoices online at RDOequipment.com/mydealer
 This order was created from order: W51892

SEGMENT# 1 C [REDACTED] RDO-020-DIAG 12/10/18 11/16/18 .57 HRS
 ENGINE DIAGNOSTICS
 CONDITION:

engine derated with def codes 004334.18 1569.31
 CAUSE:

Found pump has internal failure
 CORRECTION:

Machine has codes for Def pump failure to prime
 Connected laptop to unit
 Performed def pump test
 Found pump took excessively long to prime
 Checked pump filter
 Found filter to be ok

10402099 10501020 LABOR Warranty
 SEGMENT TOTAL==> Warranty

SEGMENT# 2 C [REDACTED] WARR DEERE 12/10/18 11/26/18 .01 HRS
 WARRANTY - Deere Machine Warranty
 CORRECTION:

Removed pump from the machine
 Installed new pump
 Cleared codes
 Performed def system test on the unit
 Found system now performing through all test properly

CONTINUED ON PAGE 02

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
[REDACTED]	JD 770G	1526	1DW770GXCHF679168	03/03/18	
	770G			03/01/22	5000 H

ADDITIONAL DESCRIPTION:

Failure Part #:DZ111284
 General Repair (Fail) Area:0400a engine
 Failure Type Code:13
 DZ111284

DEF DOSING UNIT 1 N Warranty Warranty
 DEF Dosing Unit Pump

10402099 10501020 PARTS Warranty
 LABOR Warranty
 SEGMENT TOTAL==> Warranty

***** WORK ORDER TOTALS *****
 INTERNAL CUSTOMER
 PARTS Warranty
 LABOR Warranty
 HAZ MTL (warr) Warranty
 INTERNAL TOTAL Warranty

2/1/2021

Invoice Detail

Ship To
N/A

Location		
[REDACTED]		
Date	Time	Page
12/10/18	20:03:45 (B)	01
Account Number	Phone Number	Invoice Number
[REDACTED]	[REDACTED]	[REDACTED]
Ship Via	Purchase Order	
ORIG WO: W51892	[REDACTED]	
Tax Exemption Number	Federal ID Number	
[REDACTED]	[REDACTED]	
Salesperson		
[REDACTED]		

Sold To
[REDACTED]
[REDACTED]
[REDACTED]

Description

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
9602545	JD 770G	1526	1DW770GXCHF679168	03/03/18	
	770G			03/01/22	5000 H

***Check out our quality used equipment at www.rdousedequipment.com
***View your invoices online at RDOequipment.com/mydealer

This order was created from order: W51892

SEGMENT# 1 C [REDACTED] RDO-020-DIAG 12/10/18 11/16/18 .57 HRS
ENGINE DIAGNOSTICS
CONDITION:

engine derated with def codes 004334.18 1569.31
CAUSE:

Found pump has internal failure
CORRECTION:

Machine has codes for Def pump failure to prime
Connected laptop to unit
Performed def pump test
Found pump took excessively long to prime
Checked pump filter
Found filter to be ok

10402099 10501020

LABOR Warranty
SEGMENT TOTAL==> Warranty

SEGMENT# 2 C [REDACTED] WARR DEERE 12/10/18 11/26/18 .01 HRS
WARRANTY - Deere Machine Warranty
CORRECTION:

Removed pump from the machine
Installed new pump
Cleared codes
Performed def system test on the unit
Found system now performing through all test properly

CONTINUED ON PAGE 02

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
[REDACTED]	JD 770G	1526	1DW770GXCHF679168	03/03/18	
	770G			03/01/22	5000 H

ADDITIONAL DESCRIPTION:

Failure Part #:DZ111284
General Repair (Fail) Area:0400a engine
Failure Type Code:13
DZ111284

DEF DOSING UNIT 1 N Warranty Warranty

DEF Dosing Unit Pump

10402099 10501020

PARTS Warranty
LABOR Warranty
SEGMENT TOTAL==> Warranty

***** WORK ORDER TOTALS *****
INTERNAL CUSTOMER

PARTS Warranty
LABOR Warranty
HAZ MTL (warr) Warranty
INTERNAL TOTAL Warranty

