

27/10/20	Tractor guard replacement
22/09/20	Repaired PTO due to grinding when engaging
09/09/19	Hose for Massey Tractor
06/09/19	Washed down tractor around PTO and linkage Removed lift cover, pipes and wiring Drained remaining oil from rear end Changed hydraulic pump filter Found broken circlip that keeps shaft in tractor Found damaged gears, bearings and shafts also Ordered parts Re assembled PTO assembly Re fit all covers Filled rear end with oil Tested operation Washed down area
02/05/19	Radiator maintenance - Clean exterior test and repair. Charge Air Cooler
10/04/19	Calibrate power shuttle. Bring tractor up to temperature Calibrate transmission Adjust clutch potentiometer Found linkage not working Put machine on dyno to test PTO under load Had intermittent failure of PTO Tested speed sensors Found faulty harness on sensor Remove and replace, Test Changed hydraulic filter Added 5L Vtrans fluid Linkage now working Test and diagnose 4wd staying on Remove and replace switch Remove and replace remote coupler Re test machine on dyno Test drive machine Working OK SENSOR ENG/PTO
06/03/19	Coupling carrier x 2, nipple BSPP male and x BSPP Male
06/03/19	Coupling carrier, nipple, 15L blanking plug
15/01/19	Service and filters for tractor
03/11/18	Tractor tyre replacement
25/09/18	Repair to tyre puncture
16/08/18	Repair to PTO bearing and gearing
13/07/16	Suction strainer and oil