# Coates Inspection Checklist
## Generators (Diesel or Petrol)

**See Generator Photo Log for required pictures** **Asset #** 1026145

**Photos**

**General Information:** *** Copy Data Plate information in this section ***

Make/ Model: Crommelins DSE
Year: 2010
Serial Number: 65313
Engine / Motor - Make / Model: Hatz
Engine Serial Number: 025212
Meter Reading: N/A

Comments:

☐ Data Plate

**Features:**

List features or options for the machine:

Generator Type: Single Phase ☑ 3 Phase ☐
Frame mount ☑ Trailer mount ☐

Generator KVA Rating: _____

Power Outlets: Qty Single Phase 2 Amps per outlet 15A
Qty 3 Phase _____ Amps per outlet _____

**4-Corner Photos**
☐ Left-Front Corner
☐ Left-Rear Corner
☐ Right-Front Corner
☐ Right-Rear Corner

☐ *Damage*
☐ *Damage*

**Overall Appearance:**

| | Good | Fair | Poor | Comments: |
|---|---|---|---|---|
| Control Station\Operator Station | ☐ | ☐ | ☑ | Dusty, Paint flake |
| Sheet metal\Fiberglass Condition | ☐ | ☐ | ☑ | |
| Paint | ☐ | ☐ | ☑ | |
| Lights | ☐ | ☐ | ☐ | N/A |

**Control Station**

| | Operates Yes | Operates No | N/A | Comments: |
|---|---|---|---|---|
| Operator Controls | ☑ | ☐ | | |
| Gauges Operational? | ☑ | ☐ | ☐ | |

☐ Hour Meter
☐ Guages
☐ *Damage*
☐ *Damage*

**Engine:**

Power: Diesel ☑ Petrol ☐

| | Yes | No | Comments: |
|---|---|---|---|
| Does it start? | ☑ | ☐ | flat Battery |
| Did it need to be jumped? | ☑ | ☐ | |
| Acceptable Power | ☑ | ☐ | |
| Unusual Noises | ☐ | ☑ | |

☐ Right Side hood open
☐ Left Side hood open

**Chassis**

| | Good | Fair | Poor | Inoper | Missing | N/A | Comments: |
|---|---|---|---|---|---|---|---|
| Landing Gear / Outriggers | ☐ | ☐ | ☐ | ☐ | ☐ | ☑ | |
| Frame Condition | ☐ | ☐ | ☑ | ☐ | ☐ | ☐ | Very Rough |
| Trailer Lights | ☐ | ☐ | ☐ | ☐ | ☐ | ☑ | |
| Trailer Electrical Connections | ☐ | ☐ | ☐ | ☐ | ☐ | ☑ | Condition |
| Trailer Brakes | ☐ | ☐ | ☐ | ☐ | ☐ | ☑ | |
| Switches | ☐ | ☑ | ☐ | ☐ | ☐ | ☐ | |
| Power Cables | ☐ | ☐ | ☑ | ☐ | ☐ | ☐ | |

☐ Hitch
☐ Lights on
☐ Light Tower (Extended)

**Tire Condition:**

| Left | Right |
|---|---|
| Brand- | Brand- |
| Size- | Size- |
| Condition- | Condition- |

Tire pictures at a 45 degree angle showing the tread and side walls

☐ Left
☐ Right