



VEHICLE ASSESSMENT FORM

Vendor Number	71466
Item Number	522

Vehicle Details		Optional Accessories (Y / N)	
Year, Make & Model	1997 MAZDA 323 PROTEGE SHADES	ABS Brakes	N
Body Type	SEDAN	Front Air Bags	Y
Build Date	NOV-97	Side Impact Air Bags 1st Row	N
Compliance Date	DEC-97	Air Conditioning	Y
Engine Type & Capacity	4 CYL 1.6 LTR	Alloy Wheels	N
Transmission	MANUAL	Remote Central Locking	N
Odometer (Showing)	221 520	CD Player	Y
Registration Number	OTB209 REGISTRATION TRANSFERRED	Multi-Function Steering Wheel	N
Registration Expiry	07 JAN 2014	Electric Seats	N
Colour (Exterior / Interior)	RED / GREY	Power Windows	N
VIN / Chassis Number	JM0BA116300224362	Satellite Navigation	N
Engine Number	NOT SIGHTED	Leather Trim	N
Engine turns over	Yes	Sunroof	N
Battery Condition	Starts	Roof Racks	N
Keys	Yes	Dual Fuel	N
Spare Keys	No	Tow Bar	Y
Owner's Manual	Yes	DVD Player	N
Service History	Partial	Driving Lights	N
		Bull Bar	N
		Cruise Control	N
General Condition for Age & kms		Park Assist	N
Seats & Upholstery	Good		
Floors	Good		
Controls and Dash	Good		
Paint	Fair		
Marks & Scratches - Location	Various- General		
Stone Chips - Location			
Dents - Location	Bonnet/grille, Minor RHS F guard, LHS R door and wheel arch, LHS F pillar		
Other Damage			
Other Notes	Engine R/A-smokey/steamy, A/C R/A		
Vehicle Location	19 Hewitt Street, Cheltenham, VIC, 3192		
Abbreviations	F - Front R - Rear	R/A - Requires Attention	RHS - Right hand side LHS - Left hand side

NOTE: This report is based on an external walk around and engine start-up only – the vehicles are not driven. There may be other damage, mechanical issues or body blemishes that have not been sighted or contained in this report, therefore a full inspection is highly recommended. This report is intended as a guide only.

Please note: When buying a car at Auction you will not have the same statutory warranty, cooling-off period or Certificate of Roadworthiness you would receive when buying from a licensed motor car trader.