

VEHICLE ASSESSMENT FORM

Vendor Number	71466
Item Number	540

Vehicle Details		Optional Accessories	(Y / N)
Year, Make & Model	1994 MAZDA 323 ASTINA	ABS Brakes	N
Body Type	HATCH	Front Air Bags	N
Build Date	FEB-94	Side Impact Air Bags 1st Row	N
Compliance Date	MAY-94	Air Conditioning	N
Engine Type & Capacity	4 CYL 1.6 LTR	Alloy Wheels	Ν
Transmission	MANUAL	Remote Central Locking	N
Odometer (Showing)	234 192	CD Player	N
Registration Number	FNI336 SOLD UNREGISTERED (NO PLAT	Multi-Function Steering Wheel	N
Registration Expiry		Electric Seats	N
Colour (Exterior / Interior)	GREEN / GREY	Power Windows	N
VIN / Chassis Number	JM0BG10P200159226	Satellite Navigation	N
Engine Number	NOT SIGHTED	Leather Trim	N
Engine turns over	Yes	Sunroof	N
Battery Condition	Starts	Roof Racks	N
Keys	Yes	Dual Fuel	N
Spare Keys	No	Tow Bar	N
Owner's Manual	No	DVD Player	N
Service History	None	Driving Lights	N
		Bull Bar	N
		Cruise Control	N
General Condition for Age & kms		Park Assist	N
Seats & Upholstery	Fair		
Floors	Good		
Controls and Dash	Good		
Paint	Good		
Marks & Scratches - Location			
Otana Ohina I aastian	Various- General		
Stone Chips - Location			
Dents - Location			
	Minor- all doors & F and R LHS Guards		
Other Damage			
	Drivers seat fabric worn		
Other Notes	B Winer B/A A/C B/A		
Vehicle Location	R. Wiper R/A, A/C- R/A		
. Simolo Econdon	19 Hewitt Street, Cheltenham, VIC, 3192		
Abbreviations	F - Front R/A - Requires Attention	RHS - Right hand side	
	R - Rear	LHS - Left hand side	

NOTE: This report is based on an external walk around and engine start-up only – the vehicles are not driven. There may be other damage, mechanical issues or body blemishes that have not been sighted or contained in this report, therefore a full inspection is highly recommended. This report is intended as a guide only.

Please note: When buying a car at Auction you will not have the same statutory warranty, cooling-off period or Certificate of Roadworthiness you would receive when buying from a licensed motor car trader.