

## **VEHICLE ASSESSMENT FORM**

Vendor Number	71466
Item Number	543

**Vehicle Details Optional Accessories** (Y/N)1994 NISSAN SERENA C23 Year, Make & Model **ABS Brakes** Ν PEOPLE MOVER Ν **Body Type** Front Air Bags **Build Date** AUG-94 Ν Side Impact Air Bags 1st Row Υ OCT-94 **Compliance Date** Air Conditioning 4 CYL 2.0 LTR Ν **Engine Type & Capacity** Alloy Wheels **Transmission AUTOMATIC** Ν Remote Central Locking Ν **Odometer (Showing)** 168909 CD Player **Registration Number** UZZ 546 REGISTRATION TRANSFERRED Ν Multi-Function Steering Wheel Registration Expiry 19 SEP 2014 **Electric Seats** Ν RED / BROWN Υ Colour (Exterior / Interior) Power Windows VIN / Chassis Number JN1ABAC23A0000799 Ν Satellite Navigation **Engine Number NOT SIGHTED** Ν Leather Trim Engine turns over Yes Sunroof Ν **Battery Condition** Starts Roof Racks Ν Yes Ν Keys **Dual Fuel** Yes Υ Spare Keys Tow Bar Yes Ν Owner's Manual **DVD Player** Partial Ν Service History **Driving Lights** Υ **Bull Bar** Ν Cruise Control General Condition for Age & kms Ν Park Assist Seats & Upholstery Good Fair **Floors** Good **Controls and Dash Paint** Good Marks & Scratches - Location Various-General Stone Chips - Location Bonnet, Windscreen **Dents - Location** Other Damage Drivers seat worn Other Notes Vehicle Location 19 Hewitt Street, Cheltenham, VIC, 3192 Abbreviations R/A - Requires Attention F - Front RHS - Right hand side R - Rear LHS - Left hand side

NOTE: This report is based on an external walk around and engine start-up only – the vehicles are not driven. There may be other damage, mechanical issues or body blemishes that have not been sighted or contained in this report, therefore a full inspection is highly recommended. This report is intended as a guide only.

Please note: When buying a car at Auction you will not have the same statutory warranty, cooling-off period or Certificate of Roadworthiness you would receive when buying from a licensed motor car trader.